OMB Control No.: 2127-0004

Part 573 Safety Recall Report

21V-281

Manufacturer Name: Navistar, Inc.
Submission Date: APR 22, 2021
NHTSA Recall No.: 21V-281
Manufacturer Recall No.: 21505



Manufacturer Information:

Manufacturer Name: Navistar, Inc.

Address: 2701 Navistar Drive

Lisle IL 60532

Company phone: 331-332-1590

Population:

Number of potentially involved : 10,038 Estimated percentage with defect : 17%

Vehicle Information:

Vehicle 1: 2019-2021 International LT

Vehicle Type: BUSES, MEDIUM & HEAVY VEHICLES

Body Style: OTHER Power Train: DIESEL

Descriptive Information: •

- The suspect population is identified by models equipped with A26 engines with build dates 01/13/2018 through 12/06/2019 for LT series and 02/02/2018 through 12/06/2019 for RH series.
- The inclusive vehicle build dates were determined by certain engine serial numbers of the A26 engines built with suspect connecting rods.
- The vehicles in the suspect population were built with certain A26 engines built with suspect connecting rods; and all other vehicles either have A26 engines

without suspect connecting rods or have other engine models. There are 5,825 LT series trucks in the suspect population

Production Dates: JAN 13, 2018 - DEC 06, 2019

 Vehicle 2: 2019-2021 International RH

Vehicle Type: BUSES, MEDIUM & HEAVY VEHICLES

Body Style : OTHER Power Train : DIESEL

Descriptive Information: •

• The suspect population is identified by models equipped with A26 engines with build dates 01/13/2018 through 12/06/2019 for LT series and 02/02/2018 through 12/06/2019 for RH series.

• The inclusive vehicle build dates were determined by certain engine serial numbers of the A26 engines built with suspect connecting rods.

• The vehicles in the suspect population were built with certain A26 engines built with suspect connecting rods; and all other vehicles either have A26 engines without suspect connecting rods or have other engine models.

There are 4,213 RH series trucks in the suspect population.

Production Dates: FEB 02, 2018 - DEC 06, 2019

Description of Defect:

Description of the Defect: The bushing material in the small end bore (wrist pin of rod) of the connecting

rod over time may develop cracks or lose chunks of bushing material and could

lead to connecting rod engine failure.

FMVSS 1: NR FMVSS 2: NR

Description of the Safety Risk: Connecting rod failure in some cases can result in engine shutdown with

minimal warning; while the driver can usually pull the truck to the side of the roadway, a stalled vehicle in or near the roadway can increase the risk of a

vehicle crash.

Description of the Cause: The wrist pin bore of the connecting rod was machined outside the design

tolerance for straightness.

Identification of Any Warning The operator may hear a knocking noise, notice an engine warning light, or

that can Occur: experience rough idle.

Involved Components:

Component Name 1: Connecting Rod

Component Description: Connects piston to crankshaft

Component Part Number: 7096533C91

Supplier Identification:

Component Manufacturer

Name: Camtac Manufacturing a part of Linamar C

Address: 148 Arrow Rd.

Guelph, ON Foreign States N1K 1T4

Country: Canada

Chronology:

The chronology exceeds the maximum allowed characters and will be submitted as a miscellaneous supporting document

Description of Remedy:

Description of Remedy Program: •

- The remedy will involve installing a new knock detection system software to warn the driver prior to engine connecting rod failure. The system will light a red engine warning light giving the driver and indication to stop the engine as soon as it can safely be done. This remedy will address vehicles in prior recall 20V-255, excluding engines that were replaced with new connecting rods or that received the latest calibration; and additional vehicles beyond the original recall population. Engines found with a suspect connecting rod will be repaired under warranty.
- Navistar's plan for reimbursement of pre-notification remedies, on file with NHTSA and dated 10/03/2018, applies and reimbursement instructions will be included in the customer notification.

How Remedy Component Differs The remedy will include the installation of a new knock detection system from Recalled Component: software, which will activate the engine malfunction indicator lamp. Vehicles without this remedy either had a less effective detection system, or no detection system at all.

Identify How/When Recall Condition 12/06/2019 – Navistar vehicle production changed to Albon Engineering was Corrected in Production: and Manufacturing as the new connecting rod supplier starting with ESN 4521933.

Recall Schedule:

Description of Recall Schedule: It is estimated that the Customer and Dealer notification letters will be

mailed by 07/08/2021.

Planned Dealer Notification Date: JUL 08, 2021 - JUL 08, 2021 Planned Owner Notification Date: JUL 08, 2021 - JUL 08, 2021

Part 573 Safety Recall Report	21V-281	Page 4
* NR - Not Reported		
5.00 5.00 5.00 F.5.0 B		
The information contained in this report was submitted	d pursuant to 49 CFR §573	