OMB Control No.: 2127-0004

Part 573 Safety Recall Report

21V-370

Manufacturer Name: Daimler Trucks North America, LLC

NHTSA Recall No.: 21V-370

Manufacturer Recall No.: FL-888



Manufacturer Information:

1 opulation

Manufacturer Name: Daimler Trucks North America, LLC

Address: 4747 N. Channel Avenue

Portland OR 97217-3849

Company phone: 800-745-8000

Population:

Number of potentially involved: 479 Estimated percentage with defect: 1 %

Vehicle Information:

Vehicle 1: 2021-2022 Thomas Built Buses Saf-T-Liner C2 School Bus

Vehicle Type :
Body Style :
Power Train : NR

Tower Ham. Nic

Descriptive Information: Vehicles built with certain suspect tie rod clamp nuts.

Production Dates: DEC 15, 2020 - APR 14, 2021

Vehicle 2: 2021-2022 Thomas Built Buses Saf-T-Liner HDX School Bus

Vehicle Type :
Body Style :
Power Train : NR

Descriptive Information: Vehicles built with certain suspect tie rod clamp nuts.

Production Dates: DEC 15, 2020 - APR 14, 2021

Description of Defect:

Description of the Defect: On certain vehicles, the tie rod clamp may be loose due to the supplied lock

nuts being over-crimped. This can cause thread galling of the bolt and nut during installation. When galling occurs, it is possible that assembly torque

may be achieved but the clamp is still loose.

FMVSS 1: NR FMVSS 2: NR

Description of the Safety Risk: The tie rod clamp being loose could lead to the threaded tie rod ends

becoming loose and eventual steering loss if the rod end pulls out of the tie rod, or the tube is broken due to vibration of the loose joint increasing the

risk of a crash.

Description of the Cause: NR

Identification of Any Warning Decrease in steering response

that can Occur:

Involved Components:

Component Name 1: Tie Rod Clamp Nut

Component Description: NR

Component Part Number: 10010(MPTUE0171)

Supplier Identification:

Component Manufacturer

Name: USK International S.A. de C.V.

Address: Av. Huehuetoca S/N

San Mateo Foreign States 54713

Country: Mexico

Chronology:

Late December, 2020, despite a lack of warranty claims and any other indications of failures on customer vehicles, DTNA's axle assembly plant in Mexico reported a tie rod clamp nut quality concern and promptly began a containment effort. January, 2021, DTNA discussed with the tie rod supplier the concerns, and the supplier established what it believed to be a "clean" date for tie rods assembled with properly crimped clamp nuts. No information suggested that the problem extended further, and all indications were that no defective parts escaped the production plant. February 2021, DTNA's axle assembly plant in Detroit reported finding similarly suspect parts and promptly began containment. March 2021, DTNA resumed discussions with the supplier on this issue to understand scope of issue. Early May 2021, DTNA received DFMEA from the supplier suggesting a potential safety concern. May 2021, even though DTNA is not aware of any field failures related to this concern nor has any information to suggest the existence of a defect with an unreasonable risk to the safety of any vehicles in the field, DTNA decided to conduct a voluntary safety recall. October 2021, due to parts availability, the recall release has been delayed and is expected to launch in mid-December 2021.

Description of Remedy:

Description of Remedy Program: Tie rod clamp bolts and nuts will be replaced. Repairs will be performed

by Daimler Trucks North America authorized service facilities. Details of the reimbursement plan will be included in the owner's notification letter.

How Remedy Component Differs NR

from Recalled Component:

Identify How/When Recall Condition NR

was Corrected in Production:

Recall Schedule:

Description of Recall Schedule: Customer notification will be made by first class mail using Daimler

Trucks North America records to determine the customers affected.

Planned Dealer Notification Date : JUL 17, 2021 - JUL 17, 2021 Planned Owner Notification Date : JUL 17, 2021 - JUL 17, 2021

* NR - Not Reported