OMB Control No.: 2127-0004

Part 573 Safety Recall Report

21V-544

Manufacturer Name: Osage Industries, Inc.

NHTSA Recall No.: 21V-544

Manufacturer Recall No.: NR



Manufacturer Information:

Manufacturer Name: Osage Industries, Inc.

Address: P.O. BOX 718

Linn MO 65051

Company phone: 1-800-822-3634

Population:

Number of potentially involved : 1 Estimated percentage with defect : 100 %

Vehicle Information:

Vehicle 1: 2021-2021 Ford Super-Warrior III E450 Vehicle Type: BUSES, MEDIUM & HEAVY VEHICLES

Body Style: OTHER Power Train: GAS

Descriptive Information: A letter was received from Weldon dated 10/28/2020.

At that time we identified the unit that needed to be replaced. Per the recall, only a few products had been shipped to us.

Only one was installed on a truck.

This recall only affected one on our trucks - Ford Super-Warrior III E450

Production Dates: MAR 25, 2020 - JUL 27, 2020

VIN Range 1 : Begin : NR End : NR Not sequential

Description of Defect:

Description of the Defect: A safety-related defect may exist with some Vista IV user interface panels. This

could include both touch and non-touch versions of the Vista.

Power and ground are critical to the proper operation of electronics including the Vista IV display. The Vista IV display has an operating voltage of 9-32 VDC. When the supply voltage at the display drops, even for a moment, such as when starting the engine, the V-MUX Vista IV Interface typically turns off and quickly and automatically restarts. However, the identified units may not restart on their own if the voltage dips out of range(less than 9 volts) which can increase the risk of injury. These units are different because a component part became obsolete. This may lead to a blank display and sometimes loss of button function when the LCD display or the CPU do not restart properly. The installer supplied wiring and loads engaged when starting the vehicle, may have an impact on whether the issue presents itself in any one vehicle installation.

FMVSS 1: NR FMVSS 2: NR

Description of the Safety Risk: However, the identified units may not restart on their own if the voltage dips

out of range (less than 9 volts) which can increase the risk of injury. These units are different because a component part became obsolete. This may lead to a blank display and sometimes loss of button function when the LCD display or the CPU do not restart properly. The installer supplied wiring and loads engaged when starting the vehicle, may have an impact on whether the

issue presents itself in any one vehicle installation.

Description of the Cause: NR
Identification of Any Warning NR

that can Occur:

Involved Components:

Component Name 1 : Vista IV Component Description : 6" Arm

Component Part Number: 6241-1011-58

Supplier Identification:

Component Manufacturer

Name: Weldon

Address: 607 NW 27th Ave

Ocala Florida 34475

Country: United States

Chronology:

10-28-2020 We received a letter from Weldon about the recall.

We notified the customer involved with the recall.

Description of Remedy:

Description of Remedy Program: Weldon will be remedying affected units on affected units free of charge,

but in the meantime, cycling the power will reset the unit and allows normal operation. This can be accomplished with a power reset button, if so equipped, or by restarting the vehicle to allow on existing display to

operate.

How Remedy Component Differs Weldon will be remedying affected units on affected units free of charge, from Recalled Component: but in the meantime, cycling the power will reset the unit and allows normal operation. This can be accomplished with a power reset button, if so equipped, or by restarting the vehicle to allow on existing display to

operate.

Identify How/When Recall Condition NR

was Corrected in Production:

Recall Schedule:

Description of Recall Schedule: The recall was received on 10-28-2020. The customer was notified and

Weldon shipped the customer a new unit.

Planned Dealer Notification Date: NR - NR Planned Owner Notification Date: NR - NR

* NR - Not Reported