OMB Control No.: 2127-0004

Not sequential

Part 573 Safety Recall Report

21V-679

Manufacturer Name: Porsche Cars North America, Inc.

Submission Date: SEP 01, 2021 NHTSA Recall No.: 21V-679 Manufacturer Recall No.: AMB7



Manufacturer Information:

Manufacturer Name: Porsche Cars North America, Inc.

Address: One Porsche Drive

Atlanta GA 30354

Company phone: 1-800-767-7243

Population:

Number of potentially involved: 4,934 Estimated percentage with defect: 100 %

Vehicle Information:

Vehicle 1: 2013-2014 Porsche Boxster S

Vehicle Type: LIGHT VEHICLES

Body Style : 2-DOOR Power Train : GAS

Descriptive Information: Affected vehicles have been identified through production records.

Vehicles included in this recall may have been equipped with an out-of-specification

rear-axle carrier side section.

Production Dates: SEP 05, 2012 - JUL 31, 2014

VIN Range 1 : Begin : NR End : NR

Vehicle 2: 2013-2015 Porsche Boxster

Vehicle Type: LIGHT VEHICLES

Body Style : 2-DOOR Power Train : GAS

Descriptive Information: Affected vehicles have been identified through production records.

Vehicles included in this recall may have been equipped with an out-of-specification

rear-axle carrier side section.

Production Dates: SEP 01, 2012 - JUL 31, 2014

Vehicle 3:	2014-2015 Porsche Cayman			
	LIGHT VEHICLES			
Body Style :	2-DOOR			
Power Train :	GAS			
Descriptive Information :	Affected vehicles have been identified through production records.			
	Vehicles included in this recall may have been equipped with an out-of-specification rear-axle carrier side section.			
Production Dates :	JAN 18, 2013 - JUL 31, 2014			
VIN Range 1:	Begin:	NR	End: NR	☐ Not sequential
Vehicle 4:	2014-2015 Por	sche Cayman S		
Vehicle Type :	LIGHT VEHICLES			
Body Style :				
Power Train :	GAS			
Descriptive Information :	Affected vehicles have been identified through production records.			
	Vehicles included in this recall may have been equipped with an out-of-specification rear-axle carrier side section.			
Production Dates :	DEC 17, 2012 -	JUL 30, 2014		
VIN Range 1:		NR	End: NR	■ Not sequential
Vehicle 5: 2015-2015 Porsche Cayman GTS				
	LIGHT VEHICLES			
Body Style :				
Power Train :				
Descriptive Information :	Affected vehicles have been identified through production records.			
	Vehicles included in this recall may have been equipped with an out-of-specification rear-axle carrier side section.			
Production Dates :	MAY 26, 2014 - JUL 29, 2014			
VIN Range 1:		NR	End: NR	☐ Not sequential

Vehicle 6: 2015-2015 Porsche Boxster GTS

Vehicle Type: LIGHT VEHICLES

Body Style : 2-DOOR Power Train : GAS

Descriptive Information: Affected vehicles have been identified through production records.

Vehicles included in this recall may have been equipped with an out-of-specification

rear-axle carrier side section.

Production Dates: MAY 19, 2014 - JUL 29, 2014

Description of Defect:

Description of the Defect: On the affected vehicles, there is a possibility that rear-axle carrier side

sections were installed during a certain period that do not meet the required

specifications due to a manufacturing defect.

FMVSS 1: NR FMVSS 2: NR

Description of the Safety Risk: Out of specification parts, may result in cracks or even may break over

lifetime. A fracture of both mounts could result in a potential loss of vehicle

control increasing the risk of a crash.

Description of the Cause: Material analysis indicates that on certain component production dates the

proportion of strontium in the cast component rear-axle carrier side section exceeds the specified threshold. This results in a deterioration of the material

properties.

Identification of Any Warning A rattling noise may be heard from the rear, however a warning is not ensured.

that can Occur:

Involved Components:

Component Name 1: Carrier Side Part

Component Description: The rear-axle carrier side section represents the connection to the chassis

components.

Component Part Number: NR

Supplier Identification:

Component Manufacturer

Name: Brabant Alucast Services Deutschland Gmb

Address: Wertstraße 23

Wendlingen am Neckar Foreign States 73240

Country: Germany

Chronology:

In March 2020 Porsche noted certain carrier side panels showed material abnormalities.

An initial assessment showed no immediate impact to the overall functionality and further analyses were deemed necessary to better understand the potential impact after an extended period of use.

In September 2020 a decision was made to initiate a detailed evaluation of field parts to analyze the effects by conducting a field study.

September 2020 - April 2021: first test results were available and reviewed. Some of the parts showed Strontium proportions out of specification.

April 2021 – June 2021: The further procedure regarding the evaluation of possible failure chain was coordinated and a test program for service life / residual service life was defined and performed.

July 2021 Consolidation, evaluation and reconciliation of test results showed 10 parts out of 153 which developed cracks in the subject component.

In August 2021, the final assessment was available and additional field data revealed one part with cracks in the second carrier. August 25, 2021, Porsche decided to conduct a voluntary safety recall out of abundance of caution.

Description of Remedy:

Description of Remedy Program : The affected rear-axle carrier side sections will be replaced with new

carrier side parts produced to the original specification.

How Remedy Component Differs The remedy components are manufactured within the original design

from Recalled Component: specification.

Identify How/When Recall Condition Since the beginning of 2019 the supplier was changed.

was Corrected in Production:

Recall Schedule:

Description of Recall Schedule: NR

Planned Dealer Notification Date : SEP 15, 2021 - NR Planned Owner Notification Date : NOV 01, 2021 - NR

* NR - Not Reported