

October 1, 2021

Version 1

Safety Recall: 2022 Odyssey Bridgestone Tire Inspection

AFFECTED VEHICLES

Year	Model	Trim	VIN Range
2022	Odyssey	ALL	Check the iN VIN status for eligibility

BACKGROUND

An electrical short occurred during the DOT label laser etching process, potentially causing the laser to burn a pinhole through the tire sidewall. Should the pinhole penetrate the tire's inner liner, a slow air loss may occur. If left unaddressed, this slow leak could affect tire performance and, depending upon other circumstances, increase the risk of a crash.

CUSTOMER NOTIFICATION

Owners of affected vehicles will be sent a notification of this campaign.

Do an iN VIN status inquiry to make sure the vehicle is shown as eligible.

Some vehicles affected by this campaign may be in your new or used vehicle inventory.

Failure to repair a vehicle subject to a recall or campaign may subject your dealership to claims or lawsuits from the customer or anyone else harmed as a result of such failure. To see if a vehicle in inventory is affected by this safety recall, do a VIN status inquiry before selling it.

CORRECTIVE ACTION

Inspect the DOT date code number for blemishes or marks on all 4 tires. Then, replace the tire(s) if needed.

PARTS INFORMATION

Part Name	Part Number	Quantity
Bridgestone Turanza EL440 Grand Touring A/S Tire	42751-BRI-126	1

CUSTOMER INFORMATION: The information in this bulletin is intended for use only by skilled technicians who have the proper tools, equipment, and training to correctly and safely maintain your vehicle. These procedures should not be attempted by "do-it-yourselfers," and you should not assume this bulletin applies to your vehicle, or that your vehicle has the condition described. To determine whether this information applies, contact an authorized Honda automobile dealer.

WARRANTY CLAIM INFORMATION

NOTE:

- Required photos must be included when submitting your claim, or the claim may be subject to a debit. The photos must be clear; retake any unclear photos before submitting.
- New tires must be purchased through Tire Rack when replacing a tire using this bulletin.
- To submit a warranty claim for dealer-installed tire replacement, select the T3 sublet code in the Sublet Information field and enter the total sublet amount.
- For tire handling reimbursement, select the T4 sublet code in a different Sublet Information field. Then multiply the number of replaced tires by \$10.00. Add the total handling amount in the second sublet field.

Sublet Information				
Sublet Code	Work Description	Invoice No.	Rental Days	Sublet Amount
T3	SUBLET TIRE PURCHASE	123456		50.00
T4	TIRE PURCHASE HANDLING	123456		10.00

Upload files File Attachments

Operation Number	Description	Flat Rate Time	Defect Code	Symptom Code	Template ID	Failed Part Number
4215B3	Inspect the DOT date code numbers of all four tires. (Photos of DOT date code numbers of all tires. No tire replacement).	0.2 hr	6TZ00	HBL00	A21080A	42751-BRI-126
4215B4	Remove the wheel assembly from the vehicle and mount on the machine. Mount and balance one (1) new tire. (Includes inspection and photos of the DOT date code and location of all tires).	0.5 hr	6TZ00	HBL00	A21080B	42751-BRI-126

INSPECTION PROCEDURE

1. Locate and take photos of the complete DOT Code on all 4 tires.

NOTE:

- Above the DOT number of each tire, mark its location on the vehicle. For example: Left Front: LF, Left Rear: LR, Right Front: RF, Right Rear: RR.
- Clear photos of the DOT code, tire location and date code of all 4 tires must be submitted with the warranty claim.



Are the last 4 digits of the tire date code 2821?

YES —Go to Step 2 to inspect for blemishes or marks.

NO —No inspection for blemishes or marks required.

2. Inspect the area around the 4-digit date code 2821. If these four numbers are clear, sharp and contain no blemishes or marks, the tire is not impacted by this recall. If the tire has a blemish or mark, which might include a small pin-hole on or above the first digit of the date code 2821 as shown below, the tire is impacted by this recall and **MUST BE REPLACED**.

(Examples of blemishes that require tire replacement).



Are blemishes or marks present on any of the tire date codes 2821?

YES — Go to REPAIR PROCEDURE to replace affected tires.

NO —No repair is required.

REPAIR PROCEDURE

1. Replace any tire(s) that have blemishes or marks present on the tire with the DOT date code 2821.
2. Send back the replaced tires to AHM WPI for destruction. Ship the tire(s) to this address:

American Honda – WPI

Building 500, Rollup Door #4

1919 Torrance Blvd.

Torrance, CA 90501

NOTE: Clear photos of the blemishes or marks present on the tire with DOT date code and location of all 4 tires must be submitted with the warranty claim.

END