OMB Control No.: 2127-0004

Part 573 Safety Recall Report

21V-790

Manufacturer Name: HME, Inc.
Submission Date: JUL 08, 2022
NHTSA Recall No.: 21V-790
Manufacturer Recall No.: 21E-032



Manufacturer Information:

Manufacturer Name: HME, Inc.

Address: 1950 Byron Center Ave.

Wyoming MI 49519

Company phone: 616-534-1463

Population:

Number of potentially involved: 245 Estimated percentage with defect: 100 %

Vehicle Information:

Vehicle 1: 2017-2020 HME Ahrens-Fox Model 34 Type 3, Rescue Pumpers, Tanker, Aerial,

CommFox, Wolf SA Tanker, 1871-SFO, 1871-W, 1871-Spectr, AF1

Vehicle Type: BUSES, MEDIUM & HEAVY VEHICLES

Body Style : 4-DOOR Power Train : DIESEL

Descriptive Information: These engines are equipped with High Pressure Common Rail fuel systems which

includes a high pressure fuel rail. The production begin and enddates were determined from the manufacturing and quality records thatestablished the

population of high pressure rails and engines that may contain the defect. The recall consists of engines installed in buses, schoolbuses, emergency vehicles, recreational vehicles and trailer-mountedgenerator sets due to relatively low detectability of the

potential hazard and relatively high vulnerability to potential injury in those

applications.

Production Dates: JAN 02, 2017 - DEC 31, 2020

Description of Defect:

Description of the Defect: The fuel rail assembly may develop leaks, which may result in an undetected

prolonged diesel fuel spray.

FMVSS 1: NR FMVSS 2: NR

Description of the Safety Risk: A leak involving spraying/misting fuel in the presence of an ignition source

may increase the risk of fire.

Description of the Cause: The rail end sealing bores in the fuel rail may have undersized pilot bores

for the sealing washer, thus preventing the washer from properly seating, potentially resulting in inadequate load for the joint to remain properly

sealedin service.

that can Occur: may illuminate.

Identification of Any Warning The operator may see or smell diesel fuel. In some cases, the check engine lamp

Involved Components:

Component Name 1: Accumulator

Component Description: high pressure fuel rail assembly

Component Part Number: 4307377

Supplier Identification:

Component Manufacturer

Name: Senior Flexonics Land Vehicle

Address: 300 East Devon Avenue

Bartlett Illinois 60103

Country: United States

Chronology:

February 10, 2021 - A field service technician reported to Cummins that eight buses belonging to a single customer had been repaired since December 2020for leaks at sealing washers in the fuel rail. February 11-March 1, 2021 – Cummins investigated the cause of the leaks with the supplier of the rail and beganan investigation of field warranty claims. Cummins conducted an initial Product Safety Hazard Analysis. March 3 – April 12, 2021 - Cummins escalated theissue through its Product Safety Defect Board process, gathered additional data and revised the Product Safety Hazard Analysis. Cummins issued a TechnicalService Bulletin (TSB210055) on March 4, 2021 to allow the field to replace rails that have washer leaks with a different rail and their associated fuel lines. (TSB210055 was submitted to NHTSA on April 7, 2021 in accordance with 49 CFR Part 579.5.) April 13, 2021 – Based upon the results of the investigation, Cummins' Product Defect Safety Board decided to conduct a safety campaign on engines installed in buses, school buses, emergency vehicle and recreational vehicle applications and certain other off-road applications, including generators. May 19, 2021 -Cummins determined that 378 L9 engines that were mounted by Cummins Power Systems onto trailers for use in mobile generator set applications should be added to the recall population. To date, there have been no reports of accidents, fires or injuries related to this condition.

Description of Remedy:

Description of Remedy Program: A recall-specific reimbursement plan will be provided in the Recall Portal

for those units not covered by the manufacturer's limited warranty. The rail threads will be inspected for damage. If damage is found on the threads, the rail will be replaced with a rail of a different design. The fuel lines will also be replaced with lines of a different design if the rail is replaced. If no damage is found on the threads, new crush washers will be

installed using a special tool.

Cummins will be handling all quarterly reporting for this Recall.

How Remedy Component Differs For units having no thread damage, the technician will be instructed to from Recalled Component: place a paint dot somewhere on the rail to indicate that the repair has been completed. For units that do have thread damage, the replacement rail and fuel lines will have unique part numbers. The replacement rail and

lines are also visibly different.

Identify How/When Recall Condition The rail manufacturing statistical process control for the pilot bores was was Corrected in Production: confirmed in control after October 19, 2020.

Recall Schedule:

Description of Recall Schedule: Cummins expects to notify affected OEMs no later than April 30, 2021.

Cummins will conduct the recall and notify owners. The timing of ownernotification will be determined in consultation with the affected OEMs.Cummins expects to begin sending interim notification letters on June 19,2021 to owners for which Cummins has received owner addresses. WhenCummins is ready to implement the remedy campaign, Cummins will notifyall owners for which it has received owner information. Owners who previously received an interim letter notification will receive a secondnotification. Cummins anticipates mailing owner letters communicating theavailability of the remedy

during July 2021.

Planned Dealer Notification Date: OCT 15, 2021 - OCT 15, 2021 Planned Owner Notification Date: OCT 15, 2021 - OCT 15, 2021

* NR - Not Reported