

Part 573 Safety Recall Report

21V-808

Manufacturer Name : HME, Inc.

Submission Date : OCT 15, 2021

NHTSA Recall No. : 21V-808

Manufacturer Recall No. : NR



Manufacturer Information :

Manufacturer Name : HME, Inc.

Address : 1950 Byron Center Ave.
Wyoming MI 49519

Company phone : 616-534-1463

Population :

Number of potentially involved : NR

Estimated percentage with defect : NR

Vehicle Information :

Vehicle 1 : 2019-2019 Ram 5500

Vehicle Type : LIGHT VEHICLES

Body Style : PICKUP TRUCK

Power Train : DIESEL

Descriptive Information : RAM Y21/NHTSA 21V-439 recall states: The Powertrain Control Module may have an oil life monitor strategy that does not provide adequate warning of oil consumption which may allow engine oil volume to fall below an acceptable level. Low oil volume in the engine can cause a lack of oil film on the main bearings, deteriorating the bearing which can result in engine damage, which may puncture the engine block and may lead to a vehicle fire which increases the risk of injury to occupants and persons outside the vehicle, as well as property damage.

Production Dates : JAN 02, 2019 - DEC 31, 2019

VIN Range 1 : Begin :

NR

End : NR

☐ Not sequential

Description of Defect :

Description of the Defect : RAM Y21/NHTSA 21V-439 recall states: The Powertrain Control Module may have an oil life monitor strategy that does not provide adequate warning of oil consumption which may allow engine oil volume to fall below an acceptable level. Low oil volume in the engine can cause a lack of oil film on the main bearings, deteriorating the bearing which can result in engine damage, which may puncture the engine block and may lead to a vehicle fire which increases the risk of injury to occupants and persons outside the vehicle, as well as property damage.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : Low oil volume in the engine can cause a lack of oil film on the main bearings, deteriorating the bearing which can result in engine damage, which may puncture the engine block and may lead to a vehicle fire which increases the

risk of injury to occupants and persons outside the vehicle, as well as property damage.

Description of the Cause : NR

Identification of Any Warning
that can Occur : NR

Involved Components :

Component Name 1 : NR

Component Description : NR

Component Part Number : NR

Supplier Identification :

Component Manufacturer

Name : NR

Address : NR

NR

Country : NR

Chronology :

NR

Description of Remedy :

Description of Remedy Program : FCA US will repair the vehicle free of charge (parts and labor). Dealerships will reprogram the powertrain control module. The estimated repair time is about a half an hour.

How Remedy Component Differs
from Recalled Component : NR

Identify How/When Recall Condition
was Corrected in Production : NR

Recall Schedule :

Description of Recall Schedule : NR

Planned Dealer Notification Date : NR - NR

Planned Owner Notification Date : NR - NR

* NR - Not Reported