Recall Campaign Bulletin



Campaign No. 2021110010, November 2021

Recall Campaign Bulletin

Recall Campaign Bulletin

TO: ALL MERCEDES-BENZ CENTERS

SUBJECT: Model GLE-Class, GLS-Class and C-Class (167 and 205 platform)

Model Year 2020-2021

Check All Seat Assemblies

Mercedes-Benz AG ("MBAG"), he manufacturer of Mercedes-Benz vehicles, has determined that on certain Model Year ("MY") 2020-2021 GLE-Class/GLS-Class (167 platform) and C-Class (205 platform) vehicles, the seat assembly might not meet current production specifications. Various components of the seats may not have been installed or may not match production specifications. An authorized Mercedes-Benz dealer will inspect various components of the seats and ensure that all seats are assembled according to current production specifications.

Prior to performing this Campaign:

- VMI must always be checked before performing campaigns to verify that the campaign is required on a specific vehicle. Always check for any other open campaigns, and perform accordingly.
- Please review the entire Campaign bulletin and follow the repair procedure exactly as described.

Approximately 27 vehicles are affected.

Order No. P-SC-2021110010

This bulletin has been created and maintained in accordance with MBUSA-SLP S423QH001, Document and Data Control, and MBUSA-SLP S424HH001, Control of Quality Record

Check All Seat Assemblies

Model 167 and 205

Check/test	procedure
------------	-----------

1. Check all threaded connections for the attachment of the seats on the vehicle for correct torque. Torque of threaded connections of complete seats 50 Nm in model 167 (left and right front seat, third seat row)! I For basic data for front seats, see AR91.10-P-1000ME for model 167. I For basic data for second seat row, see AR91.12-P-4026ME for model 167. I For basic data for third seat row, see AR91.12-P-0007MEX for model 167. I Torque of threaded connections of front seats 50 Nm in model 205! I For basic data for front seats, see AR91.10-P-1000LW for model 205. I Torque of threaded connections of rear seat cushions 8 Nm in model 205! I For basic data for rear seat cushion, see AR91.12-P-1020LWA for model 205. I Torque of threaded connections of rear seat backrest 40 Nm in model 205! I For basic data for rear seat backrest, see AR91.12-P-1620LW for model 205 without code I For basic data for rear seat backrest, see AR91.12-P-1720LW for model 205 with code 28 For basic data for rear seat backrest, see AR91.12-P-1720LW for model 205 with code 28 Check whether the seats of the second seat row (seat cushion, seat backrest, side cushion and arm and correspond to the correct equipment variant. I The side cushions and the armrest are installed depending on the equipment variant. Check whether the seats of the third seat row (seat cushion and seat backrest) are present and correct equipment variant. Check whether the switch for the seat backrest release (easy entry feature/seat release) and the emstrap (figure 1) are present at the second seat row. Only in model 167.9 and 167.1 with code 567 (REAR SEAT FORE/AFT ADJUSTMENT)! Only for vehicles with the third seat row equipment variant. For basic data for seat backrest release switch, see AR91.29-P-7061MEB.	test procedure must be performed on the left and right front
 Torque of threaded connections of rear seat cushions 8 Nm in model 205! i For basic data for rear seat cushion, see AR91.12-P-1020LWA for model 205. i For basic data for rear seat cushion, see AR91.12-P-1020LWA for model 205. i Torque of threaded connections of rear seat backrest 40 Nm in model 205! i For basic data for rear seat backrest, see AR91.12-P-1620LW for model 205 without code i For basic data for rear seat backrest, see AR91.12-P-1720LW for model 205 with code 28 Check whether the seats of the second seat row (seat cushion, seat backrest, side cushion and arm and correspond to the correct equipment variant. i The side cushions and the armrest are installed depending on the equipment variant. Check whether the seats of the third seat row (seat cushion and seat backrest) are present and correct equipment variant. Check whether the switch for the seat backrest release (easy entry feature/seat release) and the emstrap (figure 1) are present at the second seat row. Only in model 167.9 and 167.1 with code 567 (REAR SEAT FORE/AFT ADJUSTMENT)! Only for vehicles with the third seat row equipment variant. 	1000ME for model 167. .12-P-4026ME for model 167.
Torque of threaded connections of rear seat backrest 40 Nm in model 205! I For basic data for rear seat backrest, see AR91.12-P-1620LW for model 205 without code I For basic data for rear seat backrest, see AR91.12-P-1720LW for model 205 with code 28 Check whether the seats of the second seat row (seat cushion, seat backrest, side cushion and arm and correspond to the correct equipment variant. I The side cushions and the armrest are installed depending on the equipment variant. Check whether the seats of the third seat row (seat cushion and seat backrest) are present and correct equipment variant. Check whether the seats of the third seat row (seat cushion and seat backrest) are present and correct equipment variant. Check whether the switch for the seat backrest release (easy entry feature/seat release) and the emstrap (figure 1) are present at the second seat row. Only in model 167.9 and 167.1 with code 567 (REAR SEAT FORE/AFT ADJUSTMENT)! Only for vehicles with the third seat row equipment variant.	
For basic data for rear seat backrest, see AR91.12-P-1620LW for model 205 without code in For basic data for rear seat backrest, see AR91.12-P-1720LW for model 205 with code 282. Check whether the seats of the second seat row (seat cushion, seat backrest, side cushion and arm and correspond to the correct equipment variant. The side cushions and the armrest are installed depending on the equipment variant. Check whether the seats of the third seat row (seat cushion and seat backrest) are present and correct equipment variant. Check whether the switch for the seat backrest release (easy entry feature/seat release) and the emstrap (figure 1) are present at the second seat row. Only in model 167.9 and 167.1 with code 567 (REAR SEAT FORE/AFT ADJUSTMENT)! Only for vehicles with the third seat row equipment variant.	
 and correspond to the correct equipment variant. The side cushions and the armrest are installed depending on the equipment variant. Check whether the seats of the third seat row (seat cushion and seat backrest) are present and correct equipment variant. Check whether the switch for the seat backrest release (easy entry feature/seat release) and the emstrap (figure 1) are present at the second seat row. Only in model 167.9 and 167.1 with code 567 (REAR SEAT FORE/AFT ADJUSTMENT)! Only for vehicles with the third seat row equipment variant. 	1.12-P-1620LW for model 205 without code 287.
 Check whether the switch for the seat backrest release (easy entry feature/seat release) and the emstrap (figure 1) are present at the second seat row. Only in model 167.9 and 167.1 with code 567 (REAR SEAT FORE/AFT ADJUSTMENT)! Only for vehicles with the third seat row equipment variant. 	, ,
strap (figure 1) are present at the second seat row. i Only in model 167.9 and 167.1 with code 567 (REAR SEAT FORE/AFT ADJUSTMENT)! Only for vehicles with the third seat row equipment variant.	nion and seat backrest) are present and correspond to the
	AR SEAT FORE/AFT ADJUSTMENT)! variant.



- 5. Check whether all head restraints correspond to the correct version in accordance with the vehicle equipment variant (manual or electrical) and that the head restraint guides are present.
 - **5.1.** Carry out visual check of head restraints.

 - For vehicles with **manual** head restraints.

 5.1.1. Check whether the head restraint guides are present and that the version is correct.
 - $oxed{1}$ There must be two head restraint guides present per head restraint. One head restraint guide with release knob and one without release knob.
 - **5.1.2.** Check whether the detent notches are present on one of the head restraint bars.

 - For vehicles with **electrical** head restraints.

 5.1.3. Check whether the head restraint guides are present and that the version is correct.
 - Li There must be two head restraint guides without release knob present per head restraint.
 - **5.1.4.** Check whether there are no detent notches present on the head restraint bars.

Head restraint:

- i For basic data on front seat, see **AR91.16-P-0040ME** for model 167.
- i For basic data on second seat row, see AR91.16-P-1770ME for model 167.
- i For basic data on third seat row, see AR91.16-P-0005MEX for model 167.
- i For basic data on front seat, see AR91.16-P-0040LW for model 205.
- i For basic data on second seat row, see AR91.16-P-1770LW for model 205.

Head restraint guide:

- Li For basic data on front seat, see AR91.16-P-0051M for model 167.
- i For basic data on second seat row, see AR91.16-P-1776ME for model 167.
- i For basic data on third seat row, see AR91.16-P-0006MEX for model 167.
- For basic data on front seat, see AR91.16-P-0050LW for model 205.
- i For basic data on second seat row, see AR91.16-P-1775LW for model 205.
- **5.2.** Perform function test of head restraints.
- $oxed{f i}$ For basic data on front seat head restraint motor, see **AR91.29-P-1432ME** for model 167.
- For basic data on head restraint motor at second seat row, see AR91.29-P-1460ME for model 167.
- For basic data on front seat head restraint motor, see AR91.29-P-1432LW for model 205.

6. Check whether the threaded connections of the seat backrest trim **(A, figure 2)** at the front seats (driver and front passenger seat) are present and correctly attached.

 \square Only for **model 167**.

For basic data, see AR91.10-P-1912ME for model 167.



Figure 2

7. Check whether the fire extinguisher holder (B) at the driver's seat and fire extinguisher (C) are present (figure 3).

i Only for vehicles with code 682 (FIRE EXTINGUISHER).





Figure 3

8. Check whether the side inner trims **(D, figure 4)** and side outer trims **(E and F, figure 5)** at the front seats (driver and front passenger seat) are present.

i For basic data, see **AR91.10-P-1200ME** for model 167.

For basic data for inner trim, see AR91.10-P-1202LW for model 205.

For basic data for outer trim, see AR91.10-P-1201LWA for model 205.






Figure 4

Figure 5

- **9.** Check whether the covers for the child seat anchors at the second seat row are present and correspond to the correct equipment variant (figure 6 sample illustration).
 - Li Depending on the equipment variant, ISOFIX or i-Size child seat anchors.
- **10.** Check whether the covers for the child seat anchors at the third seat row are present and correspond to the correct equipment variant (figure 6 sample illustration).
 - i Only for model 167.9.
 - Li Depending on the equipment variant, ISOFIX or i-Size child seat anchors.



Figure 6

- 11. Check whether the cover of the seat belt guide for the lap belt of the second seat row is present.
 - i For basic data, see AR91.40-P-0683ME for model 167.
 - i For basic data, see AR68.30-P-4581LW for model 205.
- **12.** Check whether correct equipment variant of seat adjustment unit at the front seats is present.
 - The Hall sensors (figure 7) may **only** be installed in vehicles **with** code **494** (USA VERSION) or **460** (CANADA VERSION).

The Hall sensor is located, in each case, on the inner side of the seat adjustment unit of the front seats.



Figure 7

- a. Complete seats OK: Perform work procedure A .
- b. Component part or component parts of seats not OK: Perform work procedure A and B.

Work procedure A

- i Work procedure A must only be performed on vehicles with the following vehicle identification numbers (VIN).
 - W1N1671172A263162
 - 55S2050841U334930
 - 55\$2050841U334934
- 1. Replace seat cushion for front passenger seat.
 - i For basic data, see AR91.10-P-3310ME for model 167.
 - Li For basic data, see AR91.10-P-5040LWA for model 205 without code 221.
 - For basic data, see AR91.10-P-5040LW for model 205 with code 221.

Work procedure B

1.	Replace affected component parts.
	i The associated work instructions (AR) documents must be taken from the WIS system in accordance with the

1 The associated work instructions (AR) documents must be taken from the WIS system in accordance with the equipment variant for the vehicle identification number.

If the Hall sensors of the seat adjustment unit at the front seats have been installed in vehicles **without** code **494** (USA VERSION) or **460** (CANADA VERSION), the seat adjustment unit at the front seats must be replaced by the correct version in accordance with the vehicle equipment variant!

If - in spite of code **494** (USA VERSION) or **460** (CANADA VERSION) - no Hall sensors and no associated cutout in the seat adjustment unit are present, the seat adjustment unit must be replaced by the correct equipment variant and the Hall sensor installed.

For the installation of the Hall sensors of the seat adjustment unit at the front seats in vehicles **with** code **494** (USA VERSION) or **460** (CANADA VERSION), please proceed as follows.

1.1. Release front seat and remove **rear cover caps** (if present) from seat rails of seat adjustment unit.

- **1.2.** Place suitable pads behind the seat adjustment unit to protect the floor covering against damage/pressure marks caused by the seat rails of the seat adjustment unit when the front seat is tilted.
- **1.3.** Switch off ignition.
- 1.4. Clip Hall sensor (G, figure 7) into envisaged cutout in the seat adjustment unit.
- 1.5. Attach Hall sensor (G, figure 7) using screw (H, figure 7) to seat adjustment unit.
- Screw, Hall sensor to seat adjustment unit 3.5 [Hm].
- i Connect electrical connector.




Figure 7

1.6. Assemble in reverse order.

Primary Parts Information

Qty.	Part Name	Part Number
As required *	*	*

^{*} The replacement parts must be determined according to the equipment variant for the vehicle identification number via the parts process in the Xentry Portal.

Small parts such as screws, lock nuts, sealing rings, cable ties, fluids, sealant, etc. are not listed in the parts list. The required small parts are taken into account in the budgeting.

Note: The following allowable labor operation should be used when submitting a warranty claim for this repair.

Warranty Information

Damage Code	Operation Number	Description	Labor Time (hrs.)
	02-0771	Check complete seats	1.9
	02-0772	Replace seat cushion for front passenger seat (after check) model 167 Includes: Disconnect/connect ground line of battery of 12 V on-board electrical system, remove/install front passenger seat; calibrate WSS sensors	1.8
91 900 15	02-0772	Replace seat cushion for front passenger seat (after check) model 205.0 Includes: Disconnect/connect ground line of battery of 12 V on-board electrical system, remove/install front passenger seat; calibrate WSS sensors	1.6
	02-0773	Replace affected component part (after check)	ZM
	02-4762*	Connect/disconnect vehicle diagnosis system (XENTRY Diagnosis)	0.1
	02-5058*	Connect/disconnect starter battery charger (with XENTRY Diagnosis connected)	0.1

^{*} Operation item may only be invoiced once for each workshop order!

i Note: Always check ASRA for the current OP-Code times. Labor times are subject to change and updates may not be reflected in this document.