NR

Part 573 Safety Recall Report

Manufacturer Name :Ferrari North America, Inc.Submission Date :OCT 28, 2021NHTSA Recall No. :21V-833Manufacturer Recall No. :78

Manufacturer Information :

Manufacturer Name : Ferrari North America, Inc. Address : 250 Sylvan Avenue Englewood Cliffs NJ 07632-2500

Company phone : 1800-999-9999

Vehicle Information :

Vehicle 1:	2016-2019 Ferrari 488	
Vehicle Type :	LIGHT VEHICLES	
Body Style :	2-DOOR	
Power Train :	GAS	
Descriptive Information :	Ferrari has determined that a defect related to motor vehicle safety may arise in some MY 2016 - 2019 Ferrari 488 vehicles. These vehicles are equipped with a braking system that could potentially leak brake fluid, which may lead to partial or total loss of braking capability.	
Production Dates :	JUL 22, 2015 - AUG 28, 2019	
VIN Range 1:	Begin : ZFF79ALA1G0213176 End : ZFF79ALA2K0246793 📝 Not sequential	
Vehicle 2:	2010-2015 Ferrari 458	
Vehicle Type :	LIGHT VEHICLES	
Body Style :	2-DOOR	
Power Train :	GAS	
Descriptive Information :	Unknown at this time. Ferrari and the supplier of the brake booster/pump assembly, Bosch, are continuing to investigate this issue. The assembly is common to the Ferrari 458 and 488 models.	
Production Dates : SEP 26, 2009 - DEC 02, 2015		
VIN Range 1:Begin: ZFF67NHB000170100 End: ZFF75VFA4F0213136 Not sequential		

Description of Defect :

Description of the Defect : Ferrari has determined that a defect related to motor vehicle safety may arise in some MY 2010 - 2015 Ferrari 458 vehicles and some MY 2016 - 2019 Ferrari 488 vehicles. These vehicles are equipped with a braking system that could potentially leak brake fluid, which may lead to partial or total loss of braking capability.

The information contained in this report was submitted pursuant to 49 CFR §573



Number of potentially involved : 5,601

Estimated percentage with defect :

Population:

21V-833

FMVSS 1	ND
FMVSS 1 FMVSS 2	
	Upon total loss of brake fluid, the vehicle would lose braking capability, which may result in injury or death to vehicle occupants.
Description of the Cause	Unknown at this time. Ferrari and the supplier of the brake booster/pump assembly, Bosch, are continuing to investigate this issue.
	When the quantity of brake fluid in the relevant reservoir decreases by 52 % of the maximum reservoir level (so that a percentage equal to 48 % is still in such reservoir) a message will appear on the vehicle's dashboard that reads as follows: "Brake fluid level low, Go to dealer slowly". Additionally, a warning light will also appear on the dashboard and an acoustic buzzer will sound.
nvolved Components :	
-	master cylinder/brake booster assembly
Component Name 1 :	master cylinder/brake booster assembly master cylinder/brake booster assembly
Component Name 1 :	master cylinder/brake booster assembly
Component Name 1 : Component Description :	master cylinder/brake booster assembly
Component Name 1 : Component Description :	master cylinder/brake booster assembly
Component Name 1 : Component Description :	master cylinder/brake booster assembly
Component Name 1 : Component Description : Component Part Number :	master cylinder/brake booster assembly
Component Name 1 : Component Description : Component Part Number : Supplier Identification :	master cylinder/brake booster assembly
Component Name 1 : Component Description : Component Part Number : Supplier Identification : Component Manufacturer	master cylinder/brake booster assembly 000244010
Component Description : Component Part Number : Supplier Identification :	master cylinder/brake booster assembly 000244010
Component Name 1 : Component Description : Component Part Number : Supplier Identification : Component Manufacturer	master cylinder/brake booster assembly 000244010
Component Name 1 : Component Description : Component Part Number : Supplier Identification : Component Manufacturer Name : Robert Bosch Gm	master cylinder/brake booster assembly 000244010 bH

Chronology :

See attached chronology.

The information contained in this report was submitted pursuant to 49 CFR \$573

Planned Owner Notification Date : DEC 21, 2021 - NR

Description of Remedy :

Description of Remedy Program :	Ferrari is not yet aware of the root cause of this problem, nor the number of vehicles actually affected by it. Ferrari intends to send an interim notice letter to all 458 and 488 vehicle owners to warn them of this issue, and instruct them that if the "low Brake Fluid" warning message appears on the vehicle dashboard, the driver should pull off the road as soon as it is safe to do so, and then contact Ferrari Roadside Assistance and get towed to the nearest authorized Ferrari dealer.
How Remedy Component Differs from Recalled Component :	
•	The Ferrari 458 and 488 model vehicles are no longer in production, and subsequent Ferrari models do not use the same brake master cylinder/brake booster component.
Recall Schedule :	
Description of Recall Schedule :	To be determined. Ferrari is not yet aware of the root cause of this problem, nor the number of vehicles actually affected by it.
Planned Dealer Notification Date :	1 5 5

* NR - Not Reported

The information contained in this report was submitted pursuant to 49 CFR \$573