Part 573 Safety Recall Report

Manufacturer Name :Kovatch Mobile Equipment Corp.Submission Date :MAR 25, 2022NHTSA Recall No. :21V-905Manufacturer Recall No. :NR



Manufacturer Name :Kovatch Mobile Equipment Corp.Address :One Industrial Complex
Nesquehoning PA 18240Company phone :8002353926

Population :

Number of potentially involved :26Estimated percentage with defect :100 %

云 🔨 🗛 🖈

NATIONAL HIGHWAY TRAFFIC SAFETY ADMINISTRATION

21V-905

Vehicle Information :	
-----------------------	--

Vehicle 1:	2022-2022 KME Predato	or Panther	
Vehicle Type :	BUSES, MEDIUM & HEAV	Y VEHICLES	
Body Style :	OTHER		
Power Train :	DIESEL		
Descriptive Information :		using serial numbers provid n the recall were not identifien nther: 12	
Production Dates :	MAR 29, 2021 - JAN 31, 2	2022	
VIN Range 1:	Begin : NR	End: NR	☐ Not sequential
Vehicle Type : Body Style : Power Train :	DIESEL -Population determined	/Y VEHICLES using serial numbers provid	
Production Dates -	-Products not included in potential defect. -2021 KME Severe Servic -2022 KME Severe Servic APR 16, 2021 - OCT 31, 2	ce: 12	ed by Meritor as having the
VIN Range 1:		End: NR	☐ Not sequential
viiv kange 1.	Degin. NK	Liiu. Nit	Not sequential

Part 573 Safety Recall Report

21V-905

Page 2

Vehicle Type : BU Body Style : O			
Power Train :DIESELDescriptive Information :-Population determined using serial numbers provided by Meritor. -Products not included in the recall were not identified by Meritor as having the potential defect. -2022 KME Predatorr: 1			
Production Dates : AU VIN Range 1 : Beg	JG 31, 2021 - AUG 31, 20 gin : NR	D21 End: NR	Not sequential
-			
Description of the Defect :	-	80 series fractured in the spli	ne.
Description of the Defect : FMVSS 1 :	NR	80 series fractured in the spli	ne.
FMVSS 1 : FMVSS 2 :	NR NR		
Description of the Defect : FMVSS 1 :	NR NR If this condition exists which may unintentio		y hit the brake drop hose
Description of the Defect : FMVSS 1 : FMVSS 2 : Description of the Safety Risk :	NR NR If this condition exists which may unintentio lights coming on, poss	, the fracture of the pinion ma nally apply parking brake witl	y hit the brake drop hose nout detection or brake

Component Name 1 :Rear Axle CarrierComponent Description :Pinion ShaftComponent Part Number :180 Series

Supplier Identification :

Component Manufacturer

Name : Meritor

Address : 22021 Skyway Church RD Maxton North Carolina 28364

Country: United States

Chronology :

June 2020 – Pinion crack found on campus in Charlotte during a different PSR.

August – September 2020 - They completed tests to attempt to replicate and could not reproduce the fracture. Implemented 100% mag particle inspection on all 186R series. Meritor Product Engineering provided a high confidence level that this would be an infancy failure (during the carriers first high load event) due to the fracture signature.

April 2021 – Claim created through standard warranty process for pinion crack.

July 2021 – Pinion failure during delivery to the dealer from the plant. Facilitated warranty claim through Meritor, they provided new gear set.

September 2021 – Houston reached out regarding a pinion crack failure while in service (24 hours in service and under 3,000 miles), was second truck of fleet with similar failure. Pinion broke off and damaged the spring brake air supply line. Metro and Houston insisted an inspection method to validate that the rest of the fleet do not have the same failures. This resulted in Meritor completing an on-site ultrasonic test for the rest of the fleet. Meritor provided corrective action and containment dates, as well as their assessment that this issue is low risk.

October 2021 – Spartan risk assessment completed.

October – November 2021 – Reviewed past precedence. Reached out to all REV Fire businesses to check for any Meritor pinion warranty issues. E-One had one failure in the field in October 2021 but a different axle series affected. Met with Meritor to review the cause again and the potential affected population.

November 2021 – Escalated the issue to REV Group Management. February 14, 2022 - Meritor expanded the date range of affected population. February 21, 2022 - Meritor provided remainder of information for KME to determine additional population.

Description of Remedy :

Description of Remedy Program :	Meritor will work with the repair facility to replace the Differential Carrier Housing Assembly. The repair will take approximately 5 hours to complete. There is no cost to the vehicle owner for the recall remedy. Meritor is providing, free of charge, the necessary components to rectify the issue and will pay labor costs for replacing the included components that have not already been replaced during normal maintenance.
How Remedy Component Differs from Recalled Component :	
0	Meritor has implemented containment in their production facility as of April 20, 2021 and corrective action of tooling implementation as of August 2021.

Recall Schedule :

I

Page 4

Description of Recall Schedule :	Dealers will be notified: $12/20/2021-12/23/2021$ Owners will be notified: $01/03/2022-01/07/2022$ Schedule for additional population added $2/2022$: Dealers will be notified: $04/04/2022-04/08/2022$ Owners will be notified: $04/11/2022-04/15/2022$
Planned Dealer Notification Date : Planned Owner Notification Date :	

* NR - Not Reported