

# VOLKSWAGEN

GROUP OF AMERICA

James C. Owens, Acting Administrator  
National Highway Traffic Safety Administration  
1200 New Jersey Avenue, S.E.  
Washington, DC 20590

Christopher T. Sandvig NAME  
Director Title  
Group Customer Protection Department  
248-754-5000 Phone  
248-754-5093 Fax  
March 18, 2022 Date

Subject: Amended Chronology for Audi Recall 90S9/ NHTSA 21V-947  
Gateway Control Module

VOLKSWAGEN GROUP OF AMERICA, INC.  
3800 HAMLIN ROAD  
AUBURN HILLS, MI 48326  
PHONE +1 248 754 5000

Dear Mr. Owens:

Volkswagen hereby submits the following amended chronology associated with the subject recall. Specifically, entries for August 2021 and September 16, 2021, November 2021, and December 2021 are amended in the chronology below.

## Chronology of Defect

August 2020: Audi receives an inquiry from the Chinese authority regarding gateway control module failures due to liquid ingress. At that point the issue was unknown to Audi so far. Investigation regarding root cause and special circumstances commenced. It was found that all cases in China occurred due to a liquid spill on the rear seat bench.

August 2020 - February 2021: The analysis revealed that in case of a liquid ingress, the gateway control module goes into a failsafe mode as part of the safety concept in order to avoid unwanted vehicle reactions. Audi performed a safety assessment to evaluate the potential conditions and consequences that could result from a power shutdown of the gateway control module due to liquid ingress. As part of the investigation, a potential solution for the field and in production was tasked, developed and tested. Audi also conducted a risk assessment which indicated that the risk of a liquid spill leading to a failure of the gateway control module is very low and rare over the lifetime of the vehicle. This was confirmed by the field situation at the time. At the time there were only isolated cases in the North American region and all of them happened after an outside influence, mostly after a beverage spill. Audi continued to monitor the field worldwide regarding this topic.

March 2021: The North American region reported an increase in customer reports related to a gateway control module failure on Q5 vehicles after a liquid spill.

March 2021 - September 2021: Audi conducted additional testing regarding the impacts of a liquid ingress and continued to investigate a potential solution to be implemented in production and in the field. Due to single field cases alleging the failure without a liquid spill an additional investigation was initiated to rule out potential additional root causes for liquid ingress.

August 2021: Audi identified a potential manufacturing issue in the factory in Mexico. Due to a programming error of a glue bead robot, an underbody seam may not have been sealed sufficiently and therefore allow water ingress from underneath in very rare cases when driving through heavy rain or deep puddles. The adjustment to the robot was implemented immediately and analysis continued regarding impact of this additional potential cause for liquid ingress. Audi also noticed an increased number of VOQs and decided to discuss the topic with NHTSA ODI during the company's Quarterly Meeting in September 2021. In the meantime NHTSA ODI contacted VWGoA and requested a meeting to discuss the VOQs.

September 16, 2021: Upon request by NHTSA, Audi presented an overview of the topic and the U.S. market situation to the NHTSA ODI.

October 2021: The Audi Product Safety Committee decided a service campaign in order to install a protective cover for the gateway control module and to seal the underbody in the area of the insufficient glue bead. Audi started to prepare the necessary steps for the launch of the service campaign.

November 2021: In addition to NHTSA, meetings with other countries' safety agencies demonstrated concerns that a shutdown of the gateway control module due to liquid ingress may happen suddenly and the behavior may be perceived as a loss of mobility.

December 01, 2021: The concerns of NHTSA and other safety agencies were presented to the Audi Product Safety Committee and the existing service action decision was re-evaluated. Based on the foregoing, Audi decided to conduct a voluntary recall to remedy affected vehicles.

Date of determination: December 01, 2021.

Audi is not aware of any crashes or injuries due to this issue. At the time of determination, Audi had identified 298 claims for this topic dating from March 12, 2020 – November 30, 2021.

Please contact me if you require any additional information or have any questions related to this information.

Sincerely,



Christopher T. Sandvig  
Director, Group Customer Protection  
Group Quality