



David J. Johnson
Director
Service Engineering Operations
Ford Customer Service Division

Ford Motor Company
P. O. Box 1904
Dearborn, Michigan 48121

February 17, 2022

TO: All U.S. Ford and Lincoln Dealers

**SUBJECT: NEW VEHICLE DEMONSTRATION / DELIVERY HOLD – Advance Notice
Safety Recall 22S06**
Certain 2015-2017 Model Year Mustang Vehicles
Luggage Compartment Lid Wiring Inspection and Rear View Camera Improper
Function

REF: TECHNICAL SERVICE BULLETIN 19-2273
Dated September 5, 2019

AFFECTED VEHICLES

Vehicle	Model Year	Assembly Plant	Build Dates
Mustang	2015-2017	Flat Rock	February 11, 2014 through October 2, 2017

Affected vehicles are identified in OASIS and FSA VIN Lists.

REASON FOR THIS SAFETY RECALL

In all of the affected vehicles, damage to the luggage compartment lid wiring harness in the area of the right side luggage compartment lid hinge may lead to intermittent rear view camera operation, loss of satellite radio reception and/or inoperable luggage compartment release.

In addition, in some of the affected 2015 model year vehicles, insufficient electrical conductivity within the Printed Circuit Board (PCB) internal to the camera may also lead to intermittent rear view camera operation.

A rear view camera that intermittently displays a blank or distorted image can reduce the driver's view of what is behind the vehicle increasing the risk of a crash.

SERVICE ACTION

DO NOT DEMONSTRATE OR DELIVER any new in-stock vehicles involved in this safety recall. A complete Dealer Bulletin is expected to be provided to dealers early in 2nd quarter of 2022 when it is anticipated that parts ordering information and repair instructions will be available to support this safety recall.

IMPORTANT: Dealers should open a Repair Order (RO) only when a full dealer bulletin is published. Opening an RO against an Awareness or Advance Notice will result in warranty rejections against a recall.

CUSTOMER NOTIFICATION

Owners of record will be notified via first-class mail after repair instructions and parts ordering information have been provided to dealers.

PLEASE NOTE:

Federal law requires dealers to complete this recall service before a new vehicle is delivered to the buyer or lessee. Violation of this requirement by a dealer could result in a civil penalty of up to \$21,000 per vehicle. Correct all vehicles in your new vehicle inventory prior to delivery.

QUESTIONS & ASSISTANCE

For questions and assistance, contact the Special Service Support Center (SSSC) via the SSSC Web Contact Site. The SSSC Web Contact Site can be accessed through the Professional Technician System (PTS) website using the SSSC link listed at the bottom of the OASIS VIN report screen or listed under the SSSC tab.

Sincerely,

A handwritten signature in black ink that reads "D. Johnson". The signature is written in a cursive style with a large, stylized initial "D".

David J. Johnson