

Part 573 Safety Recall Report

22V-090

Manufacturer Name : Lucid Motors, Inc.**Submission Date :** FEB 16, 2022**NHTSA Recall No. :** 22V-090**Manufacturer Recall No. :** N01**Manufacturer Information :**

Manufacturer Name : Lucid Motors, Inc.

Address : 7373 Gateway Blvd.

Newark CA 94560

Company phone : 648-3553

Population :

Number of potentially involved : 188

Estimated percentage with defect : 1 %

Vehicle Information :

Vehicle 1 : 2022-2022 Lucid Motors, Inc. Air (All grades)

Vehicle Type : LIGHT VEHICLES

Body Style : 4-DOOR

Power Train : NR

Descriptive Information : Lucid was notified by its supplier, Thyssenkrupp Bilstein ("Bilstein" or "Supplier") of the potentially affected parts, the front damper assemblies. The Supplier certified that as of January 10, 2022, only conforming parts were supplied to Lucid. Lucid implemented a production countermeasure that included quarantining all incoming parts from the Supplier for inspection, inspecting all parts installed on vehicles, and replacing any affected parts. Potentially affected parts are installed on 188 vehicles built and delivered to customers during the period from October 22, 2021, to January 9, 2022. Lucid has inspected and verified parts are conforming on all other vehicles produced during this period. Vehicles produced after this date range are not affected as they were produced after the production countermeasure was implemented.

Production Dates : OCT 22, 2021 - JAN 09, 2022

VIN Range 1 : Begin : 50EA1DCA6NA001017 End : 50EA1DAA4NA003397 Not sequential**Description of Defect :**

Description of the Defect : The snap ring below the front damper lower spring seat may have been installed incorrectly by the Supplier which may result in snap ring failure, causing sudden loss of ride height, damping force, and possible damage to the front brake line hoses.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : Possible loss of vehicle control and possible diminished braking authority, leading to increased likelihood of an accident.

Description of the Cause : The cause was an incorrect build and inspection during the Supplier's

manufacturing process. The Supplier reported that it may have installed some spring seat snap rings upside down, which may result in the snap ring failing and loss of spring seat retention.

Identification of Any Warning that can Occur : The driver would not receive a warning prior to a front damper snap ring failure. If the failure caused damage to the electrical connections to the damper solenoids, the driver would receive a warning message stating "Suspension Control Fault. Contact Service Center." If the failure resulted in a brake hose leak, the driver would not receive any immediate warning. If the brake fluid level fell below 81.9% of the minimum recommended reservoir brake fluid volume, the driver would receive a warning message stating "Brake Fluid Level Low. Refill Required, Contact Service Center," with an accompanying audible warning.

Involved Components :

Component Name 1 : Thyssenkrupp Bilstein

Component Description : Front Left Damper Spring Assembly

Component Part Number : P11-SDFSL1-01/-02

Component Name 2 : Thyssenkrupp Bilstein

Component Description : Front Right Damper Spring Assembly

Component Part Number : P11-SDFSR1-01/-02

Supplier Identification :

Component Manufacturer

Name : Thyssenkrupp Bilstein of America

Address : 8685 Bilstein Boulevard
Hamilton Ohio 45015

Country : United States

Chronology :

On Jan. 6, 2022, Supplier notified Lucid that a failure of Supplier's vision system allowed for incorrect installation of spring seats on front damper assemblies. On Jan. 7, Lucid began a containment protocol to quarantine potentially affected parts. By Jan. 10, Lucid quarantined all parts and began inspecting all

quarantined and already installed parts.

On Jan. 13, this matter was raised as a safety concern to Lucid's Product Safety Working Group (PSWG). The PSWG reviewed Supplier's fatigue testing of incorrectly installed parts, which showed such parts could fail at between 4% and 44% of design life. Lucid began analysis of the impact of a failure on vehicle controllability, the likelihood of a spring seat contacting the vehicle's braided brake lines, and the impact thereof.

On Feb. 2, Supplier communicated to Lucid that, "The durability life ... can happen at extremely low cycle counts. ... The Bilstein recommendation based on the information we have is that this condition needs to be assessed on vehicles."

On Feb. 3, the Lucid PSWG met to consider Supplier's recommendation and additional analysis by Lucid engineers. Analysis of vehicle controllability impacts indicated that the front corner experiencing a failure would drop downwards and the diagonally opposite corner would experience reduced loading, resulting in degraded steering and braking performance. Analysis of the failure on braided brake lines was ongoing. It was unknown whether the damper would contact the brake lines and if it did, whether the brake lines would be damaged. Assuming the braided brake lines were damaged and a leak occurred, over time, worst case loss of braking authority would be a reduction of 50%.

On Feb. 7, the PSWG briefed Lucid's Product Safety Executive Council (PSEC) on the issue. On Feb. 9, the PSEC concluded that, out of an abundance of caution, Lucid would conduct a recall of affected vehicles.

Description of Remedy :

Description of Remedy Program : All owners of subject vehicles will be notified by first class mail with instructions to bring their vehicles to Lucid studios or Lucid satellite service centers for inspection and replacement, if necessary, of front strut dampers AT NO COST to the customer. Technicians will perform a visible inspection of the left and right front damper assemblies for proper snap ring installation. If technicians identify an incorrect snap ring orientation on either damper assembly, Lucid will replace the affected damper assembly AT NO COST to the customer.

How Remedy Component Differs from Recalled Component : Supplier has replaced the detection system in its assembly process and certified to Lucid that all subsequent front damper assemblies have been produced with the snap ring installed in the correct orientation.

Identify How/When Recall Condition was Corrected in Production : On January 6, 2022, Supplier notified Lucid of the possibility of spring seats installed incorrectly. On January 7, Lucid implemented a containment protocol to quarantine all potentially affected parts received. By January 10, all received parts were quarantined at the Lucid factory, and Lucid began inspecting all quarantined parts and all parts installed on vehicles. Supplier certified that all parts supplied after January 10 were conforming. Lucid established a clean point for production on January 10, 2022.

Recall Schedule :

Description of Recall Schedule : NR

Planned Dealer Notification Date : FEB 16, 2022 - FEB 17, 2022

Planned Owner Notification Date : FEB 24, 2022 - FEB 25, 2022

* NR - Not Reported