News Channel Update | Vans Customer Service and Parts

TO: Mercedes-Benz Principals, General Managers, Sales Managers, Service Managers, Parts Managers	FROM: Anthony Washington, Department Manager, Regulations and Certifications
Re: Initial Recall Campaign Notification Model 907 (Sprinter) Model Years 2021 Replace Torsion Bar Linkage	DATE: March, 2022



IMPORTANT RECALL CAMPAIGN INFORMATION

Please see the attached documents related to the campaign listed above



News Channel Update | Vans Customer Service and Parts

Campaign No. : Campaign Desc. :			
2022030013p	PDGVADREH	Replace Torsion Bar Linkage	
This is to notify you of an initial Recall Campaign to replace the torsion bar linkage on approximately 2,153 MY21 Mercedes-Benz Sprinter vans. The recall campaign will be visible on the www.safercar.gov website and may generate questions from customers. All affected VINs will be flagged as " PENDING " in VMI and cannot be sold.			
Background			
Issue	Mercedes-Benz AG (MBAG), the manufacturer of Mercedes-Benz Sprinter vans, has determined that the torsion bar on certain Sprinter vehicles was not bolted to the torsion bar linkage by the component supplier during front axle assembly in accordance with design specifications. The shim on the torsion bar was incorrectly installed between the nut and the torsion bar, rather than between the ball stud and the torsion bar. Due to the incorrect assembly, the torsion bar may not meet operational strength requirements. Settling effects may occur between the journal flange and the torsion bar. These effects might reduce the bolt preload at the connection, which could increase fatigue on the journal and lead to a fatigue fracture of the journal, which could increase the risk of a crash.		
What We're Doing	MBUSA is conducting a voluntary recall. An authorized Mercedes-Benz dealer will correct the position of the shim and replace the torsion bar linkage.		
Parts	Parts are not yet available.		
		Vehicles Affected	
Vehicle Model Year(s)	Model Year 2021		
` '		Sprinter VS30, Platform 907	
Vehicle Model	Sprinter VS30, Platform 90	07	
• • • • • • • • • • • • • • • • • • • •	Sprinter VS30, Platform 90	07 Vehicle Populations	
• • • • • • • • • • • • • • • • • • • •	Sprinter VS30, Platform 90 2,153		
Vehicle Model Total Recall Dealer Inventory	2,153 24	Vehicle Populations	
Vehicle Model Total Recall Dealer Inventory	2,153 24 is <u>a violation of Federal Law</u> f		
Total Recall Dealer Inventory Given this notice, it	2,153 24 is <u>a violation of Federal Law</u> f covered by this noti	Vehicle Populations for a dealer to sell or lease any <u>new Sprinter vehicles in dealer inventory</u>	
Total Recall Dealer Inventory Given this notice, it	2,153 24 is <u>a violation of Federal Law for the covered by this notion</u> and demonstrator vehicles may be is notice, it is a violation of Federal Law for the covered by this notice.	Vehicle Populations For a dealer to sell or lease any <u>new</u> Sprinter vehicles in dealer inventory fication until the vehicle has been repaired.	
Total Recall Dealer Inventory Given this notice, it	2,153 24 is <u>a violation of Federal Law for a violation of Fed</u>	Vehicle Populations For a dealer to sell or lease any <u>new Sprinter vehicles in dealer inventory</u> fication until the vehicle has been repaired. If y continue to be driven, but must not be retailed until repaired. If y continue to be driven, but must not be retailed until repaired. If y continue to be driven, but must not be retailed until repaired.	

AOMs – This recall may generate questions from your dealers. Please forward this

This recall may affect vehicles in your fleet. Please contact your respective MBUSA

fleet representative for further information and next steps. For repairs, please



AOMS/SOMS

Rental Fleet Partners

notice to your dealers ASAP.

contact your preferred MBUSA dealer.

While we regret any inconvenience this may cause, we are determined to maintain a high level of vehicle quality and

customer satisfaction.