

GROUP	MODEL
Safety Recall Campaign	2014-2016MY Cadenza (VG)
NUMBER	DATE
SC232	May 2022

# SAFETY RECALL CAMPAIGN

# SUBJECT: WINDSHIELD INSPECTION & REATTACHMENT (SC232)

This bulletin provides information to inspect and, if necessary, reattach the front windshield glass on 2014-2016MY Cadenza (VG) vehicles produced from February 1, 2013 through January 7, 2016. Certain sections of the front windshield glass may not have sufficient primer resulting in reduced adhesion of the windshield glass to the vehicle body. Although the exact cause of this condition is unknown, it is believed to be due to a deviation in the application of primer to the front windshield glass, causing windshield separation. A separated windshield increases the risk of a crash and/or injury. Follow the procedure outlined in this publication to inspect the windshield for water leakage and, if necessary, remove and reattach the windshield. Before conducting the procedure, verify that the vehicle is included in the list of affected VINs.



# 

There is no charge to the vehicle owner for this repair. Under applicable law, you may not sell or otherwise deliver any affected vehicle until it has been repaired pursuant to the procedures set forth in this bulletin.

### 

To assure complete customer satisfaction, always remember to refer to WebDCS Warranty Coverage (validation) Inquiry Screen (Service  $\rightarrow$  Warranty Coverage  $\rightarrow$  Warranty Coverage Inquiry) for a list of any additional campaigns that may need to be performed on the vehicle before returning it to the customer.

A printed copy is for reference only; publication information can be updated at any time. Always refer to KGIS for the latest information. After logging in kdealer.com, the newest technical publications are listed in 'Service Releases' and has the latest service information that has been released.

# WINDSHIELD INSPECTION AND REATTACHMENT (SC232)

Inspection Procedure:

# **NOTICE**

BEFORE beginning, inspect the condition of the windshield glass when the vehicle arrives.

Take note of any damage observed, such as large rock chips, cracks, starburst cracks, etc. and document these on the R.O., and attach photos.

If windshield passes the leakage test (OK) but previous damage was noted upon arrival, then the customer is responsible for replacement.

 Before inspecting for leakage, remove the front pillar trim (A) on both sides of the vehicle by referring to the "Body (Interior and Exterior) → Interior → Interior Trim → Repair procedures" chapter in the applicable Shop Manual on KGIS.


# 


- When removing the front pillar trim, be careful <u>not</u> to break the two (2) keys (B) at the bottom.
- After removing the screw (C) and fastener (D) lift the front pillar trim in the direction of the headlining to remove it.

### 

Use a non-marring trim removal tool (such as Snap-on<sup>®</sup> Part Number PBN5 or equivalent) to avoid damaging trim pieces.

- 2a. Mix a solution of soap and water into a clean spray bottle as follows:
  - 500ml water
  - 20ml soap
- 2b. Spray a moderate amount of soapy water along the upper outside seal area of the windshield. Make sure the solution it is evenly spread across the entire surface and edges.







### WINDSHIELD INSPECTION AND REATTACHMENT (SC232)


 Inside the vehicle, inspect for water leakage along the top (E) and side pillar (F) areas of the windshield.



- 4. Using an air gun, blow air into these areas from inside the vehicle:
  - E: Between windshield glass and headliner.
  - F: Between windshield glass and front pillars.

# 

When using the air gun, be careful NOT to lift or damage the inner tint lining on the windshield.



- Immediately after blowing with the air gun, check for bubbles appearing on the outside of the windshield glass as shown.
  - If air bubbles are not present, no further action is required. Reinstall all removed parts in the reverse order of removal.
  - If air bubbles are present, proceed to the 'Repair Procedure' on page 4 to remove and reattach the front windshield glass.



# WINDSHIELD INSPECTION AND REATTACHMENT (SC232)

#### **Repair Procedure:**

### IMPORTANT

If the windshield glass is damaged before <u>or</u> after the leakage test, follow the guidelines below for replacement:

- 1. Windshield is damaged upon arrival or before test, and passes leakage test (i.e., no water leaks), customer is responsible for the replacement. Inform customer.
- 2. Windshield is damaged upon arrival or before test, and <u>fails</u> leakage test (i.e., water leaks are present), <u>Kia will pay</u> for the replacement glass.
- 3. Windshield fails leakage test (i.e., water leaks present), and is damaged during removal/reattaching (by dealer or subcontractor), <u>Kia will pay</u> for the replacement glass.

Note: If windshield requires replacement for reasons #2 or #3, open a Techline case online.


### 

It is highly recommended to sublet the vehicle to an automotive glass company to perform the removal and reattachment of the windshield glass, if the technician is not equipped or trained to perform the repair.

 Remove and reattach the windshield glass by referring to the "Body (Interior and Exterior) → Interior → Windshield Glass → Repair procedures" chapter in the applicable Shop Manual on KGIS.

### 

- Use a rotating wire removal tool during removal to reduce the possibility of damaging the glass.
- Be careful NOT to damage the windshield glass during removal. If the glass is damaged, it <u>cannot</u> be reused.
- Perform LDWS calibration by referring to the "Body Electrical System → Lane Departure Warning System (LDWS) → Description and Operation" in the applicable Shop Manual on KGIS. <u>Note:</u> <u>The LDWS/LKAS calibration must</u> <u>be performed by dealer only.</u>



# WINDSHIELD INSPECTION AND REATTACHMENT (SC232)

### AFFECTED VEHICLE RANGE:

Model	Production Date Range				
Cadenza (VG)	February 1, 2013 to January 7, 2016				

### **REQUIRED PART:**

Dart Nama	Part	Ot v		
Part Name	Old	New	Qty.	
Windshield Molding	86130 3R000	86130 3R000QQK	1	
A-Pillar Trim Fastener*	85849 3B000	85849 3B000QQK	2	

\*If damaged during inspection/reattachment please replace both fasteners.

Part Name	Part Number		$O^{+}$	Comments	
Pari Name	Old	New	Qty.	Comments	
Windshield Glass**	86111 3R800	86110 3R800QQK	1		
	86111 3R180	86110 3R820QQK	1	Refer to Mobis Catalog for the applicable windshield glass part number.	
	86111 3R820	00110 SK020QQK			
	86111 3R860	86110 3R860QQK	1		
	86111 3R230	50110 SK800QQK			
	86111 3R870	- 86110 3R870QQK	1		
	86111 3R531	00110 SK070QQK	Ι		

\*\*Windshield Glass part numbers should <u>only</u> be ordered with Techline approval. A VIN control will be active on these part numbers.

# WINDSHIELD INSPECTION AND REATTACHMENT (SC232)

### WARRANTY INFORMATION: N Code: N99 C Code: C99

Claim Type	Causal P/N	Qty.	Repair Description	Labor Op Code	Op Time	Replacement P/N	Qty.
			(SC232) Dealer performed Windshield Inspection	221051R0	0.3 M/H	 N/A	0
			(SC232) Dealer performed Windshield Inspection + Windshield Reattachment*	221051R3	2.2 M/H		
		(SC232) Dealer performed Windshield Inspection + Windshield Reattachment <sup>•</sup> + Calibration w/LDWS/LKAS <sup>••</sup>	221051R4	2.5 M/H	-		
			(SC232) Dealer performed Windshield Inspection + Install New Windshield*	221051R7	2.2 M/H	86110 3R800QQK <b>or</b> 86110 3R820QQK	
R 86111 3R150	0	(SC232) Dealer performed Windshield Inspection + Install New Windshield* + Calibration w/LDWS/LKAS**	221051R8	2.5 M/H	or 86110 3R860QQK or 86110 3R870QQK	1	
		(SC232) Dealer performed Windshield Inspection + <b>3<sup>rd</sup> Party</b> Windshield Reattachment	221051R1	0.3 M/H			
		(SC232) Dealer performed Windshield Inspection + <b>3<sup>rd</sup> Party</b> Windshield Reattachment + Dealer performed Calibration w/LDWS/LKAS**	221051R2	0.6 M/H	N/A	0	
			(SC232) Dealer performed Windshield Inspection + <b>3<sup>rd</sup> Party</b> Install New Windshield	221051R5	0.3 M/H	86110 3R800QQK <b>or</b> 86110 3R820QQK	
			(SC232) Dealer performed Windshield Inspection + <b>3<sup>rd</sup> Party</b> Install New Windshield + Dealer performed Calibration w/LDWS/LKAS**	221051R6	0.6 M/H	or 86110 3R860QQK or 86110 3R870QQK	1

\*Use this Labor Op Code <u>only</u> if windshield is removed and reattached/installed by dealer. Kia strongly recommends 3rd party windshield reattachment or installation procedure be performed by a reputable automotive glass company.

\*\*The LDWS/LKAS calibration must be performed by dealer only.

Refer to Warranty Bulletin 2022-14 for claim submission procedures.

### 

VIN inquiry data for this repair is provided for tracking purposes only. Kia retailers should reference SC232 when accessing the WebDCS system.