OMB Control No.: 2127-0004

Part 573 Safety Recall Report

Manufacturer Name :Tiny Idahomes LLCSubmission Date :SEP 27, 2022NHTSA Recall No. :22V-260Manufacturer Recall No. :NR

Manufacturer Information :

Manufacturer Name : Tiny Idahomes LLC Address : 1050 Cascade Rd #4 Emmett ID 83617 Company phone : 2084680576

Vehicle Information :

| Vehicle 1: | 2021-2022 Rugged Mountain Custom RV Travel Trailer |
|---------------------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| Vehicle Type : | TRAILERS |
| Body Style : | |
| Power Train : | NR |
| Descriptive Information : | Trailers manufactured from 8/01/2021 to 10/31/2021 that may have had a bad coupler installed as a result from a bin of tack welded (incomplete weld) CA-5400 couplers were mixed into other finished products in July 2021 at the Pacific Trailer Factory. These couplers were assembled and shipped to their customers between 8/6/2021-10/25/2021. All couplers shipped are identified with the tracking numbers called QC codes. All customers receiving the couplers from the suspect QC codes were contacted via email, provided a "Product Bulletin" (inspection document), and asked to inspect for defect. Results show actual percent defective to be less than 0.2%. |
| | AUG 01, 2021 - OCT 31, 2021 |
| VIN Range 1: | Begin : 4T9BE3023ME168231 End : 4T9BE3023ME168231 Not sequential |
| VIN Range 2: | Begin :4T9BK3220NE168209End :4T9BK3222NE168213Image: Not sequential |
| C C | Begin :4T9BK2025ME168217End :4T9BK2020ME168223Image: Not sequential |
| VIN Range 4: | Begin :4T9BK3229NE168225End :4T9BK3229NE168226Image: Not sequential |

Description of Defect :

| Description of the Defect : | The bottom portion of the coupler that we install on our trailers may not have been completely welded. |
|----------------------------------|-----------------------------------------------------------------------------------------------------------------------------------|
| FMVSS 1 : | NR |
| FMVSS 2 : | NR |
| Description of the Safety Risk : | The coupler welds could fail and may cause trailer/tow vehicle separation and an increased risk of either crash, injury, or fire. |
| Description of the Cause : | Trailers manufactured from $8/01/2021$ to $10/31/2021$ that may have had a |
| | |

The information contained in this report was submitted pursuant to 49 CFR §573



22V-260

Population :

| Number of potentially involved : | 15 |
|------------------------------------|-----|
| Estimated percentage with defect : | 1 % |

Part 573 Safety Recall Report

Page 2

bad coupler installed as a result from a bin of tack welded (incomplete weld) CA-5400 couplers were mixed into other finished products in July 2021 at the Pacific Trailer Factory. These couplers were assembled and shipped to their customers between 8/6/2021- 10/25/2021. All couplers shipped are identified with the tracking numbers called QC codes. All customers receiving the couplers from the suspect QC codes were contacted via email, provided a "Product Bulletin" (inspection document), and asked to inspect for defect. Results show actual percent defective to be less than 0.2%.

Identification of Any Warning that can Occur : An easy visual inspection will identify the problem.

Involved Components :

Component Name 1 :RAM CA-5400 COUPLERSComponent Description :2 5/16" A FRAMEComponent Part Number :RAM CA-5400-0, CA-5400-B

Supplier Identification :

Component Manufacturer

Name :Pacific Trailer Products, IncAddress :19120 SE 34th St.
Suite 105 Vancouver Washington 98683Country :United States

Chronology :

The explanation is somebody accidently moved a bin of tack welded (to-be-welded) couplers into the finished products stocking. It then contaminated a few crates that were packed around the same time in July 2021. For an unrelated reason, the factory was asked to inspect all couplers in stock in the factory in late August. Some of the couplers had a slightly short weld (nonfunctional and completely different than the recall issue) but in the abundance of caution, the factory sorted all couplers in stock. There were about 6,000 packaged couplers in the factory. They unpacked all of them, inspected all of them, and did enhancement welding if needed. The factory didn't see any unwelded couplers among all in stock. On October 13th the factory learned about the unwelded coupler defect, the factory was notified immediately and again they inspected all in stock (about 8,000 pcs in stock). This time the factory was looking for any unwelded ones and they didn't find any from inventory. Starting November 1, 2021, all customers were notified of the possible defect and were asked to inspect using an inspection document provided by Pacific Trailer Products. Tiny Idahomes LLC. was notified March 15th,

The information contained in this report was submitted pursuant to 49 CFR §573

2022 that 15 of our trailers may have possibly been affected by the recall.

Description of Remedy :

| Description of Remedy Program : | All customers were notified in writing in November 2021 and asked to sort for the defect using an inspection document provided by Pacific Trailer Products. All costs will or were reimbursed for this issue. NHTSA recall letters and process will occur in February 2022. Tiny Idahomes customers that find a defect may contact Nathan Schauer at Dexter by email to nathan.schauer@dextergroup.com. He will we handle all repairs or replacements for any Tiny Idahomes customer that has a coupler defect. |
|---------------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| 5 1 | The remedy coupler is fully welded on the bottom side. The recalled coupler is not fully welded on the bottom side. |
| | The unwelded coupler crate was mixed in production in July 2021, after extensive sorting and inspection starting August 2021, no incomplete welded couplers were found. An in-process inspection was added to inspect for the condition immediately after the condition was identified in October 2021. |

Recall Schedule :

| Description of Recall Schedule : | Letters will be mailed to potentially affected Tiny Home RV owners in |
|------------------------------------|-----------------------------------------------------------------------|
| | September 2022. There are no dealers that need notification. |
| Planned Dealer Notification Date : | NR - NR |
| Planned Owner Notification Date : | SEP 27, 2022 - SEP 30, 2022 |

* NR - Not Reported