



Recall 22V-308

Claim Preparation & Repair Instructions

Please complete a warranty claim pre-authorization request using the following codes & labor times:

LABOR:

Operation Code:	910029
Fault Code:	Recall
Labor Time:	.3 hrs. inspection/soap test .2 hrs. R & R per quick disconnect (If necessary) .3 hrs. for drop test
Administrative Allowance:	.1 hrs.


PARTS: **#220061 – Quick Disconnect**

PRE-AUTH REQUIREMENT: Must file pre-authorization with recall flat rate code. Photo of cracked quick disconnect required. No part returns.

Recall 22V-308

REPAIR INSTRUCTIONS:

1. Perform a visual inspection of **all** quick disconnect fittings on the unit. There may be as many as **three** quick disconnects depending on the floorplan. Inspect the quick disconnect carefully to identify any cracks on the “fixed ring” end of the quick disconnect fitting. *See example below*



2. Spray each fitting with a soapy water mixture to test for leaks, concentrating on the fixed ring end of the fitting. If a crack is identified, replace the quick disconnect fitting.
3. Once failed quick disconnect(s) are replaced, perform a drop test to ensure there are no leaks in the LP system.

Promptly submit all pre-authorizations/claims through our Dealer Portal. If you have any questions or need assistance, please call our Technical Service Team at 888-825-2820 or email recall@granddesignrv.com.

11333 County Road 2, Middlebury, IN 46540
Phone: 574-825-8000, Fax: 574-825-9700
granddesignrv.com