



U.S. Department of Transportation
**National Highway Traffic Safety
Administration**

May 11, 2022

Mr. Greg Gunther
Department Manager VCA
Mercedes-Benz USA, LLC
13470 International Parkway
Jacksonville, FL 32218

1200 New Jersey Avenue SE
Washington, DC 20590

NEF-107ES
22V-315

Subject: Brake Booster Corrosion May Impair Braking

Dear Mr. Gunther:

This letter serves to acknowledge Mercedes-Benz USA, LLC's notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall which will be conducted pursuant to Federal law for the product(s) listed below. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

Makes/Models/Model Years:

MERCEDES BENZ/AMG R63/2007
MERCEDES BENZ/GL320/2007-2009
MERCEDES BENZ/GL350/2010-2012
MERCEDES BENZ/GL450/2007-2012
MERCEDES BENZ/GL550/2008-2012
MERCEDES BENZ/ML320/2007-2009
MERCEDES BENZ/ML350/2006-2011
MERCEDES BENZ/ML450/2010-2011
MERCEDES BENZ/ML500/2006-2007
MERCEDES BENZ/ML550/2008-2011
MERCEDES BENZ/R320/2007-2009
MERCEDES BENZ/R500/2006-2007
MERCEDES-BENZ/AMG ML63/2007-2011
MERCEDES-BENZ/R350/2006-2012
MERCEDES-BENZ/R550/2008

Mfr's Report Date: May 9, 2022

NHTSA Campaign Number: 22V-315

Components:

SERVICE BRAKES, HYDRAULIC:POWER ASSIST:VACUUM

Potential Number of Units Affected: 292,287

Problem Description:

Mercedes-Benz USA, LLC (MBUSA) is recalling certain 2006-2012 ML-Class, GL-Class, and R-Class vehicles. Please refer to MBUSA's recall report for specific vehicle model details. Moisture may accumulate and cause corrosion in the brake booster housing unit, which can result in reduced brake performance or brake failure.

Consequence:

Reduced brake performance or brake failure can increase the risk of a crash.

Remedy:

Owners are advised not to drive their vehicles until the remedy has been performed. Dealers will remove the rubber sleeve, inspect the brake booster, and as necessary, replace the brake booster. All repairs will be performed free of charge. Owner notification letters are expected to be mailed May 27, 2022. Owners may contact MBUSA customer service at 1-800-367-6372.

Notes:

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to www.nhtsa.gov.

Please be reminded of the following requirements:

You are required to submit a draft owner notification letter to this office no less than five days prior to mailing it to the customers. Also, copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

As stated in Part 573.7, submission of the first of eight consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on, or before, 30 days after the close of the calendar quarter.

Mercedes-Benz USA, LLC's contact for this recall will be Emily C. Smith who may be reached by email at emily.c.smith@dot.gov. We look forward to working with you.

Sincerely,



Alex Ansley
Chief, Recall Management Division
Office of Defects Investigation
Enforcement