

August 8, 2022

Ms. Marie Claude Gagnon Prod. Cert.& Spec. Specialist Corp. Micro Bird, Inc. 3000 Girardin Drummondville 001

Subject: Inside Panels Insufficiently Attached/FMVSS 221

Dear Ms. Gagnon:

This letter serves to acknowledge Corp. Micro Bird, Inc.'s notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall which will be conducted pursuant to Federal law for the product(s) listed below. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

Makes/Models/Model Years:

MICRO BIRD/G5/2021-2022 MICRO BIRD/MB II/2021-2022 MICRO BIRD/T-SERIES/2021-2022

Mfr's Report Date: July 27, 2022

NHTSA Campaign Number: 22V-540

Components: STRUCTURE:BODY

Potential Number of Units Affected: 127

Problem Description:

Corp. Micro Bird, Inc. (Micro Bird) is recalling certain 2021-2022 G5, MBII, and T-Series school buses. The inside panels under the windows may have been insufficiently attached. As such, these vehicles fail to comply with the requirements of the Federal Motor Vehicle Safety Standard number 221, "School Bus Body Joint Strength."

Consequence:

Insufficiently attached panels may separate during a crash, increasing the risk of an injury.

Remedy:

Dealers will provide parts and instructions on how to correct the defect, free of charge. The manufacturer has not yet provided a schedule for recall notification. Owners may contact Micro Bird's customer service at 1-819-477-2012. Micro Bird's number for this recall is 22-094-PUS.

Notes:

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to www.nhtsa.gov.

Image: Constraint of the second state of the second st

1200 New Jersey Avenue SE Washington, DC 20590

> NEF-107MR 22V-540

Please ensure the following requirements are met:

Your company must supply the estimated date(s) for which it will notify dealers and/or distributors regarding this safety recall. If your company subsequently becomes aware that either the beginning or the completion dates reported to the agency for any of the notifications will be delayed by more than two weeks, your company shall promptly advise the agency of the delay and the reasons therefor, and furnish a revised estimate. If your company does not have dealers or distributors, please state so in the 573 (49 CFR 573.6 (c)(8)(ii)).

AMENDED 573 REQUIRED.

Your company must supply the estimated date(s) for which it will notify owners regarding this safety recall. Please be reminded that all owners must be notified of the safety risk associated with this filing within 60 days of the 573 being submitted. If the remedy is not available at that time, mail the interim notice, following it with a second notice once the remedy becomes available. If your company subsequently becomes aware that either the beginning or the completion dates reported to the agency for any of the notifications will be delayed by more than two weeks, your company shall promptly advise the agency of the delay and the reasons therefor, and furnish a revised estimate. If there are no owners involved in this recall, please state so in the 573 (49 CFR 573.6 (c)(8)(ii)).

AMENDED 573 REQUIRED.

Your company's program shall include a plan for reimbursing an owner or purchaser who incurred costs to obtain a remedy for the problem addressed by the recall within a reasonable time in advance of your company's notification of owners, purchasers and dealers, in accordance with § 573.13. Your company's plan may incorporate by reference a general reimbursement plan it previously submitted to NHTSA, together with information specific to the individual recall. Information required by § 573.13 that is not in a general reimbursement plan shall be submitted in your company's report to NHTSA. If your company submits one or more general reimbursement plans, your company shall update each plan every two years (§ 573.13). If the vehicles are new and would be covered under the manufacturer's warranty program, please state that in the remedy section of your filing.

AMENDED 573 REQUIRED.

A description of the manufacturer's program for remedying the defect or noncompliance (49 CFR 573.6 (c)(8)(i)).

AMENDED 573 REQUIRED.

Please be reminded of the following requirements:

You are required to submit a draft owner notification letter to this office no less than five days prior to mailing it to the customers. Also, copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

Under 49 U.S.C. § 30112(a), it is illegal for anyone, including a manufacturer, distributor, dealer, or retailer to sell an item of equipment or vehicle that fails to comply with all applicable Federal motor vehicle safety standards.

As stated in Part 573.7, submission of the first of eight consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on, or before, 30 days after the close of the calendar quarter.



Corp. Micro Bird, Inc.'s contact for this recall will be Michelle Rice who may be reached by email at michelle.rice@dot.gov. We look forward to working with you.

Sincerely,

Alare Anoly

Alex Ansley Chief, Recall Management Division Office of Defects Investigation Enforcement

