OMB Control No.: 2127-0004

Part 573 Safety Recall Report

22V-634

Manufacturer Name: Daimler Trucks North America, LLC

NHTSA Recall No.: 22V-634

Manufacturer Recall No.: FL843



Manufacturer Information:

Manufacturer Name: Daimler Trucks North America, LLC

Address: 4747 N. Channel Avenue

Portland OR 97217-3849

Company phone: 800-745-8000

Population:

Number of potentially involved : 7,601Estimated percentage with defect : 100%

Vehicle Information:

Vehicle 1: 2011-2021 Thomas Built Buses Saf-T-Liner HDX

Vehicle Type: BUSES, MEDIUM & HEAVY VEHICLES

Body Style : Power Train : NR

Descriptive Information: Certain Saf-T-Liner HDX School Buses built with a wall mounted barrier at the 1st

rafter on the passenger side manufactured within the above dates. All HDX school buses built with wall mounted barrier at the first rafter on passenger side after

-10/21/2009, when FMVSS 571.222 changed school bus barrier

requirements.

Production Dates: OCT 21, 2009 - DEC 16, 2019

VIN Range 1 : Begin : NR End : NR Not sequential

Description of Defect:

Description of the Defect: On the affected school buses, the forward barrier was determined not to meet

the requirements of Federal Motor Vehicle Safety Standard (FMVSS) 222, S5.2.3: Barrier performance forward. When 5/8 inch of aesthetic foam was added to seat barriers for styling purposes, FMVSS 222 changed the conditions of the seat barrier test with which the prior seat complied. The amount of energy absorbed by the seat barrier under the revised test did not meet the specification standard 5.2 of 452 joules / person within the first 356 mm of deflection.

FMVSS 1: NR FMVSS 2: NR

Description of the Safety Risk: In the affected population, the forward barrier was determined not to meet

the requirements of S5.2.3 of Federal Motor Vehicle Safety Standard (FMVSS) 222. In the event of a crash, if the occupant contacts the barrier they may experience higher impact than intended, which may result in injury to the occupant. There have been no reported injuries or accidents related to this

The information contained in this report was submitted pursuant to 49 CFR §573

defect.

Description of the Cause: NR

Identification of Any Warning NR

that can Occur:

Involved Components:

Component Name 1: Wall Mounted Barrier

Component Description: Wall Mount Barrier High Back Foam

Component Part Number: 159527

Component Name 2: Wall Mounted Barrier

Component Description: Wall Mount Barrier High Back Foam

Component Part Number: 159528

Component Name 3: Wall Mounted Barrier

Component Description: Wall Mount Barrier High Back Foam

Component Part Number: 159529

Supplier Identification:

Component Manufacturer

Name: Thomas Built Bus

Address: NR

NR

Country: United States

Chronology:

October 30, 2019, NHTSA notified DTNA of potential noncompliance with FMVSS 222, S5.2.3: Barrier performance forward relating to certain barriers equipped on the Saf-T-Liner HDX School Buses. Based on the information provided by NHTSA's testing, DTNA began to investigate the issue to evaluate the potential noncompliance and to determine the scope and establish the potentially affected population. November 2019

DTNA requested a visit to NHTSA's test facility to review findings. On December 11, 2019, DTNA visited the NHTSA test facility to review test procedure and findings with NHTSA. On December 17, 2019, DTNA determined that a non-compliance exists on certain vehicles built with the suspect barrier mounted at the 1st rafter on the passenger side. The issue was that a purely aesthetic piece of foam changed the technicalities of how structural testing is performed, resulting in barrier with the foam not passing the amended FMVSS 222, S5.2.3 requirement. On January 16, 2020, DTNA submitted a petition seeking exemption from the notification and remedy requirements of 49 U.S.C. 30118 (d) and 49 C.F.R. Part 556 on the basis that a noncompliance with FMVSS 222 is inconsequential as it relates to motor vehicle safety. On or about August 4, 2022, DTNA received notice from NHTSA that petition was not approved. On August 10 2022, DTNA filed the amended DIR to begin the process of recalling those Barriers upon receiving the notification of NHTSA's determination regarding the petition. I mid-August 2022, DTNA refiled this recall at the request of the agency. It will supersede 19V899.

Description of Remedy:

Description of Remedy Program: Daimler Trucks North America is currently working on a plan for repairs.

Repairs will be performed by Daimler Trucks North America authorized service facilities. Details of the reimbursement plan will be included in the

owner's notification letter.

How Remedy Component Differs NR

from Recalled Component:

Identify How/When Recall Condition NR

was Corrected in Production:

Recall Schedule:

Description of Recall Schedule: Customer notification will be made by first class mail using Daimler

Trucks North America records to determine the

customers affected.

Planned Dealer Notification Date : OCT 04, 2022 - OCT 04, 2022 Planned Owner Notification Date : OCT 04, 2022 - OCT 04, 2022

* NR - Not Reported