OMB Control No.: 2127-0004

## Part 573 Safety Recall Report

### 22V-744

Manufacturer Name: Rivian Automotive, LLC

NHTSA Recall No.: 22V-744

Manufacturer Recall No.: FSAM 997



#### **Manufacturer Information:**

Manufacturer Name: Rivian Automotive, LLC

Address: 13250 North Haggerty Road

PLYMOUTH MI 48170

Company phone: 999

#### **Population:**

Number of potentially involved: 12,212 Estimated percentage with defect: 1 %

#### **Vehicle Information:**

Vehicle 1: 2022-2022 Rivian R1T

Vehicle Type: LIGHT VEHICLES Body Style: PICKUP TRUCK

Power Train: NR

Descriptive Information: The subject population is comprised of MY 2022 R1T and R1S vehicles built during a

13-month period, and, a subset of EDVs produced between December 10, 2021 and September 27, 2022, in which records cannot confirm that the front upper control arm and the steering knuckle retention fastener for each front wheel was properly

torqued.

Production Dates: AUG 23, 2021 - SEP 24, 2022

Vehicle 2: 2022-2022 Rivian R1S

Vehicle Type: LIGHT VEHICLES

Body Style: SUV Power Train: NR

Descriptive Information: The subject population is comprised of MY 2022 R1T and R1S vehicles built during a

13-month period, and, a subset of EDVs produced between December 10, 2021 and September 27, 2022, in which records cannot confirm that the front upper control arm and the steering knuckle retention fastener for each front wheel was properly

torqued.

Production Dates: SEP 28, 2021 - SEP 23, 2022

Vehicle 3: 2022-2022 Rivian EDV

Vehicle Type: LIGHT VEHICLES

Body Style : VAN Power Train : NR

Descriptive Information: The subject population is comprised of MY 2022 R1T and R1S vehicles built during a

13-month period, and, a subset of EDVs produced between December 10, 2021 and September 27, 2022, in which records cannot confirm that the front upper control arm and the steering knuckle retention fastener for each front wheel was properly

torqued.

Production Dates: DEC 10, 2021 - SEP 27, 2022

#### **Description of Defect:**

Description of the Defect: The nut connecting the front upper control arm and steering knuckle may not

have been sufficiently torqued.

FMVSS 1: NR FMVSS 2: NR

Description of the Safety Risk: An improperly torqued steering knuckle fastener could cause excessive wheel

camber, or, in rare instances, a separation, affecting the driver's ability to

control the vehicle, and increasing the risk of a crash.

Description of the Cause: NR

Identification of Any Warning Customers with affected VINs may experience excessive noise, vibration, and

that can Occur: harshness from the front suspension and/or a change in steering performance

or feel.

#### **Involved Components:**

Component Name 1: NR
Component Description: NR

Component Part Number: NR

#### **Supplier Identification:**

#### **Component Manufacturer**

Name: NR

Address: NR

NR

Country: NR

#### **Chronology:**

On August 13, 2022, Rivian identified a vehicle where the upper control arm had separated from the steering knuckle. The incident was reviewed by engineering and an investigation into root cause and scope was initiated.

On September 24, 2022, Rivian became aware of two vehicles where the steering knuckle had become loose or separated.

As of September 28, 2022, Rivian had become aware of six reports potentially related to this issue that had accumulated over the production of R1T, R1S, and EDV vehicles (a rate of 0.037%).

On September 29, 2022, Rivian completed its investigation, confirming the suspected root cause, risk assessment, remedy, and affected population.

On September 30, 2022, Rivian determined that a safety-related defect exists related to this matter.

#### **Description of Remedy:**

Description of Remedy Program : Rivian will inspect and, as necessary, properly secure the steering knuckle

fasteners in the affected vehicles. In the event that components require

replacement, Rivian will replace components, as necessary.

Rivian has a policy and practice of reimbursing owners who have paid for a repair that subsequently becomes the subject of a field action. To ensure consistency, Rivian, as part of the owner letter, will request that customers send the original receipt and/or other adequate proof of payment to the

company for confirmation of the expense.

How Remedy Component Differs The remedy components will be a sufficiently torqued fastener.

from Recalled Component :

Identify How/When Recall Condition NR

was Corrected in Production:

#### **Recall Schedule:**

Description of Recall Schedule: Rivian will begin notifying affected customers as soon as possible

through emails and text messages. We will mail notifications on or before

November 24th, 2022.

As a direct-to consumer manufacturer, Rivian owns and operates all of the Company's sales and service operations. As all "dealers" are Rivian owned entities, notification will be through internal means to our

# **Part 573 Safety Recall Report**

22V-744

Page 4

licensed store and service operations addressing this recall on or before

the date set forth in this response.

Planned Dealer Notification Date : NOV 24, 2022 - NOV 24, 2022 Planned Owner Notification Date : NOV 24, 2022 - NOV 24, 2022

\* NR - Not Reported