OMB Control No.: 2127-0004

Part 573 Safety Recall Report

23V-406

Manufacturer Name: Tiffin Motorhomes, Inc.

NHTSA Recall No.: 23V-406

Manufacturer Recall No.: TIF-131



Manufacturer Information:

Manufacturer Name: Tiffin Motorhomes, Inc.

Address: 105 2nd Street NW

PO Box 596 Red Bay AL 35582

Company phone: 999

Population:

Number of potentially involved : 450 Estimated percentage with defect : 50 %

Vehicle Information:

Vehicle 1: 2022-2023 TIFFIN PHAETON

Vehicle Type: BUSES, MEDIUM & HEAVY VEHICLES

Body Style : OTHER Power Train : DIESEL

Descriptive Information: PowerGlide chassis controller, IFM brand. In review of manufacturing records, Tiffin

Motorhomes started using an additional brand of chassis controller, IFM brand, due to supply chain shortages on 05/02/2022 so the population will include all Phaetons, Allegro Buses and Zephyrs built on PowerGlide Chassis between 05/02/2022 and 05/22/2023. Tiffin Motorhomes has identified 450 chassis located in the United States that could contain this controller. All PowerGlide chassis built during this period are involved, the chassis controller would need to be inspected to confirm if it

is the recalled component or not.

Production Dates: MAY 02, 2022 - MAY 22, 2023

VIN Range 1: Begin: 5VBBA27A0PA122871 End: 5VBZA89AXPA123184 ✓ Not sequential

Vehicle 2: 2022-2023 TIFFIN ALLEGRO BUS Vehicle Type: BUSES, MEDIUM & HEAVY VEHICLES

Body Style : OTHER Power Train : DIESEL

Descriptive Information: PowerGlide chassis controller, IFM brand. In review of manufacturing records, Tiffin

Motorhomes started using an additional brand of chassis controller, IFM brand, due to supply chain shortages on 05/02/2022 so the population will include all Phaetons, Allegro Buses and Zephyrs built on PowerGlide Chassis between 05/02/2022 and 05/22/2023. Tiffin Motorhomes has identified 450 chassis located in the United States that could contain this controller. All PowerGlide chassis built during this period are involved, the chassis controller would need to be inspected to confirm if it

is the recalled component or not.

Production Dates: MAY 02, 2022 - MAY 22, 2023

VIN Range 1: Begin: 5VBBA27A0PA122871 End: 5VBZA89AXPA123184 ✓ Not sequential

Vehicle 3: 2022-2023 TIFFIN ZEPHYR

Vehicle Type: BUSES, MEDIUM & HEAVY VEHICLES

Body Style : OTHER Power Train : DIESEL

Descriptive Information: PowerGlide chassis controller, IFM brand. In review of manufacturing records, Tiffin

Motorhomes started using an additional brand of chassis controller, IFM brand, due to supply chain shortages on 05/02/2022 so the population will include all Phaetons, Allegro Buses and Zephyrs built on PowerGlide Chassis between 05/02/2022 and 05/22/2023. Tiffin Motorhomes has identified 450 chassis located in the United States that could contain this controller. All PowerGlide chassis built during this period are involved, the chassis controller would need to be inspected to confirm if it

is the recalled component or not.

Production Dates: MAY 02, 2022 - MAY 22, 2023

Description of Defect:

Description of the Defect: PowerGlide chassis controller, IFM brand. In the event of an a/c compressor

failure, the current draw spike from the compressor will blow the fuse

protecting the circuit. The fuse also supplies the ignition power circuit causing

a loss of ignition power to the chassis when the fuse is blown.

FMVSS 1: NR FMVSS 2: NR

Description of the Safety Risk: Loss of all power to chassis, engine stoppage, which could lead to an

increased risk of crash.

Description of the Cause: Lack of circuit protection in the event of an a/c compressor failure.

Identification of Any Warning None

that can Occur:

Involved Components:

Component Name 1: MODULE MULTI PLEX IFM

Component Description: CHASSIS CONTROL MODULE

Component Part Number: CR0033

Supplier Identification:

Component Manufacturer

Name: IFM EFFECTOR, INC Address: PO BOX 8538-307

PHILADELPHIA Pennsylvania 19171-0307

Country: United States

Chronology:

04/30/2023 there was a field complaint reported to the chassis service department about a of loss of chassis power. Tiffin field service technicians and chassis engineering began to investigate and determined the dash A/C compressor had failed and that the dash A/C compressor and the ignition switch power were wired on the same circuit block. 5/30/2023 Issue was brought before the safety committee, and they voted to issue a recall.

Description of Remedy:

Description of Remedy Program : All field units involved in the recall will be inspected to verify which brand

of chassis controller is installed. If a chassis has the IFM controller, a harness with an inline fuse will be installed into the wiring harness for the A/C compressor so that in the event of a failure of the A/C compressor, the inline fuse will blow and the power to the ignition switch will not be lost. Letters will be mailed to all owners and dealers with involved units

notifying them of a recall.

The repair will be completed at no charge to the owner. There is no plan for reimbursement because any failures would have been covered under

Tiffin's PowerGlide chassis warranty.

How Remedy Component Differs In the field, a jumper harness with the inline fuse will be installed at the from Recalled Component: chassis controller. In production, a programming change will be applied to

separate the circuit for the A/C compressor and the ignition switch.

separate the electric for the We compressor and the ignition switch.

Identify How/When Recall Condition As of 05/22/2023, an engineering change notification was issued to was Corrected in Production : provide a controller programming change to separate the A/C compressor

from the ignition power supply.

Recall Schedule:

Description of Recall Schedule: Tiffn Motorhomes will mail letters to customers and dealers that are in

possession of the involved coaches explaining the issue and asking them to take the motorhome to a dealer or service center for inspection and

replacement, if needed, at no cost to the owner.

Planned Dealer Notification Date : $AUG\ 04,\ 2023$ - $AUG\ 04,\ 2023$

Planned Owner Notification Date: AUG 04, 2023 - AUG 04, 2023

Part 573 Safety Recall Report	23V-406	Page 4
* NR - Not Reported		
The information contained in this report was submitted pursuant to 49 CFR §573		