#### OMB Control No.: 2127-0004

# Part 573 Safety Recall Report

## 23V-438

**Manufacturer Name:** Altec Industries, Inc.

NHTSA Recall No.: 23V-438

Manufacturer Recall No.: CSN 3091



#### **Manufacturer Information:**

Manufacturer Name: Altec Industries, Inc.

Address: 210 Inverness Center Drive

Birmingham AL 35242

Company phone: 205 991 7733

## **Population:**

Number of potentially involved: 18 Estimated percentage with defect: 100 %

## **Vehicle Information:**

Vehicle 1: 2019-2022 Altec AT335

Vehicle Type :
Body Style :
Power Train : NR

Descriptive Information: The recall population was determined from a review of production records.

Production Dates: APR 05, 2019 - DEC 28, 2022

## **Description of Defect:**

Description of the Defect: An inverter-powered outlet might have been installed at the aerial boomtip

without GFCI protection.

FMVSS 1: NR FMVSS 2: NR

Description of the Safety Risk: If the 110V outlet at the boom tip does not have GFCI protection, the lack of

circuit protection increases the risk of severe electric shock or thermal events

in moist environments.

Description of the Cause: NR

Identification of Any Warning There is no warning.

that can Occur:

## **Involved Components:**

Component Name 1: NA
Component Description: NR
Component Part Number: NR

## **Supplier Identification:**

### **Component Manufacturer**

Name: Altec Inc.

Address: 2106 S Riverside Rd

Saint Joseph Missouri 64507-2535

**Country: United States** 

## **Chronology:**

In December 2022, Altec initiated a review of compliance with a revision to an internal standard and discovered engineering might not have revised some unit design specifications to ensure they complied with the new requirements. On March 28, 2023, an investigation was initiated to determine if units in the field could have a 110V outlet at the boom tip without an inline GFCI mounted in the body compartment. On June 16, 2023, after reviewing the data collected in the investigation, Altec determined that a defect could exist on units in the field, and a campaign should be completed to inspect and update the affected units. There were no warranty claims or field reports identified. There have been no accidents, injuries, or deaths related to this issue.

## **Description of Remedy:**

Description of Remedy Program: The remedy will include an inspection for a GFCI outlet located in the body

compartment that houses the inverter between the inverter and the boomtip outlet. If there is no GFCI outlet inline, a GFCI outlet will be added. The recall remedy will be completed free of charge when presented for repair. The Altec Warranty Policy covers the recall remedy, including cases requiring reimbursement for the cost of obtaining a pre-notification

remedy of the problem associated with this recall.

How Remedy Component Differs The remedy adds a GFCI outlet for the boomtip outlet circuit in a body

from Recalled Component: compartment.

Identify How/When Recall Condition On December 19, 2022, production documents were updated to specify was Corrected in Production: that a GFCI be installed in the body compartment for the boomtip outlet

circuit.

#### **Recall Schedule:**

Description of Recall Schedule: Altec will issue CSN 3091 to the owners of the affected units. Altec does

not have a dealer network and issues letters to owners only.

Planned Dealer Notification Date : AUG 25, 2023 - AUG 25, 2023 Planned Owner Notification Date : AUG 25, 2023 - AUG 25, 2023

\* NR - Not Reported