

	GROUP	NUMBER	
	RECALL	23-01-065H	
DATE		MODEL(S)	
	AUGUST 2023	Tucson (NX4a)	

SUBJECT:

TIRE PRESSURE LABEL REPLACEMENT (RECALL 247)


### \* IMPORTANT

Vehicle repairs related to recalls are critically important and must be performed properly in accordance with TSB procedures. Review this bulletin in its entirety prior to beginning any repair work.

As required by federal law, dealers must not deliver new vehicles for sale or for lease to customers until all open recalls have been performed. Dealers must also perform all open recalls on used vehicles, demo, and rental vehicles prior to placing them into customer use and whenever an affected vehicle is in the shop for any maintenance or repair.


Access the "Vehicle Information" screen via WEBDCS to identify open recalls.

**Description:** The current tire and loading information labels on some 2024MY Tucson (NX4a) vehicles indicate tire pressure specification for a spare tire. However they do not have a spare tire. This bulletin provides the procedures to remove incorrect tire pressure labels, and replace with revised labels on some Tucson (NX4a) vehicles equipped with a tire mobility kit (TMK).



Applicable Vehicles (Certain): 2024MY Tucson (NX4a) produced 6/24/2023-7/17/2023.

#### **Parts Information:**



**Warranty Information:** 

Model	Op. Code	Operation	Op. Time	Casual Part	Nature Code	Cause Code
Tucson (NX4a)	31DA16R0	Tire Pressure Label Replacement	0.3 M/H	05203-CW400	B11	ZZ7

NOTE 1: Submit claim on Claim Entry Screen as "Campaign" type.

**NOTE 2:** If a part is found in need of replacement while performing this recall and the affected part is still under warranty, submit a separate claim using the same repair order. If the affected part is out of warranty, submit a Prior Approval request for goodwill consideration prior to performing the work.

**NOTE 3:** This TSB includes Repair validation photos. Op times include VIN, Mileage and Repair validation photos as outlined in the Digital Documentation Policy.

TSB #: 23-01-065H Page 2 of 4

#### **Service Procedure:**

## STUI



This TSB includes Repair validation photos. Refer to the latest Warranty Digital Documentation Policy for requirements.

1. Open driver's door and locate the tire pressure label in the door jamb.





TSB #: 23-01-065H Page 3 of 4

2. Peel off the original label.



3. Clean off any adhesive residue left by the label, dirt, or other contamination using a clean cloth.



4. Install the new label in the same location and orientation.

# STUI



Using STUI, take a photo of the new tire pressure label with the last 6 digits of the VIN and the date of repair on a piece of paper.

Upload the photo to STUI.



5. The service procedure is now complete.

TSB #: 23-01-065H Page 4 of 4