

Part 573 Safety Recall Report

24V-004

Manufacturer Name : Mickey Truck Bodies, Inc.**Submission Date :** JAN 05, 2024**NHTSA Recall No. :** 24V-004**Manufacturer Recall No. :** NR**Manufacturer Information :****Manufacturer Name :** Mickey Truck Bodies, Inc.**Address :** 1305 Trinity Avenue
PO Box 2044 High Point NC 27261**Company phone :** 336-882-6806**Population :****Number of potentially involved :** 37**Estimated percentage with defect :** 95 %**Vehicle Information :****Vehicle 1 :** 2020-2023 Isuzu NRR**Vehicle Type :** BUSES, MEDIUM & HEAVY VEHICLES**Body Style :** VAN**Power Train :** DIESEL**Descriptive Information :** Carrier Transicold has decided that a defect which relates to motor vehicle safety exists in Supra series S6, S7, S8, S9 and S10 diesel truck refrigeration units (together, the "affected TRUs"). This recall includes 121 units.**Production Dates :** JAN 03, 2020 - NOV 06, 2023**VIN Range 1 : Begin :**

NR

End : NR☐ Not sequential**Description of Defect :****Description of the Defect :** The 12-volt wire harness, used for the fuel heat option within the affected TRUs, may be exposed and missing heat shrink.**FMVSS 1 :** NR**FMVSS 2 :** NR**Description of the Safety Risk :** The exposed, energized 12-volt wires, can, under certain conditions, lead to electrical arcing and possibly a fire.**Description of the Cause :** Carrier Transicold manufacturing error.**Identification of Any Warning** NR
that can Occur :**Involved Components :**

Component Name 1 : 12-volt wire harness

Component Description : used for the fuel heat option

Component Part Number : NR

Supplier Identification :

Component Manufacturer

Name : Carrier Transicold

Address : 700 Olympic Dr.
Athens 306601

Country : NR

Chronology :

December 19, 2022, Carrier Transicold determined that a defect which relates to motor vehicle safety exists in Supra series S6, S7, S8, S9 and S10 diesel truck refrigeration units (together, the "affected TRUs").

Description of Remedy :

Description of Remedy Program : The inspection and rework will be provided at no charge to the customer. During inspection, the dealer will straight cut any exposed wires in the harness, apply new heat shrink for some wires, add a connector to the remaining wires, and remove a fuse. The inspection and securing of an affected TRU's 12-volt harness will take approximately 1.5 hours.

How Remedy Component Differs from Recalled Component : The exposed wiring will be covered with heat shrink that will prevent any electrical arcs.

Identify How/When Recall Condition was Corrected in Production : NR

Recall Schedule :

Description of Recall Schedule : The customer will be notified of the defect via phone and certified mail beginning 1/5/2024.

Planned Dealer Notification Date : JAN 08, 2024 - FEB 29, 2024

Planned Owner Notification Date : JAN 05, 2024 - FEB 29, 2024

* NR - Not Reported