



David J. Johnson  
Director  
Service Engineering Operations  
Ford Customer Service Division

Ford Motor Company  
P. O. Box 1904  
Dearborn, Michigan 48121

May 12, 2022

**TO:** All U.S. Ford and Lincoln Dealers

**SUBJECT: NEW VEHICLE DELIVERY HOLD**  
Customer Satisfaction Program 21B61  
Certain 2021 Model Year Mach-E Vehicles  
Long Regen Stop Safely Now

**PROGRAM TERMS**

This program will be in effect from May 12, 2022 through May 12, 2023. There is no mileage limit for this program.

**URGENCY / EXPIRATION DATE**

This Customer Satisfaction Program has an expiration date of May 12, 2023, to encourage dealers and customers to have this service performed as soon as possible. FSA VIN Lists are expected to be available by May 12, 2022.

**AFFECTED VEHICLES**

Vehicle	Model Year	Assembly Plant	Build Dates
Mach-E	2021	Cuautitlan	February 24, 2020 through March 19, 2021

Affected vehicles are identified in OASIS and FSA VIN Lists.

**REASON FOR THIS PROGRAM**

In some of the affected vehicles, loss of propulsion during extended downhill drives may occur. This condition only occurs in drive cycles that consist of mostly downhill driving for an extended period of time.

**SERVICE ACTION**

Before delivering any new in-stock vehicles involved in this program, dealers are to update the software and replace the park pawl. This service must be performed on all affected vehicles at no charge to the vehicle owner.

**OWNER NOTIFICATION MAILING SCHEDULE**

Owner letters are expected to be mailed the week of June 1, 2022. Dealers should repair any affected vehicles that arrive at their dealerships, whether or not the customer has received a letter.

**ATTACHMENTS**


Attachment I: Administrative Information  
Attachment II: Labor Allowances and Parts Ordering Information  
Attachment III: Technical Information  
Owner Notification Letter

**QUESTIONS & ASSISTANCE**

For questions and assistance, contact the Special Service Support Center (SSSC) via the SSSC Web Contact Site. The SSSC Web Contact Site can be accessed through the Professional Technician

System (PTS) website using the SSSC link listed at the bottom of the OASIS VIN report screen or listed under the SSSC tab.

Sincerely,

A handwritten signature in black ink, appearing to read "D. Johnson". The signature is written in a cursive style with a large initial "D" and a long, sweeping underline.

David J. Johnson

**NEW VEHICLE DELIVERY HOLD**  
**Customer Satisfaction Program 21B61**  
Certain 2021 Model Year Mach-E Vehicles  
Long Regen Stop Safely Now

**OASIS ACTIVATION**

OASIS will be activated on May 12, 2022.

**FSA VIN LISTS ACTIVATION**

FSA VIN Lists will be available through <https://web.fsavinlists.dealerconnection.com> on May 12, 2022. Owner names and addresses will be available by June 17, 2022.

**NOTE:** Your FSA VIN Lists may contain owner names and addresses obtained from motor vehicle registration records. The use of such motor vehicle registration data for any purpose other than in connection with this program is a violation of law in several states, provinces, and countries. Accordingly, you must limit the use of this listing to the follow-up necessary to complete this service action.

**SOLD VEHICLES**

- Owners of affected vehicles will be directed to dealers for repairs.
- Immediately contact any of your affected customers whose vehicles are not on your VIN list but are identified in OASIS. Give the customer a copy of the Owner Notification Letter (when available) and schedule a service date.
- Correct other affected vehicles identified in OASIS which are brought to your dealership.
- Dealers are to prioritize repairs of customer vehicles over repairs of new and used vehicle inventory.

**STOCK VEHICLES**

- Correct all affected units in your new vehicle inventory before delivery.
- Use OASIS to identify any affected vehicles in your used vehicle inventory.

**TITLE BRANDED / SALVAGED VEHICLES**

Affected title branded and salvaged vehicles are eligible for this service action.

**OWNER REFUNDS**

Refunds are not approved for this program.

**RENTAL VEHICLES**

Rental vehicles are not approved for this program.

**NEW VEHICLE DELIVERY HOLD**  
**Customer Satisfaction Program 21B61**  
Certain 2021 Model Year Mach-E Vehicles  
Long Regen Stop Safely Now

**ADDITIONAL REPAIR (LABOR TIME AND/OR PARTS)**

Additional repairs identified as necessary to complete the FSA should be managed as follows:

- For related damage and access time requirements, refer to the Warranty and Policy Manual / Section 6 – Ford & Lincoln Program Policies / General Information & Special Circumstances for FSA's / Related Damage.
- For vehicles within new vehicle bumper-to-bumper warranty coverage, no SSSC approval is required, although related damage must be on a separate repair line with the "Related Damage" radio button checked.
  - Ford vehicles – 3 years or 36,000 miles
- For vehicles outside new vehicle bumper-to-bumper warranty coverage, submit an Approval Request to the SSSC Web Contact Site prior to completing the repair.

**CLAIMS PREPARATION AND SUBMISSION**

- **Claim Entry:** Enter claims using Dealer Management System (DMS) or One Warranty Solution (OWS) online.
  - When entering claims:
    - Claim type 31: Field Service Action. The FSA number 21B61 is the sub code.
    - Customer Concern Code (CCC): Z08
    - Condition Code (CC): 79
    - Causal Part Number: 7D410
    - Part Quantity: 0
  - For additional claims preparation and submission information, refer to the Recall and Customer Satisfaction Program (CSP) Repairs in the OWS User Guide.
- **Related Damage/Additional labor and/or parts:** Must be claimed as Related Damage on a separate repair line from the FSA with same claim type and sub code as described in Claim Entry above.  
**IMPORTANT:** Click the Related Damage Indicator radio button.
- Multiple refunds should be submitted on one repair line and the invoice details for each repair should be detailed in the comments section of the claim.

**NEW VEHICLE DELIVERY HOLD**  
**Customer Satisfaction Program 21B61**  
 Certain 2021 Model Year Mach-E Vehicles  
 Long Regen Stop Safely Now

**LABOR ALLOWANCES**

Description	Labor Operation	Labor Time
Software Update - SOBDMC - Secondary On-Board Diagnostic Control Module C (Includes Any Other Module Required To Complete SOBDMC Programming) (Can Be Used With C)	MT21B61B	Up to 2.0 Hours
Park Pawl Replacement (Can be Used With B)	21B61C	6.1 Hours

**PARTS REQUIREMENTS / ORDERING INFORMATION****SSSC Web Contact Site:**

To place an order for K-Coded parts submit a VIN-specific Part Order contact via the SSSC Web Contact Site.

Part Number	Description	Order Quantity	Claim Quantity
LJ9Z-7A233-A	Gear	1	1
LJ9Z-7D410-A	Rod – Parking Pawl Actuating (Rod park shift, Cam-bullet Nose, Spring-Rod – KIT)	1	1
LJ9Z-7D412-A	Pin – Pawl Actuating Lever	1	1
LJ9Z-7A441-A	Pawl Assembly - Parking	1	1
LJ9Z-7L252-A	Spring	1	1
LJ9Z-7C078-A	Wiring Assembly - Transmission	1	1
LJ9Z-15K861-A	Bracket	1	1
LJ9Z-3B498-B	Intermediate Shaft Retaining Circlip	1	1
LJ9Z-7045-A	Park Gear Nut	1	1
LJ9Z-7H260-B	LH Rear Half Shaft Seal	1	1
LK9Z-7061-B	Intermediate Shaft Seal	1	1

Dealers will be notified via a DOES II communication if circumstances warrant a change in part supply strategy and when open ordering resumes.

**DEALER PRICE**

For latest prices, refer to DOES II.

**NEW VEHICLE DELIVERY HOLD**  
**Customer Satisfaction Program 21B61**  
Certain 2021 Model Year Mach-E Vehicles  
Long Regen Stop Safely Now

**PARTS RETENTION, RETURN, & SCRAPPING**

Follow the provisions of the Warranty and Policy Manual, Section 1 - WARRANTY PARTS RETENTION AND RETURN POLICIES. If a replaced part receives a scrap disposition, the part must be scrapped in accordance with all applicable local, state and federal environmental protection and hazardous material regulations. Federal law prohibits selling motor vehicle parts or components that are under safety, compliance, or emissions recall.

**EXCESS STOCK RETURN**

Excess stock returned for credit must have been purchased from Ford Customer Service Division in accordance with Policy Procedure Bulletin 4000.

**REPLACED FSA PARTS INSPECTION AND SIGN OFF**

Effective March 1<sup>st</sup> 2021 all parts replaced as part of an FSA repair with a repair order open date of March 1<sup>st</sup> 2021 or later must be inspected and signed off on the repair order by a member of your dealers fixed operations management team or an employee the task has been delegated to. If the task is to be delegated to a non-management employee, the employee needs to be someone other than the technician who completed the repair and needs to understand the importance of completing this task consistently and accurately.

- All parts replaced as part of an FSA repair should be returned to the parts department following the Warranty Parts Retention and Return Policies.
- Inspect the replaced parts to verify the FSA repair was completed.
- If the FSA repair is found to be complete, the designated employee signs the repair order line or parts return stamp area (electronic or hand signed) for the FSA repair indicating the parts were inspected and validated to have been replaced.
- After the parts have been inspected, they should be handled based on the guidance in the parts status report in the Online Warranty System (Hold, Return, CORE, Scrap, etc.).
- This process is subject to review during warranty audits for FSA repairs with a repair order open date of March 1<sup>st</sup> 2021 or later. Any eligible FSA claims requiring parts replacement, found not to have been inspected and signed off during a warranty audit will be subject to chargeback and consideration for enrollment into the Dealer Incomplete Recall Repair Process.

**Note:** Other approvals (electronic or handwritten) for add-on repair lines, dealer owned vehicle repairs, and repeat repairs do not qualify as FSA parts inspection approvals. The post repair FSA parts inspection process (electronic or handwritten) is independent from other warranty approval requirements. The approval by the designated employee implies that the FSA parts were found to be replaced and must be able to be clearly identified on the Repair Order. If multiple FSA's require approval on a single Repair Order, each applicable occurrence will require individual post repair approval by the designated employee.

## CERTAIN 2021 MODEL YEAR MACH-E VEHICLES — LONG REGEN STOP SAFELY NOW

### SERVICE PROCEDURE

#### Module Programming and Park Pawl Replacement

1. Replace the park lock actuator, park pawl, and park gear. Please follow Workshop Manual (WSM) procedures in Section 302-02.

**NOTE:** Program appropriate vehicle modules before performing diagnostics and clear all DTC's after programming. For DTC's generated after programming, follow normal diagnostic service procedures.

2. Connect a battery charger to the 12V battery.

**NOTE:** Verify that the negative cable of the charger is installed on a chassis or engine ground, and not the 12 volt battery negative terminal to prevent the battery saver mode from activating on the vehicle.

**NOTE:** If the diagnostic software does not load or if the vehicle cannot be identified properly, make sure there is a good internet connection and the VCM is properly connected to the DLC.

3. Log into Ford Diagnostic and Repair System (FDRS).

**NOTE:** Vehicle information is automatically retrieved by the diagnostic software and a Network Test is run. Vehicle identification data appears on the screen when this is complete.

4. Click 'Read VIN from Vehicle' or manually enter the VIN.

**NOTE:** Available modules are shown on the LH side of the screen, and available procedures are listed on the RH side of the screen. Modules that are communicating are highlighted in green.

5. Select Toolbox tab.

6. From the list on the LH side of the screen, select the SOBDMC.

7. From the list on the RH side of the screen, select SOBDMC - Secondary On-Board Diagnostic Control Module C (SOBDMC) Software Update.

8. Click RUN. Follow all on-screen instructions carefully.

**NOTE:** If the Powertrain Control Module (PCM) is not updated during the SOBDMC update, it will need to be ran prior to proceeding with step 9.

9. From the list on the RH side of the screen, select Self-Test and click RUN.



10. Click the Run Selected Tests button in the lower right.
11. Click the Clear & Retest button at the top of the screen to clear DTC's in all modules.
12. Disconnect the battery charger from the 12V battery once the programming has completed.

**IMPORTANT NOTE: Federal law prohibits selling motor vehicle parts or components that are under safety, compliance, or emissions recall. Unless a part is requested to be returned to Ford, all parts replaced under this FSA must be scrapped in accordance with all applicable local, state and federal environmental protection and hazardous material regulations. Refer to the Parts Retention, Return, & Scrapping section of the FSA dealer bulletin for further information.**

### Important Information for Module Programming

**NOTE:** When programming a module, use the following basic checks to ensure programming completes without errors.

- Make sure the 12V battery is fully charged before carrying out the programming steps and connect FDRS/scan tool to a power source.

**NOTE:** A good internet connection is necessary to identify the vehicle and to load the diagnostic software.

- Inspect Vehicle Communication Module II (VCM II)/Vehicle Communication and Measurement Module (VCMM) and cables for any damage. Make sure scan tool connections are not interrupted during programming.
- A hardwired connection is strongly recommended.
- Turn off all unnecessary accessories (radio, heated/cooled seats, headlamps, interior lamps, HVAC system, etc.) and close doors.
- Disconnect/depower any aftermarket accessories (remote start, alarm, power inverter, CB radio, etc.).
- Follow all scan tool on-screen instructions carefully.
- Disable FDRS/scan tool sleep mode, screensaver, hibernation modes.
- Create all sessions key on engine off (KOEO). Starting the vehicle before creating a session will cause errors within the programming inhale process.

### Recovering a module when programming has resulted in a blank module

- a. Disconnect the VCMII or VCMM from the data link connector (DLC) and your PC.
- b. After ten seconds, reconnect the VCMII/VCMM to the DLC and the PC. Launch FDRS. The VCMII/VCMM icon should turn green in the bottom right corner of the screen. If it does not, troubleshoot the FDRS to VCM connection.
- c. If you are using the same FDRS as the initial programming attempt, select the appropriate VIN from the Vehicle Identification menu. If you are using a different FDRS, select "Read VIN from Vehicle" and proceed through the Network Test.
- d. In the Toolbox menu, navigate to the failed module and Download/Run Programmable Module Installation (PMI). Follow the on-screen prompts. When asked if the original module is installed, select "No" and continue through the installation application.
- e. Once programming has completed, a screen may list additional steps required to complete the programming process. Make sure all applicable steps are followed in order.

