



## AFFECTED VEHICLES

A total of 59,934 U.S. WRX STI vehicles will be affected by this recall, as listed below:

Model Year	Carline	Production Date Range
2015-2021	WRX STI	November 14, 2013 – October 21, 2021

Not all vehicles in the production range listed above are affected by this recall. Coverage must be confirmed by using the Vehicle Coverage Inquiry function on [subarunet.com](http://subarunet.com) prior to repair.

## RETAILER RESPONSIBILITY

Any vehicles listed in any recall/campaign that are in retailer stock must be:


- Immediately identified
- Tagged or otherwise marked to prevent their delivery or use prior to repair
- Repaired in accordance with the repair procedures outlined in the Product Campaign Bulletin

Retailers are to promptly perform the applicable service procedures, to correct all affected vehicles in their inventory (used, demo & SSLP). Whenever a vehicle subject to this recall is taken into retailer inventory necessary steps should be taken to ensure the recall correction has been made before selling or releasing the vehicle.

## OWNER NOTIFICATION

Subaru will notify affected vehicle owners by first class mail on September 16, 2022.


## COMPONENT DESCRIPTION:



*Continued...*

**PART INFORMATION:**

**IMPORTANT:** BACK-UP LAMP SWITCH KIT A (p.n. X3200AA220) and BACK-UP SWITCH KIT B (p.n. X3200AA330) MUST be ordered through PRIME.

2015 MY- 2018 MY except 2018MY Type RA				
Part Description	Part Number	Qty	Identification Label	
BACK LAMP SW KIT A	X3200AA220	1		
KIT Component Breakdown				
	Part Description	Part Number	Qty	Details
(1)	SW ASSY-BACK LAMP (Back lamp switch)	32005AA1139R	1	 Gasket is in the Package
(2)	GSKT-INTER COOLER	21896AA0729R	1	
(3)	GASKET(CR)	44022AA1239R	1	
(4)	SPRING PIN UN,G/S	6330460209R	1	
(5)	SELF LOCK NUT M10	9023300119R	4	
(6)	NUT FLG M8	9023800159R	6	
(7)	GSKT	44011AG0019R	1	
(8)	GASKET	44011SG0109R	2	  Major axis: 45.7 mm  Minor axis: 41.7 mm

*Continued...*

**North America: 2019 MY - 2021 MY and 2018MY Type RA**

Part Description	Part Number	Qty	Identification Label
BACK LAMP SW KIT B	X3200AA330	1	

**KIT Component Breakdown**

	Part Description	Part Number	Qty	Details	
(1)	SW ASSY-BACK LAMP (Back lamp switch)	32005AA1139R	1		Gasket Included
(2)	GSKT-INTER COOLER	21896AA0729R	1		
(3)	GASKET(CR)	44022AA1239R	1		
(4)	SPRING PIN UN,G/S	6330460209R	1		
(5)	SELF LOCK NUT M10	9023300119R	4		See Additional Note
(6)	NUT FLG M8	9023800159R	6		
(7)	GSKT	44011AG0019R	1		
(8)	GASKET	44011SG0009R	2		Major axis: 53.8 mm  Minor axis: 49.8 mm
(9)	SELF LOCK NUT	0235080009R	12		STI draw Stiffener fixing nut Discard if these are not used.

*Continued...*

**ADDITIONAL PARTS NOTES:**

**IMPORTANT:** (5) SELF LOCK NUT M10 (p.n. 9023300119R) and (6) NUT FLG M8 (p.n. 9023800159R) supplied in the kit may be different from the nuts installed in the affected vehicle. These parts are interchangeable and can be used for this recall work.


<b>(5) SELF LOCK NUT M10</b>			
<b>Part Application</b>	<b>Part Number</b>	<b>Details</b>	
Replacement Part	9023300119R		Nut is exclusive for this recall
Vehicles Produced up to April 2016	902350001		Original installation nut & normal repair part
Vehicles Produced After April 2016	902330011		

<b>(6) NUT FLG M8</b>			
<b>Part Application</b>	<b>Part Number</b>	<b>Details</b>	
Replacement Part	9023800159R	 No Crimping	Nut is exclusive for this recall
Vehicles Produced up to July 2014	902350028	 Crimping	Original installation nut & normal repair part
Vehicles Produced After July 2014	902380015	 No Crimping	

**IMPORTANT:** The exhaust hardware and gaskets included in the kits are no longer required due to a procedure change introduced on 11/10/23.

**Required Tools:**

A Pin Punch with an 8mm Diameter and recommended length of 200mm or more. This is used for the removal and installation of the shift rod locking spring.



*Continued...*


**IMPORTANT:** The following tools framed in **BLUE** will be included in WRE-22 Tool Kit (p.n. SOA635173). This kit will be shipped to all retailers.

The Extended Universal Socket (p.n. 18270AA090) is used for removing and installing the back-up lamp switch.




### Component Details:

The configuration images below outline the part application, part numbers, and torque information of the components involved when performing this work procedure. A **black star (★)** in the component breakdown illustrations is used to indicate one-time use parts.




*Continued...*

## 2015-16MY Intercooler




## 2015-21MY Engine Area




Continued...

## 2015-21MY Drive Shaft / Exhaust




Continued...

# 2015-21MY Manual Transmission



Continued...

Service Procedure Overview Flowchart:




*Continued...*

**SERVICE PROCEDURE / INFORMATION:**


**STEP 1:** Lift up the vehicle.

**STEP 2:** For 2019MY S209 model, remove the STI flexible draw stiffener. Refer to the [S209 Service Manual](#)

**STEP 3:** Remove clip (A), the two bolts (B), the two clips (C) and clip (D). The lower transmission cover can then be removed.



**STEP 4:** Perform a visual inspection of the wiring harness colors on the back-up lamp switch.




Inspect the coloring of the two wires on the switch side of the gray connector  
The black protection tube can be pulled back for inspection

*Continued...*

**STEP 5:** Apply the visual inspection results from **STEP 4** to the table below to verify the next course of action.

Wiring Harness Color	WHITE/GREEN 	BLACK 
Back-Up Lamp Switch Version	<b>OLD</b>	<b>NEW</b>
Back-Up Lamp Switch Replacement	<b>REQUIRED</b>	<b><u>NOT</u> REQUIRED</b>
Next Step	<b>Proceed to STEP 6</b>	No further action is required. Reinstall the removed parts in the reverse order of disassembly.

**STEP 6:** Refer to the applicable Service Manual and review: General Description > Repair Contents > Action required before & after Battery Disconnect. Additionally, record any stored seat position(s) before proceeding. Relearn any seat position memory after work is complete. Confirm that the shift lever is in the Neutral position. Confirm the parking brake is released. Depress the brake pedal several times to remove any pressure in the brake booster. **CAREFULLY** remove the ground terminal from the battery.



*Continued...*


**STEP 7:** Remove the intercooler in accordance with the applicable Service Manual.

**NOTE:** S209 models will require the removal of the STI Flexible Tower Bar. The strut mounting nuts are one-time use parts. Refer to Refer to the [S209 Service Manual](#).

**CAUTION:** Be mindful not to deform or damage the intercooler fins. Tape and cardboard can be used for added protection.



**STEP 8:** Remove the pitching stopper. Take note of the hardware positioning for reassembly.




**STEP 9:** Set the transmission jack to support the transmission.




*Continued...*


**STEP 10:** Prepare two pieces of cardboard or thick paper by cutting them to the sized dimensions outlined.



**STEP 11:** Remove the four heat shield mounting bolts. DO NOT removed the shield at this time. Remove the six mounting bolts and two mounting nuts for the crossmember.



**STEP 12:** Slowly lower the transmission jack. Using the 80mm cut section as a gauge, confirm the distance between the transmission output dust cover and the floor pan is 80mm.



*Continued...*

**STEP 13:**


Remove the crossmember toward the left side of the vehicle.



**STEP 14:** Loosen the mounting bolts securing the center heat shield and then CAREFULLY remove the heat shield toward the passenger side of the vehicle. Swing the rear portion of the heat shield out first and CAREFULLY thread the oxygen sensor wiring through the shield.




**STEP 15:** Remove the snap pin and washer from the reverse check cable. These parts will be reused and should be stored securely. Once removed, disconnect the cable from the reverse check lever.




*Continued...*

**STEP 16:** Loosen the stay bolt. Remove the stay, stay bolt, and reverse check bracket by moving it in a downward direction away from the shift bracket.




**STEP 17:** Slowly lower the transmission jack. Using the 95mm cut section as a gauge, confirm the distance between the transmission output dust cover and the floor pan is 95mm.

**CAUTION: DO NOT increase the distance beyond 95mm. This may cause damage to the transmission and propeller shaft.**




**STEP 18:** Release the retaining bands holding the back-up switch harness.





*Continued...*

**STEP 19:** Disconnect the gray two-pin connector on the back-up switch harness.



**STEP 20:** Using compressed air, clear any debris from the back-up switch. This will help prevent any contamination.



**STEP 21:** Install the special tool (p.n. 18270AA090) onto the back-up switch with the wires aligned with the socket recess. Make sure the tool is passed under the switch harness. A 3/8 universal socket and eight-inch extension can be used in conjunction with the special tool.




**CAUTION:** Confirm the socket is fully seated onto the back-up switch. Confirm the wires are not damaged by the socket.




*Continued...*


**CAUTION:** Take particular care not to damage the neutral position switch with the special tool.



**STEP 22:** Loosen the back-up switch from the transmission case. Rotate the switch harness while turning the socket to prevent any excessive tension. The switch and the special tool cannot be removed together due to interference with the transmission case. Remove the tool before removing the switch.




**STEP 23:** Install the new back-up switch with the new gasket. Rotate the switch by hand while turning its connector in order to avoid any twisting of the harness.




*Continued...*

**STEP 24:** Using the same precautions practiced in the switch removal, tighten the new switch, and set the torque to **32Nm (23.6 ft-lb)**.


**STEP 25:** Connect the new back-up switch connector. Secure the wiring harness to the associated retaining bands.



**STEP 26:** Slowly raise the transmission jack. Using the 80mm cut section as a gauge, confirm the distance between the transmission output dust cover and the floor pan is 80mm.




**STEP 27:** Apply a thin layer of Conoco Philips Multiplex Red #2 (p.n. 000041000) to the contact portions between the shift bracket and stay bushing. This will help assist the installation.




*Continued...*


**STEP 28:** Apply a thin layer of Conoco Philips Multiplex Red #2 (p.n. 000041000) to the bushing of the reverse check cable its associated contact point.





**STEP 29:** Install the stay, stay bolt, and cable plate into the shift bracket and tighten the bolt to 32Nm (23.6ft-lb).



**CAUTION:** CAREFULLY align the claw for the cable plate with the groove of the shift bracket before tightening the stay bolt. If the bolt is tightened without this alignment, the plate can be damaged.




**STEP 30:** Install the reverse check cable to the reverse check lever. Secure the connection with the washer and locking snap pin.



*Continued...*

**STEP 31:** Install the cross member to the transmission with the two mounting nuts. Install the heat shield with the mounting bolts hand tight. Confirm the alignment is sufficient by adjusting the transmission jack if needed. Install the cross member to the vehicle body with the six mounting bolts. Torque the crossmember mounting bolts. Once the torque procedure is complete, the transmission jack can be removed.




**Torque Specification**  
**T1: 35Nm (25.8ft-lb)**  
**T2: 70Nm (51.6ft-lb)**  
**T3: 140Nm (103ft-lb)**

**STEP 32:** Torque the heat shield mounting bolts to **18Nm (13.3ft-lb)**.

**STEP 33:** Lower the vehicle and confirm the parking brake is applied. 2019MY S209 models, install the STI flexible draw stiffener. Refer to the [S209 Service Manual](#).


**STEP 34:** Install the pitching stopper with the two mounting bolts. Torque the vehicle body side bolt to **58Nm (42.8ft-lb)**. Torque the engine side mounting bolt to **50Nm (36.9ft-lb)**.



**STEP 35:** Reinstall the intercooler in accordance with the applicable Service Manual. Be mindful not to deform or damage the intercooler fins. For 2019MY S209 models, install the STI flexible Tower Bar. Refer to the [S209 Service Manual](#).

*Continued...*

**STEP 36:** Reconnect the ground cable terminal to the battery sensor, torque to **7.5Nm (5.5ft.-lbs. or 66inch-lbs.)** while supporting the sensor with the other hand.



**NOTE:** If needed, clean the battery cable terminals, and apply the approved protectant.

**STEP 37:** Perform and function test of the back-up switch by moving the shift lever into the reverse position and confirm the lamp illuminates when required.

**STEP 38:** Perform Intake and Exhaust leak check and confirm that there are no leaks.

**CLAIM REIMBURSEMENT AND ENTRY PROCEDURES:**

Credit to perform this recall will be based on properly completed repair order information. Retailers may submit claims through [Subarunet.com](http://Subarunet.com).

Labor Description	Labor Operation #	Labor Time	Fail Code
WIRE HARNESS INSPECTION ONLY	A168-428	0.2	WRE-22
NON-S209 INSPECTION & BACKUP LAMP SWITCH REPLACEMENT	A168-421	1.7	
S209 INSPECTION & BACKUP LAMP SWITCH REPLACEMENT	A168-422	2.0	

Up to 10 cents can be claimed in sublet for Conoco Philips Multiplex Red #2 (p.n. 000041000).

**IMPORTANT REMINDERS:**


- SOA strongly discourages the printing and/or local storage of service information as previously released information and electronic publications may be updated at any time.
- Always check for any open recalls or campaigns anytime a vehicle is in for servicing.
- Always refer to STIS for the latest service information before performing any repairs.

*Continued...*

**SERVICE PROGRAM IDENTIFICATION LABEL:**

Type or print the necessary information on a Campaign Identification Label. The completed label should be attached to the vehicle's upper radiator support. Additional labels are available through normal parts ordering channels. The part number is **MSA6P1302**, which comes as one sheet of 20 labels.

Part Number	Applicability	Description	Order Quantity
MSA6P1302	All Models	Campaign Completion Labels (contains one sheet of 20 labels)	1



*Continued...*

**URGENT  
IMPORTANT SAFETY RECALL**



**SUBARU**

Subaru of America, Inc  
PO Box 9103  
Camden, NJ 08101-9877  
844-373-6614  
www.subaru.com

**Subaru Safety Recall WRE-22  
NHTSA ID 22V-522  
September 2022**

**Dear Subaru Owner:**

This notice is sent to you in accordance with the National Traffic and Motor Vehicle Safety Act.

SUBARU OF AMERICA, INC. has decided that a defect, which relates to motor vehicle safety, exists in certain 2015-2021 model year WRX STI vehicles.

You received this notice because our records indicate that you currently own one of these vehicles.

**DESCRIPTION OF THE DEFECT**

Your vehicle may contain a defective back-up lamp switch, which may cause the back-up lamps to not illuminate, the rear-view camera (if equipped) to not display an image, and the select lever/gear position indicator in the combination meter to not display 'R' when driving in reverse.

**SAFETY RISK**

If the back-up lamps do not illuminate when the vehicle is in reverse gear, this may reduce the awareness of other motorists or road users of the driver's intention to operate the vehicle in reverse, increasing the risk of a crash. Additionally, a rear-view camera that does not display an image can reduce the driver's view of what is behind the vehicle, increasing the risk of a crash.

**WHAT SUBARU WILL DO**

Subaru will conduct an inspection and replace the back-up lamp switch with improved one, if necessary, at no cost to you.

**WHAT YOU SHOULD DO**

Please contact your Subaru retailer (dealer) immediately for an appointment to have this repair performed, at no cost to you.

Until this repair is performed, please use caution when driving in reverse. You should always check the rear view and the surrounding area by turning your head rearward and/or using the mirrors and move backward at a slow speed.

## **HOW LONG WILL THE REPAIR TAKE?**

The time it will take to inspect your vehicle is less than fifteen minutes. If it is found that the switch needs to be replaced, the time for this repair is approximately two hours. However, it may be necessary to leave your vehicle for a longer period of time on the day of your scheduled appointment to allow your Subaru retailer flexibility in scheduling.

## **OWNER INFORMATION**

Government regulations require that recall notifications be sent to the last known owner of record. That information is based primarily on state registration and title data. If you are a lessor of this vehicle, federal regulations require you to forward this notice to your lessee within ten days.

If you have moved or sold your vehicle, please go to <https://www.subaru.com/support/customer-support.html> to send us your information.

## **IF YOU HAVE PREVIOUSLY PAID FOR A REPAIR**

If you have already paid for repairs associated with this condition, you may be eligible for reimbursement. Reimbursement consideration will be based on the amount an authorized Subaru retailer in your area would charge for the same repair.

Please send the original service repair order, which has the name of the repair facility, date of repair, mileage at the time of repair, complete 17-digit vehicle identification number (VIN), and your name, with correct mailing address and telephone number to the address listed below.

**Subaru of America, Inc.**  
**Customer Advocacy Department, Attention: WRE-22 Recall**  
**P.O. Box 9103, Camden, NJ 08101-9877**

Please send original receipts only and retain a photocopy for your records. Please be assured that we will attempt to process your reimbursement request as quickly as possible, but it may take up to 60 days for this process to be completed.

## **IF YOU NEED FURTHER ASSISTANCE:**

To locate the nearest Subaru retailer, you can access our website at [www.subaru.com](http://www.subaru.com) and select 'Find a Retailer.'

For additional information, please go to: <http://www.wre22.service-campaign.com>.

If you need additional assistance, please contact us directly:

- By e-mail: Go to [www.subaru.com](http://www.subaru.com) and select "Customer Support"
- By telephone: 1-844-373-6614  
Monday through Friday between 8:00 a.m. and 7:00 p.m. ET
- By U.S. Postal mail: Write us at Subaru of America, Inc.  
Attn: Customer Advocacy Department  
P.O. Box 9103, Camden, NJ 08101-9877

To subscribe to the NHTSA Recall Notification email System, please go to: <https://www-odi.nhtsa.dot.gov/nhtsa/subscriptions>.

Please contact us immediately if the Subaru retailer fails or is unable to make the necessary repairs free of charge.

You may also contact the Administrator, National Highway Traffic Safety Administration (NHTSA), 1200 New Jersey Ave., SE, Washington, DC 20590 or call the toll-free Vehicle Safety Hotline at 1-888-327-4236 (TTY: 1-800-424-9153) or go to <http://www.NHTSA.gov> if you believe the Subaru retailer has failed or is unable to remedy your vehicle without charge within a reasonable amount of time.

Your continued satisfaction with your Subaru is important to us. Please understand that we have taken this action in the interest of your safety and your vehicle's proper operation. We sincerely apologize for any inconvenience this matter may cause and urge you to schedule an appointment as soon as possible.

Sincerely,

Subaru of America, Inc.

A subsidiary of SUBARU CORPORATION