Service Campaign Bulletin



Campaign No. 2021080017, November 2021

TO: ALL MERCEDES-BENZ CENTERS

SUBJECT: Model smart-Class (453 platform) Model Year 2017-2019

Update Battery Management System Control Unit Software

Mercedes-Benz AG ("MBAG"), the manufacturer of Mercedes-Benz, has determined that on certain MY 2017-2019 Smart-Class (453 platform) vehicles, the software for the battery management system does not correspond with the current series production configuration. It may be possible that a fault message displays in the instrument cluster and subsequently inhibits vehicle starting. MBUSA will conduct a service campaign. An authorized Mercedes-Benz dealer will update the battery management software.

Prior to performing this Campaign:

- VMI must always be checked before performing campaigns to verify that the campaign is required on a specific vehicle. Always check for any other open campaigns, and perform accordingly.
- Please review the entire Campaign bulletin and follow the repair procedure exactly as described.

Approximately 2451 vehicles are affected.

Order No. P-SC-2021080017 This bulletin has been created and maintained in accordance with MBUSA-SLP S423QH001, Document and Data Control, and MBUSA-SLP S424HH001, Control of Quality Records.

Service Campaign Bulletin

Service Campaign Bulletin

Update battery management system control unit software Model 453

- Ensure use of **XENTRY Diagnosis version** BD/DVD (**03/2021**) or higher.
 - Before starting the work procedure, install all the add-ons that are updated daily in XENTRY Diagnosis.
 - Make sure to follow the operation steps exactly as described in XENTRY Diagnosis.
 - Use a battery charger to ensure sufficient power supply of the vehicle **on-board electrical system battery** (for a greater than 12.5 V).

i If two or more software updates or SCN codings are performed during one workshop visit, operation items 02-4762, 02-5058 and 02-6508 may be invoiced **only once for each workshop order**!

Work procedure

1. <u>Perform power disconnect for high-voltage system.</u>

i For basic data, see AR54.10-P-1160SRE.

i Replace power electronics cover seal.

- **2.** Connect XENTRY Diagnosis.
- 3. Update N82/2 battery management system (BMS) control unit software.

 I To do this, select menu item "Quick test view ➡ N82/2 ➡ Battery management system (BMS) ➡ Adaptations ➡ Control unit update ➡ Updating of control unit software".
 I Then follow the user guidance in XENTRY Diagnosis.
- Perform commissioning for high-voltage system.
 I For basic data, see AR54.10-P-1160SRE.
- 5. Disconnect XENTRY Diagnosis.

Primary Parts Information

Qty.	Part Name	Part Number
1	Seal	A 453 528 03 00

i Note:

• The following allowable labor operation should be used when submitting a warranty claim for this repair:

Warranty Information

(with XENTRY Diagnosis connected)		Perform power disable/commissioning for high-voltage on-board electrical system (with XENTRY Diagnosis connected) Includes: Replace power electronics cover seal
(02-9	9334)	Update battery management system control unit software (with XENTRY Diagnosi connected)
(02-4	4762)*	Connect/disconnect vehicle diagnosis system (XENTRY Diagnosis)
(02-	5058)*	Connect/disconnect starter battery charger (with XENTRY Diagnosis connected)

Damage Code	Operation Number	Labor Time (hrs.)
	02-6508	0.9
E4 080 26	02-9334	0.1
54 989 26	02-4762*	0.1
	02-5058*	0.1

* Operation item may only be invoiced once for each repair order!

i_{Note}

Always check ASRA for the current OP-Code times. Labor times are subject to change and updates may not be reflected in this document.