TO: Mercedes-Benz Dealer Principals, General Managers, Sales Managers, Service Managers, Parts Managers	FROM: Gregory Gunther, Department Manager, Vehicle Compliance and Analysis, Engineering Services
RE: Emission Service Campaign 2022070004 Launch	
Notification	DATE: August 11, 2022
Replace Braided Hose of Low-Pressure Fuel Line	

IMPORTANT NEW EMISSION SERVICE CAMPAIGN INFORMATION

Please note that all customer inquiries should be directed to the Customer Assistance Center at 1-800-FOR-MERCEDES.

Sincerely,

Gregory Gunther

Department Manager, Vehicle Compliance & Analysis

Mercedes-Benz USA, LLC A Mercedes-Benz Group AG Company



News Channel Update Vehicle Compliance and Analysis

Emission Service Campaign Launch Notification		h Notification	August 11, 2022			
Campaign No. :	Campaign Desc. :		Replace Braided Hose of Low-Pressure			
2022070004	21P0792208		Fuel Line			
This is to notify you of an Emission Service Campaign launch to replace the braided hose of the low-pressure fuel line and install a heat shield over the new braided hose on 23,958 Model Year ("MY") 2018-2021 S-Class, S-Class Coupe/Cabriolet (217 and 222 platforms) vehicles. The affected vehicles will be visible and flagged in VMI as "OPEN" on August 12, 2022.						
	Background					
Issue What We're Doing		 Mercedes-Benz AG ("MBAG"), the manufacturer of Mercedes-Benz vehicles, has determined that on certain Model Year ("MY") 2028-2021 S-Class, S-Class Coupe/Cabriolet (217 and 222 platforms) vehicles, the low pressure fuel line does not correspond to the current series production configuration. Therefore, it is possible that accelerated aging in the area of connection could occur, resulting in a leak. A risk of fire can be ruled out. MBUSA will conduct an Emission Service Campaign. An authorized Mercedes-Benz dealer will replace the braided hose of low-pressure fuel line and install a heat shield over the new braided hose 				
Parts		Parts are available and may be ordred as necessary.				
Vehicles Affected						
Vehicle Model Year(s)	nicle Model Year(s) 2018-2021					
Vehicle Model		S-Class, S-Class Coupe/Cabriolet				
Vehicle Population						
Total Campaign Populatio	on	23,958				
While we regret any inconvenience this may cause, MBUSA is determined to maintain a high level of vehicle quality and customer satisfaction. Please refer all customer inquiries to the Customer Assistance Center at 1-800-FOR-MERCEDES.						

Mercedes-Benz USA, LLC A Mercedes-Benz Group AG Company





Campaign No. 2022070004, August 2022

TO: ALL MERCEDES-BENZ CENTERS

<u>Service</u> Campaign Bulletin

Service Campaign Bulletin

SUBJECT: Model S-Class (217 and 222 platform) Model Year 2018 - 2021

Replace Braided Hose of Low-Pressure Fuel Line

Mercedes-Benz AG ("MBAG"), the manufacturer of Mercedes-Benz vehicles, has determined that on certain Model Year ("MY") 2018-2021 S-Class, S-Class Coupe/Cabriolet (217 and 222 platforms) vehicles, the low pressure fuel line does not correspond to the current series production configuration. Therefore, it is possible that accelerated aging in the area of connection could occur, resulting in a leak. A risk of fire can be ruled out.

Prior to performing this Campaign:

- VMI must always be checked before performing campaigns to verify that the campaign is required on a specific vehicle. Always check for any other open campaigns, and perform accordingly.
- Please review the entire Campaign bulletin and follow the repair procedure exactly as described.

Approximately 23,958 vehicles are affected.

Order No. P-SC-2022070004

This bulletin has been created and maintained in accordance with MBUSA-SLP S423QH001, Document and Data Control, and MBUSA-SLP S424HH001, Control of Quality Record


Service Campaign Bulletin

Replace braided hose of right low-pressure fuel line Model 217 and 222

Work Procedure

- Remove right air filter housing.

 For basic data, see AR09.10-P-1152MNL.
- 2. Reduce fuel pressure via the service connection. i For basic data, see AR07.03-P-1460-01MNL.
- Remove bleed line between right cylinder head cover and oil separator (figure 1).
 Sealing ring will be reused.





Unscrew fastening clamps of low-pressure line (A, Figure 2) upstream and downstream of the braided hose.
 I The fastening clamps (A, Figure 2) should not be removed.



Figure 2

i

- 5. Open CLIC clamps on the braided hose and take off (figure 3, left). Carefully cut through the braided hose along its length and remove from the metal line (figure 3, right).
 - This makes it easier to remove the braided hose from the metal line.
 - Cover work environment with a rag so that the remaining fuel is collected.



P-SC-2022070004

Figure 3

6. <u>Slide</u> on new braided hose, position, and fasten with new CLIC clamps.

i Slide CLIC clamps onto line before the fabric hose.

i Position braided hose on metal line based on markings (figure 4, middle and right).

i Metal lines must not be bent during assembly!



Figure 4

- 7. Install heat shield over the new braided hose.
 - i Close snap fasteners.



Figure 5

8. Assemble in reverse order.

Primary Parts Information

Qty.	Part Name	Part Number
2	Hose clamp	A 000 995 60 10
1	Fuel hose	A 177 070 31 00
1	Heat shield	A 177 096 05 00

Note: The following allowable labor operation should be used when submitting a warranty claim for this repair.

Warranty Information

Damage Code	Operation Number	Description	
07 922 08	02-0900	Replace hose of right fuel line in low-pressure fuel circuit	0.9

Note: Always check ASRA for the current OP-Code times. Labor times are subject to change and updates may not be reflected in this document.