TO: Mercedes-Benz Dealer Principals, General Managers,	FROM: Gregory Gunther, Department Manager, Vehicle	
Sales Managers, Service Managers, Parts Managers	Compliance and Analysis, Engineering Services	
RE: Service Campaign Launch Notification		
Repair Seam Seal at A-Pillar	DATE: May 26, 2023	
MY23 GLC (253 platform)		

IMPORTANT SERVICE CAMPAIGN LAUNCH

Please note that all customer inquiries should be directed to the Customer Assistance Center at 1-800-FOR-MERCEDES (1-800-367-6372).

Sincerely,

Gregory Gunther

Department Manager, Vehicle Compliance & Analysis

Mercedes-Benz USA, LLC A Mercedes-Benz Group AG Company



Vehicle Compliance & Analysis

Service Campaign Launch Notification May 26, 2023					
Campaign No. :	Campaign Desc. :	Repair Seam Seal at A-Pillar			
2023050002	22P6391008				
		o repair the seam seal on the A-pillar in <u>98</u> Model Year ("MY") 2023 GLC (253 be visible and flagged in VMI as "OPEN" on May 26, 2023.			
		Background			
lssue	that on on a sm specific	des-Benz AG ("MBAG"), the manufacturer of Mercedes-Benz, has determined certain Model Year ("MY") 2023 GLC (253 platform) vehicles, the seam seal nall portion of the right A-pillar does not correspond with current production cations. It cannot be ruled out that a leak may occur due to an inconsistency seam seal.			
What We're Doing		MBUSA will conduct a service campaign. An authorized Mercedes-Benz dealer will repair the seam seal at the A-pillar.			
Parts	The rem	medy is available and can be performed as necessary.			
	V	Phicles Affected			
Vehicle Model Year(s)	2023				
Vehicle Model	GLC				
	Vehicle Populations				
Total Campaign Population	on 98				
Next Steps/Notes					
AOMS/SOMS	AON	As – This campaign may generate questions from your dealers.			

While we regret any inconvenience this may cause, MBUSA is determined to maintain a high level of vehicle quality and customer satisfaction. Please refer all customer inquiries to the Customer Assistance Center at 1-800-FOR-MERCEDES.

Mercedes-Benz USA, LLC A Mercedes-Benz Group AG Company



Service Campaign Bulletin



Campaign No. 2023050002, May 2023

TO: ALL MERCEDES-BENZ CENTERS

SUBJECT: Model GLC (253 platform) Model Year 2023

Repair Seam Seal at A-Pillar

Mercedes-Benz AG ("MBAG"), the manufacturer of Mercedes-Benz, has determined that on certain Model Year ("MY") 2023 GLC (253 platform) vehicles, the seam seal on a small portion of the right A-pillar does not correspond with current production specifications. It cannot be ruled out that a leak may occur due to an inconsistency in this seam seal. An authorized Mercedes-Benz dealer will repair the seam seal at the A-pillar.

Prior to performing this Campaign:

- VMI must be checked before performing campaigns to verify that the campaign is required on a specific vehicle. Always check for any other open campaigns, and perform accordingly.
- Please review the entire Campaign bulletin and follow the repair procedure exactly as described.

Approximately 98 vehicles are affected.

Order No. P-SC- 2023050002

Service Campaign Bulletin

Service Campaign Bulletin

Repair Seam Seal at A-Pillar

Work Procedure

- 1. Open right front door.
- 2. Fold back A-pillar cover (1, Figure 1) in upper area and fix in place with a suitable plastic wedge (2, Figure 1).



Figure 1: Example of seam seal with defect.

- Clean the affected area (see arrow in Figure 1).
 Silicone remover can be used for example.
- Apply activator to affected area (see arrow in Figure 1).
 Observe manufacturer's specifications for product!

Apply seam seal in affected area (Figure 2) with a suitable brush.
 Observe manufacturer's specifications for product!



Figure 2: Refinish seam seal.

- 6. Once the applied seam seal has dried, fold back A-pillar cover (1, Figure 1) again and slightly press on.
- i Via the residual stress of the material, the A-pillar cover (1, Figure 1) will lie flat again on its own after a short time.
- **7.** Close right front door.

Primary Parts Information

Qty.	Part Name	Part Number
1*	Activator	A 000 989 31 00
1*	Seam seal (transparent)	A 000 989 32 00 09

*One packaging unit suffices for at least 10 vehicles.

ISmall parts such as screws, lock nuts, sealing rings, cable ties, fluids, sealant, etc. are not listed in the parts list. The required small parts are taken into account in the budgeting.

iNote: The following allowable labor operation should be used when submitting a warranty claim for this repair.

Warranty Information

Damage Code	Operation Number	Description	
63 910 08	12-1685	Refinish seam seal at right A-pillar	

Note: Always check Xentry Operation Time (XOT) for the current OP-Code times. Labor times are subject to change and updates may not be reflected in this document.