

# Ferrari

Ferrari North America, Inc.

RECEIVED

MAR 11 1998

SALES & SERVICE DEPARTMENT

March 10, 1998

Ms. Kathleen DeMeter, Director  
Office of Defects Investigation  
National Highway Traffic Safety Administration  
400 Seventh Street, SW  
Washington, D.C. 20590

98V-057 (01)



Dear Ms. DeMeter:

Enclosed please find Vehicle Safety Defect Initial Information Reports regarding the Recall Campaign which we are initiating in order to correct the following:

On Ferrari vehicles, 1995 through 1997 F355 models with assembly numbers between 19318 and 23604, which have been fitted with single fuel pumps, the fuel injection line fitting may fracture if the aluminum nut attaching the lines is tightened in excess of the required tightening specifications. The potential for damage to the fuel lines by interference from the water hose clamp exists.

This condition was determined to exist after Ferrari factory laboratory testing showed that the repetitive tightening, without following the Ferrari's prescribed tightening torque specifications, can provoke stresses that can lead to fracture of the aluminum nut.

The remedy consists of replacing the 6 fuel injection lines which have nuts made of aluminum with new fuel injection lines, which have nuts made of steel, in accordance with the attached technical instructions, as well as checking and adjusting the positioning of the water hose clamp.

Attached you will find a list of all vehicles affected.

For the above campaign, it is our intention to notify each Ferrari Dealer with a comprehensive letter explaining the remedy and to notify each potentially affected vehicle owner with a letter informing them of the required recall modification. Follow-up letters will be sent if necessary.

Enclosed are draft letters that Ferrari North America, Inc. will send to the potentially affected owners and to the Authorized Ferrari Dealers, as well as a draft of the technical instructions.



Please do not hesitate to contact me at 201-816-2652 with any questions that you may have regarding the foregoing.

Thank you.

98V-057 (02)

Best regards,

*William S. Story - cc.*

William S. Story  
Director of Technical Services

WSS:cc

Enclosures

FERRARI NORTH AMERICA, INC.  
 250 SYLVAN AVENUE  
 ENGLEWOOD CLIFFS, NJ 07632  
 March 6, 1998

VEHICLE SAFETY DEFECT  
 INITIAL INFORMATION REPORT  
 FUEL INJECTION LINES AND CLAMP  
 (SINGLE FUEL PUMP VEHICLES)  
 RECALL No. 158

Date Submitted: March-98  
 Date Received: January-98  
 Campaign No.: 158  
 Campaign Date: March-98

<u>MAKE</u>	<u>MODEL</u>	<u>MODEL YEAR</u>	<u>NO. OF VEHICLES</u>	<u>ENCLOSED MFG. DATES</u> From Through	<u>OTHER VEHICLE IDENTIFICATION</u>
FERRARI	F 355	1995-1997	760	July 1995 September 1996	Vehicles fitted with single Fuel Pumps. See attached list

FERRARI NORTH AMERICA, INC.  
250 SYLVAN AVENUE  
ENGLEWOOD CLIFFS, NJ 07632  
March 6, 1998

VEHICLE SAFETY DEFECT  
INITIAL INFORMATION REPORT  
F355 FUEL INJECTION LINES AND CLAMP  
(SINGLE FUEL PUMP VEHICLE)  
RECALL No. 158

A) DESCRIPTION OF DEFECT:

On Ferrari Vehicles: Model year 1995-1997 F 355 fitted with single fuel pumps.

On Ferrari vehicles, 1995 through 1998 F355 models with assembly numbers between 19318 and 27398, which have been fitted with single fuel pumps, the fuel injection line fitting may fracture if the aluminum nut attaching the lines is tightened in excess of the required tightening specifications. The potential for damage to the fuel lines by interference with the water hose clamp exists. As with any type of fuel system leakage, the possibility of a vehicle engine fire exists.

B) CHRONOLOGY OF EVENTS WHICH LED TO DETERMINATION OF A SAFETY DEFECT:

The Ferrari Factory informed us of the following:

This condition was determined to exist after laboratory tests have shown that the repetitive tightening, without following the Ferrari's prescribed tightening torque, will provoke stresses that lead to damage.

C) MEASURES TO BE TAKEN TO REPAIR VEHICLE:

Remove the 6 fuel injection lines that have the nut made of aluminum and replace with the new fuel injection lines that have the nut made of steel, as well as checking and adjusting the positioning of the water hose clamp. The operation is free-of charge for the vehicle owner, and will require approximately 2.2 hours.

ESTIMATED INITIATION OF CORRECTIVE ACTION:

March-98

98V-057 (04)

**DRAFT**

March 1998

SBV-057 (05)

Dear Ferrari Customer:

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act.

Ferrari S.p.A., the manufacturer of Ferrari automobiles, has determined that a defect exists in certain 1995, 1996, and 1997 model year F355 Ferrari vehicles fitted with single fuel pumps.

On Ferrari vehicles, 1995 through 1998 F355 models with assembly numbers between 19318 and 23604, which have been fitted with single fuel pumps, the fuel injection line fitting may fracture if the aluminum nut attaching the lines is tightened in excess of the required tightening specifications. The potential for damage to the fuel lines by interference with the water hose clamp exists. As with any type of fuel system leakage, the possibility of a vehicle engine fire exists.

Since your car is among those affected by the above condition, we kindly ask you to contact any Ferrari Authorized Dealer immediately in order to arrange for the dealer to perform the required modification.

The corrective action for the above listed repair will be performed free of charge to you and will require approximately 2.2 hours to complete. Please plan, however, to leave your vehicle with the dealer all day to allow the dealer some flexibility for scheduling your repairs.

By the time you receive this letter, the Authorized Ferrari Dealer will have been supplied with the instructions and parts to perform the repair. If the Dealer fails or is unable to make the necessary repairs free of charge within a reasonable time, you should inform the National Headquarters Office of Ferrari North America, Inc.

250 Sylvan Avenue  
Englewood Cliffs, NJ 07632  
(701) 816-2651 (National Technical Office)

Although we urge you to immediately call the number indicated above, if the vehicle is not repaired free of charge to you or within a reasonable time, you may also contact the Administrator of the National Traffic Safety Administration in Washington, D.C. 10590 or call the Auto Safety Hot line at 800-424-9393 nationally and (202) 366-0123 for Washington, D.C. area residents.

We urge you to comply with this notice promptly and we apologize for any inconvenience this may cause you.

Best Regards,

William S. Story  
Directory of Technical Services

**DRAFT**

March 1998

98V-057 (08)

Dear Ferrari Dealer:

Ferrari S.p.A., the manufacturer of Ferrari automobiles, has determined that a defect exists in certain 1995, 1996, 1997 and 1998 model year F355 Ferrari vehicles fitted with single fuel pumps.

On Ferrari vehicles, 1995 through 1997 F355 models with assembly numbers between 19318 and 23604, which have been fitted with single fuel pumps, the fuel injection line fitting may fracture if the aluminum nut attaching the lines is tightened in excess of the required tightening specifications. The potential for damage to the fuel lines by interference with the water hose clamp exists. As with any type of fuel system leakage, the possibility of a vehicle engine fire exists.

The remedy consists of replacing the 6 fuel injection lines which have nuts made of aluminum with new fuel injection lines which have nuts made of steel in accordance with the attached technical instructions, as well as checking and adjusting the positioning of the water hose clamp.

The corrective action will require approximately 2.2 hours.

We have accordingly sent notices to all owners of the affected vehicles advising them of this problem and requesting that they contact any Authorized Ferrari Dealer for the repairs, as per the attached notification letter.

Upon transmittal of the repair under the normal warranty system, we will of course reimburse you for the labor and applicable parts necessary to carry out this campaign.

Obviously, if you have any of the affected vehicles in your stock, you must not sell them until you have performed the necessary repairs. If you have already sold any vehicles with the chassis numbers specified in the enclosed instructions and have not yet sent in the retail sales cards, please do so at once so we may notify these owners.

Thank you for your cooperation

Best Regards,

William S. Story  
Directory of Technical Services

WSS:cc

**RECALL CAMPAIGN NO. 158****INTRODUCTION :** Fuel Injection Lines and Hose Clamp (single fuel pump vehicles)

98/- 057 (07)

**SUBJECT :** Recall Campaign No. 158  
Ferrari F355 Fuel Injection Lines and Hose Clamp**VEHICLES :** Ferrari F 355 1995 through 1997 vehicles with a vehicle identification number between 101818 and 106742 fitted with single fuel pumps.**CONDITION :** The aluminum nuts fitted on the fuel injection lines will fracture if the nut is tightened in excess of the required torque specified by Ferrari. The potential for the hose clamp to interfere with the fuel lines exists.  
Should such a condition occur, the result would be leakage of fuel from the fractured nut.**REMEDY :** Replacement of the six fuel injection lines which have nuts made of aluminum with new fuel injection lines, which have nuts made of steel. Adjust positioning of the hose clamp.**PARTS :** The new lines are identified by the following part numbers -

<u>Old Part Number</u>	<u>New Part Number</u>	<u>Quantity</u>	<u>Description</u>
165564	171342	1	Fuel pump-filter delivery pipe
165566	171346	1	Fuel return pipe
165533	171344	2	Fuel delivery pipes to pressure regulator
165534	171345	2	Fuel pipes from distributor to block
113910	113910	3	Gasket for fuel pipes
-	140727	6	Clip
-	127816	1	O-Ring

**COST :**  
A) An initial supply of new fuel lines will be sent to your dealership. Your Parts Account will be charged accordingly.  
B) Additional fuel lines can be ordered from the Ferrari North America Parts Department in Englewood Cliffs, New Jersey.**LABOR :**

MEDEA Recall No.	1580	Defect Code	01
Component Code	1471	Cost Code	24
Labor Operation	14710	Time	2.2 Hours

**REIMBURSEMENT** Upon receipt of claim via MEDEA

## INSTRUCTIONS FOR FUEL LINE REPLACEMENT AND HOSE CLAMP INSPECTION

A: Preliminary : The replacement fuel lines and hose clamps are supplied as spare parts by the part numbers listed on the previous page.


B: Procedure for installation

### WARNING NO SMOKING

**HIGHLY FLAMMABLE MATERIAL. KEEP AWAY FROM SPARKS OR OPEN FLAMES. PROVIDE ADEQUATE VENTILATION. FUEL, WHEN SATURATED ON CLOTHING, WILL CAUSE SKIN IRRITATION. PROCEED ACCORDINGLY.**

**NOTE: BE SURE TO UTILIZE PROPER EQUIPMENT FOR SAFE TRANSFER OF FUEL FROM CAR TO APPROVED FUEL CONTAINER.**

**DO NOT PERFORM THIS PROCEDURE ON A WARM ENGINE.**



- 1) Disconnect battery (main switch).
- 2) Cover rear fenders with fender covers.
- 3) Remove fuel tank fill cap to release pressure from the fuel tank.




- 4) Lift vehicle using a suitable hoist and remove center under panel
- 5) Remove the LH rear wheel
- 6) Remove LH inner fender panel
- 7) Drain the fuel from the tank into an approved fuel container

**NOTE: PRIOR TO DISCONNECTING FUEL LINES, CARE MUST BE TAKEN TO CATCH FUEL WHEN THE LINES ARE REMOVED.**

**REPLACE THE COPPER WASHERS ON THE NEW FUEL LINES WITH THE SUPPLIED WASHERS AND LUBRICATE WITH WHITE GREASE OR VASELINE THE PIPES TO BE CONNECTED TO THE FUEL DISTRIBUTION BLOCK.**

- 8) Disconnect the fuel delivery line "1" from the fuel pump
- 9) Disconnect the fuel return line "2" from the fuel pump
- 10) Disconnect the fuel delivery line "1" from the fuel filter
- 11) Disconnect the fuel return line "2" from the fuel distribution block
- 12) Remove the fuel lines "1" and "2" from the vehicle noting their original routing positions
- 13) Install the new fuel delivery "1" and return "2" lines tightening to a torque of 25 Nm (18.44 lb. ft.) angling them so that they do not rub against the fuel tank
- 14) Disconnect the RH fuel delivery line "3" from the fuel distribution block
- 15) Disconnect the RH fuel line "4" from the fuel distribution block
- 16) Disconnect the RH fuel delivery line "3" from the fuel injection rail
- 17) Disconnect the RH fuel line "4" from the fuel pressure regulator
- 18) Remove the RH fuel lines from the vehicle noting their original routing positions
- 19) Install the new RH fuel delivery "3" and return "4" lines tightening to a torque of 25 Nm (18.44 lb. ft.) with a crowfoot wrench.
- 20) Repeat items 14 - 19 for the LH side



98V-057 (10)

- 21) Rotate the clamp (p.n. 12177090) which connects the water hose to the coolant pipe as per the above diagram. Turn and tighten the clamp so there is enough clearance as to not interfere and damage the fuel line 171344 (old p.n. 165533)
- 22) Check all fuel lines making sure that there is no interference between them. It is mandatory to create enough clearance between each fuel line by coupling them together using the supplied clips p.n. 140727
- 23) Using the clamp p.n. 140727, connect the upper fuel filter line to the lower fuel filter line "1" 171342 at a point below the fuel filter

**NOTE: FOR IDENTIFICATION PURPOSES, PLEASE PAINT THE END OF FUEL LINE (P.N. 171344) WITH RED PAINT**

- 24) Transfer the fuel back into the fuel tank replacing the fuel cap
- 25) Reconnect battery
- 26) Start the engine and check for fuel leaks at all unions and repair if necessary
- 27) Install the inner fender panel
- 28) Install the rear wheel tightening the wheel bolts to a torque of 100 Nm (72 lb. ft.)
- 29) Install the center under panel





98V-057

# RECALL CAMPAIGN

REF. NO. 158  
FUEL INJECTION LINES AND CLAMP  
(SINGLE FUEL PUMP VEHICLES)  
F 355

RECEIVED  
MARCH 1998

## MARCH 1998

READ, INITIAL  
AND PASS ON »

Service Manager	Parts Manager	Service Writer	Technician				Warranty Clerk



March 1998

Dear Ferrari Dealer :

Ferrari S.p.A., the manufacturer of Ferrari automobiles, has determined that a defect exists in certain 1995, 1996, 1997 and 1998 model year F355 Ferrari vehicles fitted with single fuel pumps.

On Ferrari vehicles, 1995 through 1997 F355 models with assembly numbers between 19318 and 23604, which have been fitted with single fuel pumps, the fuel injection line fitting may fracture if the aluminum nut attaching the lines is tightened in excess of the required tightening specifications. The potential for damage to the fuel lines by interference with the water hose clamp exists. As with any type of fuel system leakage, the possibility of a vehicle engine fire exists.

The remedy consists of replacing the 6 fuel injection lines which have nuts made of aluminum with new fuel injection lines which have nuts made of steel in accordance with the attached technical instructions, as well as checking and adjusting the positioning of the water hose clamp.

The corrective action will require approximately 2.2 hours.

We have accordingly sent notices to all owners of the affected vehicles advising them of this problem and requesting that they contact any Authorized Ferrari Dealer for the repairs, as per the attached notification letter.

Upon transmittal of the repair under the normal warranty system, we will of course reimburse you for the labor and applicable parts necessary to carry out this campaign.

Obviously, if you have any of the affected vehicles in your stock, you must not sell them until you have performed the necessary repairs. If you have already sold any vehicles with the chassis numbers specified in the enclosed instructions and have not yet sent in the retail sales cards, please do so at once so we may notify these owners.

Thank you for your cooperation

Best Regards,

A handwritten signature in black ink, appearing to read "William S. Story", is written over a horizontal line.

William S. Story  
Directory of Technical Services

WSS:cc



## RECALL CAMPAIGN NO. 158

**INTRODUCTION :** Fuel Injection Lines and Hose Clamp (Single Fuel Pump Vehicles)

**SUBJECT :** Recall Campaign No. 158  
Ferrari F355 Fuel Injection Lines and Hose Clamp

**VEHICLES :** Ferrari F 355 1995 through 1997 vehicles with a vehicle identification number between 101818 and 106742 fitted with single fuel pumps.

**CONDITION :** The aluminum nuts fitted on the fuel injection lines will fracture if the nut is tightened in excess of the required torque specified by Ferrari. The potential for the hose clamp to interfere with the fuel lines exists.  
Should such a condition occur, the result would be leakage of fuel from the fractured nut.

**REMEDY :** Replacement of the six fuel injection lines which have nuts made of aluminum with new fuel injection lines, which have nuts made of steel. Adjust positioning of the hose clamp.

**PARTS :** The new lines are identified by the following part numbers :

<u>Old Part Number</u>	<u>New Part Number</u>	<u>Quantity</u>	<u>Description</u>
165564	171342	1	Fuel pump-filter delivery pipe
165566	171346	1	Fuel return pipe
165533	171344	2	Fuel delivery pipes to pressure regulator
165534	171345	2	Fuel pipes from distributor to block
113910	113910	3	Gasket for fuel pipes
-	140727	6	Clip
-	127816	1	O-Ring

**COST :** A) An initial supply of new fuel lines will be sent to your dealership.  
Your Parts Account will be charged accordingly.  
B) Additional fuel lines can be ordered from the Ferrari North America Parts Department in Englewood Cliffs, New Jersey.

<b>LABOR :</b>	MEDEA Recall No.	1580	Defect Code	01
	Component Code	1471	Cost Code	24
	Labor Operation	14710	Time	2.2 Hours

**REIMBURSEMENT** Upon receipt of claim via MEDEA



## INSTRUCTIONS FOR FUEL LINE REPLACEMENT AND HOSE CLAMP INSPECTION

A: Preliminary: The replacement fuel lines and hose clamps are supplied as spare parts by the part numbers listed on the previous page.


B: Procedure for installation

**WARNING**      **NO SMOKING**

**HIGHLY FLAMMABLE MATERIAL. KEEP AWAY FROM SPARKS OR OPEN FLAMES. PROVIDE ADEQUATE VENTILATION. FUEL, WHEN SATURATED ON CLOTHING, WILL CAUSE SKIN IRRITATION. PROCEED ACCORDINGLY.**

**NOTE:**      **BE SURE TO UTILIZE PROPER EQUIPMENT FOR SAFE TRANSFER OF FUEL FROM CAR TO APPROVED FUEL CONTAINER.**

**DO NOT PERFORM THIS PROCEDURE ON A WARM ENGINE.**



- 1) Disconnect battery (main switch).
- 2) Cover rear fenders with fender covers.
- 3) Remove fuel tank fill cap to release pressure from the fuel tank.




- 4) Lift vehicle using a suitable hoist and remove center under panel
- 5) Remove the LH rear wheel
- 6) Remove LH inner fender panel
- 7) Drain the fuel from the tank into an approved fuel container

**NOTE: PRIOR TO DISCONNECTING FUEL LINES, CARE MUST BE TAKEN TO CATCH FUEL WHEN THE LINES ARE REMOVED.**

**REPLACE THE COPPER WASHERS ON THE NEW FUEL LINES WITH THE SUPPLIED WASHERS AND LUBRICATE WITH WHITE GREASE OR VASELINE THE PIPES TO BE CONNECTED TO THE FUEL DISTRIBUTION BLOCK.**

- 8) Disconnect the fuel delivery line "1" from the fuel pump
- 9) Disconnect the fuel return line "2" from the fuel pump
- 10) Disconnect the fuel delivery line "1" from the fuel filter
- 11) Disconnect the fuel return line "2" from the fuel distribution block
- 12) Remove the fuel lines "1" and "2" from the vehicle noting their original routing positions
- 13) Install the new fuel delivery "1" and return "2" lines tightening to a torque of 25 Nm (18.44 lb. ft.) angling them so that they do not rub against the fuel tank
- 14) Disconnect the RH fuel delivery line "3" from the fuel distribution block
- 15) Disconnect the RH fuel line "4" from the fuel distribution block
- 16) Disconnect the RH fuel delivery line "3" from the fuel injection rail
- 17) Disconnect the RH fuel line "4" from the fuel pressure regulator
- 18) Remove the RH fuel lines from the vehicle noting their original routing positions
- 19) Install the new RH fuel delivery "3" and return "4" lines tightening to a torque of 25 Nm (18.44 lb. ft.) with a crowfoot wrench.
- 20) Repeat items 14 - 19 for the LH side





- 21) Rotate the clamp (p.n. 12177090) which connects the water hose to the coolant pipe as per the above diagram. Turn and tighten the clamp so there is enough clearance as to not interfere and damage the fuel line 171344 (old p.n. 165533)
- 22) Check all fuel lines making sure that there is no interference between them. It is mandatory to create enough clearance between each fuel line by coupling them together using the supplied clips p.n. 140727
- 23) Using the clamp p.n. 140727, connect the upper fuel filter line to the lower fuel filter line "1" 171342 at a point below the fuel filter

**NOTE: FOR IDENTIFICATION PURPOSES, PLEASE PAINT THE END OF FUEL LINE (P.N. 171344) WITH RED PAINT**

- 24) Transfer the fuel back into the fuel tank replacing the fuel cap
- 25) Reconnect battery
- 26) Start the engine and check for fuel leaks at all unions and repair if necessary
- 27) Install the inner fender panel
- 28) Install the rear wheel tightening the wheel bolts to a torque of 100 Nm (72 lb. ft.).
- 29) Install the center under panel



Recall Campaign No. 158  
Serial Number List

<u>Serial Number</u>	<u>Assembly Number</u>	<u>Model Description</u>
101818	20111	F355 GTS
101819	20418	F355 GTS
101831	20421	F355 GTS
101832	20427	F355 GTS
101844	20436	F355 GTS
101845	20476	F355 GTS
101857	20504	F355 GTS
101883	19489	F355 SPIDER USA MY 95
102459	19345	F355 BERLINETTA USA MY95
102460	19318	F355 BERLINETTA USA MY95
102467	19332	F355 BERLINETTA USA MY95
102468	19327	F355 BERLINETTA USA MY95
102469	19366	F355 BERLINETTA USA MY95
102470	19465	F355 BERLINETTA USA MY95
102555	19483	F355 BERLINETTA USA MY95
102567	19495	F355 BERLINETTA USA MY95
102578	19502	F355 BERLINETTA CDN MY95
102579	19498	F355 BERLINETTA USA MY95
102591	19531	F355 BERLINETTA USA MY95
102615	19535	F355 BERLINETTA USA MY95
102623	19509	F355 SPIDER USA MY 95
102629	19553	F355 BERLINETTA USA MY95
102642	19574	F355 BERLINETTA USA MY95
102649	19518	F355 SPIDER USA MY 95
102655	19582	F355 BERLINETTA USA MY95
102663	19533	F355 SPIDER USA MY 95
102669	19603	F355 BERLINETTA CDN MY95
102670	19594	F355 BERLINETTA USA MY95
102680	19593	F355 BERLINETTA USA MY95
102681	19599	F355 BERLINETTA USA MY95
102689	19549	F355 SPIDER USA MY 95
102696	19606	F355 BERLINETTA USA MY95
102703	19555	F355 SPIDER USA MY 95
102708	19609	F355 BERLINETTA USA MY95
102716	19557	F355 SPIDER USA MY 95
102717	19585	F355 SPIDER USA MY 95
102722	19637	F355 BERLINETTA USA MY95
102729	19622	F355 SPIDER USA MY 95
102735	19661	F355 BERLINETTA USA MY95
102742	19589	F355 SPIDER USA MY 95
102743	19638	F355 SPIDER USA MY 95
102748	19670	F355 BERLINETTA USA MY95
102755	19635	F355 SPIDER USA MY 95
102758	19651	F355 SPIDER USA MY 95
102764	19705	F355 BERLINETTA USA MY95
102768	19660	F355 SPIDER USA MY 95



102777	19771	F355 BERLINETTA USA MY95
102781	19682	F355 SPIDER USA MY 95
102782	19708	F355 SPIDER USA MY 95
102786	19685	F355 SPIDER USA MY 95
102767	19773	F355 SPIDER USA MY 95
102788	19777	F355 SPIDER USA MY 95
102878	19781	F355 SPIDER USA MY 95
102879	19792	F355 SPIDER USA MY 95
102883	19786	F355 BERLINETTA USA MY95
102884	19789	F355 BERLINETTA CDN MY95
102891	19817	F355 SPIDER USA MY 95
102892	19784	F355 SPIDER USA MY 95
102904	19807	F355 SPIDER USA MY 95
102905	19794	F355 SPIDER USA MY 95
102910	19823	F355 BERLINETTA USA MY95
102916	19815	F355 SPIDER USA MY 95
102917	19835	F355 SPIDER USA MY 95
102918	19827	F355 SPIDER USA MY 95
102929	19821	F355 SPIDER USA MY 95
102930	19819	F355 SPIDER USA MY 95
102935	19891	F355 BERLINETTA USA MY95
102936	19855	F355 BERLINETTA CDN MY95
102940	19831	F355 SPIDER USA MY 95
102941	19833	F355 SPIDER USA MY 95
102942	19849	F355 SPIDER USA MY 95
102949	19857	F355 BERLINETTA USA MY95
102954	19853	F355 SPIDER USA MY 95
102955	19852	F355 SPIDER USA MY 95
102956	19859	F355 SPIDER USA MY 95
102963	19862	F355 BERLINETTA USA MY95
102969	19865	F355 SPIDER USA MY 95
102970	19863	F355 SPIDER USA MY 95
102980	19953	F355 SPIDER USA MY 95
102981	19867	F355 SPIDER USA MY 95
102982	19874	F355 SPIDER USA MY 95
102988	19811	F355 BERLINETTA USA MY95
102989	19894	F355 BERLINETTA CDN MY95
102993	19869	F355 SPIDER USA MY 95
102994	19887	F355 SPIDER USA MY 95
102995	19893	F355 SPIDER USA MY 95
103006	19901	F355 SPIDER USA MY 95
103007	19889	F355 SPIDER USA MY 95
103008	19909	F355 SPIDER USA MY 95
103015	19928	F355 BERLINETTA USA MY95
103020	19903	F355 SPIDER USA MY 95
103021	19913	F355 SPIDER USA MY 95
103027	19949	F355 BERLINETTA USA MY95
103031	19915	F355 SPIDER USA MY 95
103032	19938	F355 SPIDER USA MY 95
103038	19906	F355 BERLINETTA USA MY95
103043	19941	F355 SPIDER USA MY 95



103044	19945	F355 SPIDER USA MY 95
103045	19978	F355 SPIDER USA MY 95
103058	19981	F355 SPIDER USA MY 95
103059	19983	F355 SPIDER USA MY 95
103060	19989	F355 SPIDER USA MY 95
103064	19975	F355 BERLINETTA USA MY95
103069	19967	F355 SPIDER USA MY 95
103070	19972	F355 SPIDER USA MY 95
103071	20002	F355 SPIDER USA MY 95
103072	19986	F355 SPIDER USA MY 95
103082	20010	F355 SP
103083	20006	F355 SP
103084	20012	F355 SP
103085	20035	F355 SP
103090	20068	F355 BERLINETTA
103094	20047	F355 SP
103095	20031	F355 SP
103104	20057	F355 SP
103105	20070	F355 SP
103108	20072	F355 SP
103109	20086	F355 SP
103116	20023	F355 BERLINETTA
103127	20077	F355 SP
103128	20107	F355 SP
103141	20090	F355 SP
103142	20115	F355 SP
103152	20179	F355 SP
103153	20147	F355 SP
103154	20060	F355 BERLINETTA
103167	20117	F355 SP
103168	20119	F355 SP
103180	20122	F355 SP
103181	20140	F355 SP
103182	20142	F355 SP
103194	20155	F355 SP
103195	20148	F355 SP
103196	20112	F355 BERLINETTA
103221	20157	F355 SP
103222	20171	F355 SP
103223	20173	F355 SP
103224	20159	F355 BERLINETTA
103237	20974	F355 B USA MY/96
103246	20187	F355 SP
103249	20182	F355 SP
103251	21047	F355 B USA MY/96
103263	20207	F355 SP
103264	20212	F355 SP
103265	20225	F355 SP
103266	20286	F355 BERLINETTA
103279	20232	F355 SP
103280	20215	F355 SP



103294	20218	F355 SP
103295	20228	F355 SP
103296	20230	F355 SP
103302	20643	F355 BERLINETTA
103314	20221	F355 SP
103315	20234	F355 SP
103316	20210	F355 BERLINETTA
103329	20256	F355 SP
103330	20260	F355 SP
103331	20258	F355 SP
103342	20276	F355 SP
103343	20279	F355 SP
103344	20659	F355 BERLINETTA
103356	20266	F355 SP
103357	20302	F355 SP
103358	20283	F355 SP
103369	20304	F355 SP
103370	20310	F355 SP
103371	20715	F355 BERLINETTA
103383	20308	F355 SP
103384	20337	F355 SP
103385	20312	F355 SP
103399	20314	F355 SP
103400	20319	F355 SP
103401	20773	F355 BERLINETTA
103414	20325	F355 SP
103415	20333	F355 SP
103416	20328	F355 SP
103430	20335	F355 SP
103431	20355	F355 SP
103471	20383	F355 SP
103472	20379	F355 SP
103473	20381	F355 SP
103474	20401	F355 SP
103476	20375	F355 SP
103485	20369	F355 SP
103486	20371	F355 SP
103487	20373	F355 SP
103514	20407	F355 SP
103515	20388	F355 SP
103525	20415	F355 SP
103526	20405	F355 SP
103527	20403	F355 SP
103538	20409	F355 SP
103539	20433	F355 SP
103550	20425	F355 SP
103561	20429	F355 SP
103562	20475	F355 SP
103574	20459	F355 SP
103582	20490	F355 BERLINETTA
103584	20457	F355 SP



103585	20466	F355 SP
103598	20478	F355 SP
103609	20489	F355 SP
103610	20487	F355 SP
103621	20501	F355 SP
103622	20485	F355 SP
103633	20528	F355 SP
103634	20530	F355 SP
103647	20513	F355 SP
103656	20566	F355 GTS
103659	20536	F355 SP
103660	20541	F355 SP
103672	20558	F355 SP
103673	20568	F355 SP
103680	20733	F355 BERLINETTA
103684	20597	F355 GTS
103686	20637	F355 SP
103696	20623	F355 GTS
103698	20603	F355 SP
103699	20574	F355 SP
103705	20811	F355 BERLINETTA
103711	20577	F355 SP
103712	20580	F355 SP
103725	20622	F355 SP
103728	20598	F355 SP
103731	20780	F355 BERLINETTA
103732	20767	F355 BERLINETTA
103735	20663	F355 BERLINETTA
103739	20613	F355 SP
103747	20764	F355 BERLINETTA
103750	20652	F355 GTS
103752	20605	F355 SP
103753	20615	F355 SP
103765	20619	F355 SP
103766	20640	F355 SP
103767	20645	F355 SP
103768	20647	F355 SP
103769	20650	F355 SP
103770	20654	F355 SP
103771	20670	F355 SP
103772	20684	F355 SP
103773	20714	F355 SP
103785	20758	F355 SP
103788	20673	F355 SP
103802	20726	F355 SP
103803	20688	F355 SP
103804	20717	F355 SP
103815	20712	F355 SP
103816	20735	F355 SP
103831	20752	F355 SP
103832	20761	F355 SP



103839	20762	F355 GTS
103843	20786	F355 SP
103849	20760	F355 BERLINETTA
103854	20756	F355 GTS
103856	20766	F355 SP
103866	20770	F355 SP
103872	20822	F355 BERLINETTA
103873	20786	F355 BERLINETTA
103877	20782	F355 SP
103883	20843	F355 BERLINETTA
103887	20816	F355 GTS
103889	20789	F355 SP
103890	20841	F355 SP
103896	20795	F355 BERLINETTA
103901	20793	F355 GTS
103904	20850	F355 SP
103906	20813	F355 BERLINETTA
103908	20819	F355 BERLINETTA
103915	20864	F355 SP
103916	20862	F355 SP
103923	20825	F355 BERLINETTA
103927	20838	F355 GTS
103930	20839	F355 SP
103933	20868	F355 BERLINETTA
103934	20846	F355 BERLINETTA
103941	20856	F355 SP
103942	20870	F355 SP
103947	20921	F355 BERLINETTA
103952	20872	F355 GTS
103955	20875	F355 SP
103959	20896	F355 BERLINETTA
103960	20860	F355 BERLINETTA
103965	20891	F355 GTS
103967	20894	F355 SP
103973	20908	F355 BERLINETTA
103974	20902	F355 BERLINETTA
103982	20900	F355 SP
103986	20912	F355 BERLINETTA
103987	20910	F355 BERLINETTA
103990	20906	F355 GTS
103995	20914	F355 SP
104005	20918	F355 GTS
104008	20945	F355 SP
104009	20950	F355 SP
104016	20972	F355 GTS
104019	20933	F355 SP
104027	20935	F355 BERLINETTA
104033	20948	F355 SP
104034	20947	F355 SP
104039	20969	F355 BERLINETTA
104043	20962	F355 GTS



104046	20976	F355 SP
104054	20988	F355 BERLINETTA
104055	20984	F355 BERLINETTA
104059	20986	F355 SP
104060	20978	F355 SP
104061	20993	F355 SP
104073	20991	F355 SP
104074	21012	F355 SP
104075	21026	F355 SP
104087	21013	F355 SP
104088	21038	F355 SP
104089	21025	F355 SP
104090	21014	F355 SP
104096	20980	F355 BERLINETTA
104112	21028	F355 BERLINETTA
104182	21160	F355 BERLINETTA
104202	21116	F355 SP
104210	21188	F355 BERLINETTA
104250	21145	F355 BERLINETTA
104281	21175	F355 BERLINETTA
104286	21101	F355 SP
104310	21110	F355 SP
104311	21258	F355 SP
104321	21282	F355 BERLINETTA
104326	21135	F355 SP
104336	21186	F355 GTS
104337	21139	F355 SP
104338	21157	F355 SP
104349	21232	F355 BERLINETTA
104353	21162	F355 SP
104357	21164	F355 SP
104358	21194	F355 SP
104365	21240	F 355 SPIDER
104366	21271	F355 GTS USA MY/96
104369	21209	F355 SP
104370	21206	F355 SP
104374	21283	F 355 SPIDER
104375	21300	F355 GTS USA MY/96
104377	21269	F355 BERLINETTA
104379	21439	F355 B USA MY/96
104384	21204	F355 SP
104388	21416	F 355 SPIDER
104389	21365	F355 GTS USA MY/96
104390	21289	F355 BERLINETTA
104392	21466	F355 B USA MY/96
104395	21874	F355 SP CA MY96
104398	21216	F355 SP
104399	21227	F355 SP
104402	21293	F 355 SPIDER
104403	21382	F355 GTS USA MY/96
104404	21314	F355 BERLINETTA





104406	21487	F355 B USA MY/96
104413	21315	F 355 SPIDER
104414	21451	F355 GTS USA MY/96
104415	21296	F355 BERLINETTA
104418	21482	F355 B USA MY/96
104425	21362	F 355 SPIDER
104426	21327	F355 BERLINETTA
104428	21530	F355 B USA MY/96
104440	21333	F 355 SPIDER
104441	21353	F355 BERLINETTA
104443	21580	F355 B USA MY/96
104452	21361	F 355 SPIDER
104453	21338	F355 BERLINETTA
104455	21614	F355 B USA MY/96
104464	21386	F 355 SPIDER
104465	21371	F355 BERLINETTA
104467	21612	F355 B USA MY/96
104477	21359	F 355 SPIDER
104478	21408	F355 BERLINETTA
104489	21389	F 355 SPIDER
104490	21390	F355 BERLINETTA
104503	21415	F 355 SPIDER
104504	21430	F355 BERLINETTA
104516	21444	F355 BERLINETTA
104517	21423	F 355 SPIDER
104531	21418	F 355 SPIDER
104544	21352	F 355 B CA MY96
104545	21436	F 355 SPIDER
104559	21370	F 355 B CA MY96
104560	21899	F355 SP CA MY96
104561	21457	F355 GTS USA MY/96
104562	21455	F 355 SPIDER
104563	21508	F 355 SPIDER
104564	21480	F 355 SPIDER
104565	21503	F355 GTS USA MY/96
104566	21474	F 355 SPIDER
104567	21494	F 355 SPIDER
104568	21514	F 355 SPIDER
104740	21516	F 355 SPIDER
104741	21536	F 355 SPIDER
104742	21555	F 355 SPIDER
104751	21542	F 355 SPIDER
104752	21549	F 355 SPIDER
104753	21568	F 355 SPIDER
104765	21569	F 355 SPIDER
104766	21581	F 355 SPIDER
104767	21579	F 355 SPIDER
104778	21597	F 355 SPIDER
104779	21590	F 355 SPIDER
104780	21603	F 355 SPIDER
104792	21606	F 355 SPIDER



104806	21528	F 355 SPIDER
104807	21635	F 355 SPIDER
104808	21645	F 355 SPIDER
104816	21652	F355 B USA MY/96
104817	21695	F355 B USA MY/96
104818	21708	F355 B USA MY/96
104820	21655	F 355 SPIDER
104821	21659	F 355 SPIDER
104822	21663	F 355 SPIDER
104823	21520	F355 GTS USA MY/96
104829	21770	F355 B USA MY/96
104830	21788	F355 B USA MY/96
104834	21671	F 355 SPIDER
104835	21677	F 355 SPIDER
104848	21682	F 355 SPIDER
104849	21692	F 355 SPIDER
104851	21684	F 355 SPIDER
104852	21704	F 355 SPIDER
104858	21554	F355 GTS USA MY/96
104859	21584	F355 GTS USA MY/96
104860	21609	F355 GTS USA MY/96
104861	21636	F355 GTS USA MY/96
104862	21679	F355 GTS USA MY/96
104871	21690	F355 GTS USA MY/96
104872	21734	F355 GTS USA MY/96
104873	21710	F 355 SPIDER
104874	21723	F 355 SPIDER
104875	21716	F 355 SPIDER
104883	21728	F355 GTS USA MY/96
104884	21753	F355 GTS USA MY/96
104885	21725	F 355 SPIDER
104886	21744	F 355 SPIDER
104887	21747	F 355 SPIDER
104888	21736	F 355 SPIDER
104889	21751	F 355 SPIDER
104896	21762	F355 GTS USA MY/96
104897	21795	F355 GTS USA MY/96
104898	21772	F 355 SPIDER
104899	21774	F 355 SPIDER
104900	21782	F 355 SPIDER
104906	21785	F 355 SPIDER
104907	21802	F 355 SPIDER
104908	21793	F 355 SPIDER
104918	21807	F355 GTS USA MY/96
104920	21818	F 355 SPIDER
104924	21862	F355 B USA MY/96
104932	21850	F 355 SPIDER
104933	21837	F 355 SPIDER
104938	22036	F355 GTS USA MY/96
104953	21846	F 355 SPIDER
104954	21869	F 355 SPIDER



104964	22043	F355 GTS USA MY/96
104967	21860	F 355 SPIDER
104972	21909	F355 B USA MY/96
104979	21865	F 355 SPIDER
104980	21883	F 355 SPIDER
104991	22047	F355 GTS USA MY/96
104996	21886	F 355 SPIDER
105004	22049	F355 GTS USA MY/96
105008	21892	F 355 SPIDER
105022	21922	F 355 SPIDER
105023	21902	F 355 SPIDER
105029	22076	F355 B USA MY/96
105033	22062	F355 GTS USA MY/96
105036	21906	F 355 SPIDER
105051	21942	F 355 SPIDER
105052	21927	F 355 SPIDER
105056	22024	F355 B USA MY/96
105060	22067	F355 GTS USA MY/96
105064	21952	F 355 SPIDER
105079	21939	F 355 SPIDER
105080	21915	F355 SP CA MY96
105090	22064	F355 GTS USA MY/96
105093	21963	F 355 SPIDER
105094	21980	F 355 SPIDER
105105	22073	F355 GTS USA MY/96
105109	22008	F 355 SPIDER
105115	22187	F355 B USA MY/96
105123	22017	F 355 SPIDER
105124	22005	F 355 SPIDER
105133	22082	F355 GTS USA MY/96
105138	21969	F 355 SPIDER
105147	22106	F355 GTS USA MY/96
105151	22011	F 355 SPIDER
105159	22091	F355 GTS USA MY/96
105163	22021	F 355 SPIDER
105164	22027	F 355 SPIDER
105175	22167	F355 GTS USA MY/96
105178	22038	F 355 SPIDER
105184	22242	F355 B USA MY/96
105189	22284	F 355 SPIDER
105190	22240	F 355 SPIDER
105204	21947	F355 SP CA MY96
105207	21871	F 355 GTS CA MY96
105217	21957	F355 SP CA MY96
105222	21877	F 355 GTS CA MY96
105237	21919	F 355 GTS CA MY96
105245	22279	F355 B USA MY/96
105246	22516	F355 B USA MY/96
105253	22195	F355 GTS USA MY/96
105262	22199	F355 GTS USA MY/96
105263	22176	F355 GTS USA MY/96



105275	22223	F355 GTS USA MY/96
105276	22203	F355 GTS USA MY/96
105277	22215	F355 GTS USA MY/96
105290	22206	F355 GTS USA MY/96
105291	22225	F355 GTS USA MY/96
105292	22257	F355 GTS USA MY/96
105307	22217	F355 SP CA MY96
105310	22233	F355 SP CA MY96
105311	22248	F355 SP CA MY96
105315	22907	F355 GTS USA MY/96
105316	22876	F355 GTS USA MY/96
105321	22266	F355 SP CA MY96
105328	22253	F 355 GTS CA MY96
105329	22312	F 355 GTS CA MY96
105333	22250	F 355 SPIDER
105339	22503	F355 B USA MY/96
105340	22524	F355 B USA MY/96
105347	22282	F 355 SPIDER
105365	22286	F 355 SPIDER
105368	22260	F 355 SPIDER
105369	22296	F 355 SPIDER
105378	22307	F 355 SPIDER
105379	22314	F 355 SPIDER
105380	22320	F 355 SPIDER
105392	22324	F 355 SPIDER
105393	22298	F 355 SPIDER
105394	22345	F 355 SPIDER
105405	22326	F 355 SPIDER
105406	22339	F 355 SPIDER
105407	22330	F 355 SPIDER
105419	22336	F 355 SPIDER
105420	22343	F 355 SPIDER
105421	22358	F 355 SPIDER
105432	22362	F 355 SPIDER
105433	22369	F 355 SPIDER
105434	22389	F 355 SPIDER
105445	22372	F 355 SPIDER
105446	22391	F 355 SPIDER
105447	22400	F 355 SPIDER
105457	22405	F 355 SPIDER
105458	22383	F 355 SPIDER
105459	22374	F 355 SPIDER
105507	22407	F 355 SPIDER
105508	22413	F 355 SPIDER
105509	22506	F 355 SPIDER
105523	22453	F 355 SPIDER
105525	22462	F355 SP CA MY96
105526	22519	F 355 SPIDER
105527	22534	F 355 SPIDER
105533	22479	F355 SP CA MY96
105534	22476	F355 SP CA MY96



105535	22484	F355 SP CA MY96
105536	22489	F355 SP CA MY96
105537	22498	F355 SP CA MY96
105547	22530	F355 B USA MY/96
105553	22577	F 355 SPIDER
105559	22532	F355 B USA MY/96
105565	22544	F 355 SPIDER
105566	22553	F 355 SPIDER
105573	22572	F355 B USA MY/96
105581	22546	F 355 SPIDER
105582	22548	F 355 SPIDER
105586	22631	F355 B USA MY/96
105592	22567	F 355 SPIDER
105593	22574	F 355 SPIDER
105595	22566	F355 B USA MY/96
105596	22593	F355 B USA MY/96
105604	22579	F 355 SPIDER
105606	22641	F355 B USA MY/96
105612	22584	F 355 SPIDER
105614	22588	F 355 SPIDER
105623	22604	F 355 SPIDER
105624	22597	F 355 SPIDER
105635	22600	F 355 SPIDER
105636	22615	F 355 SPIDER
105637	22621	F 355 SPIDER
105647	22607	F 355 SPIDER
105648	22623	F 355 SPIDER
105649	22633	F 355 SPIDER
105659	22644	F 355 SPIDER
105660	22650	F 355 SPIDER
105661	22657	F 355 SPIDER
105672	22661	F 355 SPIDER
105673	22665	F 355 SPIDER
105674	22670	F 355 SPIDER
105686	22691	F 355 SPIDER
105687	22689	F 355 SPIDER
105698	22701	F 355 SPIDER
105699	22683	F 355 SPIDER
105700	22704	F 355 SPIDER
105712	22685	F 355 SPIDER
105713	22674	F 355 SPIDER
105724	22710	F 355 SPIDER
105725	22715	F 355 SPIDER
105726	22724	F 355 SPIDER
105738	22744	F 355 SPIDER
105739	22719	F 355 SPIDER
105740	22730	F 355 SPIDER
105750	22735	F 355 SPIDER
105751	22738	F 355 SPIDFR
105752	22748	F 355 SPIDER
105852	22807	F355 B USA MY/96



105856	22897	F355 GTS USA MY/96
105857	22810	F 355 GTS CA MY96
105862	22819	F355 SP CA MY96
105874	22831	F355 B USA MY/96
105884	22821	F 355 GTS CA MY96
105890	22838	F355 SP CA MY96
105903	22863	F355 B USA MY/96
105908	22826	F 355 GTS CA MY96
105916	22853	F355 SP CA MY96
105922	22873	F355 B USA MY/96
105933	22849	F 355 GTS CA MY96
105937	22913	F 355 SPIDER
105938	22889	F355 SP CA MY96
105950	22884	F355 B USA MY/96
105963	22903	F 355 SPIDER
105964	22867	F355 SP CA MY96
105977	22895	F355 B USA MY/96
105984	23030	F 355 SPIDER
105994	22920	F355 B USA MY/96
106005	22943	F 355 SPIDER
106011	22939	F355 B USA MY/96
106017	22955	F 355 SPIDER
106113	22949	F 355 SPIDER
106114	23004	F 355 SPIDER
106115	22973	F 355 SPIDER
106119	23022	F 355 SPIDER
106121	22980	F 355 SPIDER
106122	22993	F 355 SPIDER
106126	23008	F 355 SPIDER
106127	23020	F 355 SPIDER
106128	23062	F 355 SPIDER
106159	23066	F 355 SPIDER
106169	23082	F 355 SPIDER
106172	23099	F355 B USA MY/96
106179	23090	F 355 SPIDER
106180	23094	F 355 SPIDER
106185	23106	F355 B USA MY/96
106188	23120	F355 GTS USA MY/96
106189	23121	F355 GTS AUSTRALIA
106192	23109	F 355 SPIDER
106197	23129	F355 B USA MY/96
106201	23123	F355 GTS USA MY/96
106205	23126	F 355 SPIDER
106206	23130	F355 SP CA MY96
106211	23159	F355 B USA MY/96
106214	23141	F355 GTS USA MY/96
106218	23167	F355 SP CA MY96
106222	23139	F355 B USA MY/96
106226	23157	F355 GTS USA MY/96
106230	23146	F 355 SPIDER
106231	23152	F355 SP CA MY96



106235	23164	F355 B USA MY/96
106238	23171	F355 GTS USA MY/96
106242	23176	F355 SP CA MY96
106248	23181	F355 B USA MY/96
106251	23204	F355 GTS USA MY/96
106252	23173	F 355 GTS CA MY96
106257	23191	F 355 SPIDER
106262	23199	F355 GTS USA MY/96
106263	23201	F 355 GTS CA MY96
106267	23185	F 355 SPIDER
106275	23218	F 355 GTS CA MY96
106396	23234	F355 SPIDER USA MY97
106397	23212	F355 SPIDER USA MY97
106398	23215	F355 SPIDER USA MY97
106401	23222	F355 SPIDER USA MY97
106402	23226	F355 SPIDER USA MY97
106403	23231	F355 SPIDER USA MY97
106406	23239	F355 SPIDER USA MY97
106407	23245	F355 SPIDER USA MY97
106408	23248	F355 SPIDER USA MY97
106409	23251	F355 SPIDER USA MY97
106416	23255	F355 SPIDER USA MY97
106417	23261	F355 SPIDER USA MY97
106418	23266	F355 SPIDER USA MY97
106419	23263	F355 SPIDER USA MY97
106421	23281	F355 SPIDER USA MY97
106422	23275	F355 SPIDER USA MY97
106423	23273	F355 SPIDER USA MY97
106424	23270	F355 SPIDER USA MY97
106427	23279	F355 SPIDER USA MY97
106428	23287	F355 SPIDER USA MY97
106429	23291	F355 SPIDER USA MY97
106431	23295	F355 SPIDER USA MY97
106432	23300	F355 SPIDER USA MY97
106433	23307	F355 SPIDER USA MY97
106434	23310	F355 SPIDER USA MY97
106436	23314	F355 SPIDER USA MY97
106437	23316	F355 SPIDER USA MY97
106438	23328	F355 SPIDER USA MY97
106441	23319	F355 SPIDER USA MY97
106442	23324	F355 SPIDER USA MY97
106443	23337	F355 SPIDER USA MY97
106444	23335	F355 SPIDER USA MY97
106446	23340	F355 SPIDER USA MY97
106447	23346	F355 SPIDER USA MY97
106448	23343	F355 SPIDER USA MY97
106449	23353	F355 SPIDER USA MY97
106466	23358	F355 SPIDER USA MY97
106467	23360	F355 SPIDER USA MY97
106466	23372	F355 SPIDER USA MY97
106482	23364	F355 SPIDER USA MY97



106483	23377	F355 SPIDER USA MY97
106484	23419	F355 SPIDER USA MY97
106498	23379	F355 SPIDER USA MY97
106501	23383	F355 SPIDER USA MY97
106502	23386	F355 SPIDER USA MY97
106518	23403	F355 SPIDER USA MY97
106521	23398	F355 SPIDER USA MY97
106532	23415	F355 SPIDER USA MY97
106534	23433	F355 SPIDER USA MY97
106536	23410	F355 SPIDER USA MY97
106537	23417	F355 SPIDER USA MY97
106548	23435	F355 GTS CANADA MY97
106552	23428	F355 SPIDER USA MY97
106553	23423	F355 SPIDER USA MY97
106567	23438	F355 B USA MY97
106568	23458	F355 SPIDER USA MY97
106569	23440	F355 SPIDER USA MY97
106571	23443	F355 SPIDER USA MY97
106581	23446	F355 B USA MY97
106583	23445	F355 SPIDER USA MY97
106584	23450	F355 SPIDER USA MY97
106588	23462	F355 B USA MY97
106589	23466	F355 B USA MY97
106597	23529	F355 B USA MY97
106598	23538	F355 B USA MY97
106602	23453	F355 SPIDER USA MY97
106604	23483	F355 B USA MY97
106606	23486	F355 B USA MY97
106607	23474	F355 B USA MY97
106618	23491	F355 B USA MY97
106619	23488	F355 B USA MY97
106621	23496	F355 B USA MY97
106638	23511	F355 GTS CANADA MY97
106639	23494	F355 SPIDER USA MY97
106641	23499	F355 SPIDER CANADA MY97
106647	23508	F355 B USA MY97
106653	23555	F355 GTS USA MY97
106656	23472	F355 SPIDER USA MY97
106661	23540	F355 B USA MY97
106667	23576	F355 GTS USA MY97
106671	23520	F355 SPIDER USA MY97
106678	23550	F355 B USA MY97
106682	23604	F355 GTS USA MY97
106686	23523	F355 SPIDER USA MY97
106699	23544	F355 SPIDER USA MY97
106706	23571	F355 B USA MY97
106713	23565	F355 SPIDER USA MY97
106719	23584	F355 B USA MY97
106721	23587	F355 B USA MY97
106727	23573	F355 SPIDER USA MY97
106741	23598	F355 SPIDER USA MY97





March 1998

Dear Ferrari Customer:

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act.

Ferrari S.p.A., the manufacturer of Ferrari automobiles, has determined that a defect exists in certain 1995, 1996, and 1997 model year F355 Ferrari vehicles fitted with single fuel pumps.

On Ferrari vehicles, 1995 through 1998 F355 models with assembly numbers between 19318 and 23604, which have been fitted with single fuel pumps, the fuel injection line fitting may fracture if the aluminum nut attaching the lines is tightened in excess of the required tightening specifications. The potential for damage to the fuel lines by interference with the water hose clamp exists. As with any type of fuel system leakage, the possibility of a vehicle engine fire exists.

Since your car is among those affected by the above condition, we kindly ask you to contact any Ferrari Authorized Dealer immediately in order to arrange for the dealer to perform the required modification.

The corrective action for the above listed repair will be performed free of charge to you and will require approximately 2.2 hours to complete. Please plan, however, to leave your vehicle with the dealer all day to allow the dealer some flexibility for scheduling your repairs.

By the time you receive this letter, the Authorized Ferrari Dealer will have been supplied with the instructions and parts to perform the repair. If the Dealer fails or is unable to make the necessary repairs free of charge within a reasonable time, you should inform the National Headquarters Office of Ferrari North America, Inc.

250 Sylvan Avenue  
Englewood Cliffs, NJ 07632  
(201) 816-2651 (National Technical Office)

Although we urge you to immediately call the number indicated above, if the vehicle is not repaired free of charge to you or within a reasonable time, you may also contact the Administrator of the National Traffic Safety Administration in Washington, D.C. 10590 or call the Auto Safety Hot line at 800-424-9393 nationally and (202) 366-0123 for Washington, D.C. area residents.

We urge you to comply with this notice promptly and we apologize for any inconvenience this may cause you.

Best Regards,

William S. Story  
Directory of Technical Services

# Ferrari

Ferrari North America, Inc.

March 24, 1998

Via U.S. Mail

Ms. Kathleen DeMeter , Director  
Office of Defects Investigation  
National Highway Traffic Safety Administration  
400 Seventh Street, SW  
Washington, D.C. 20590



Ref: Recall 158 and 159

Dear Ms. DeMeter:

For your records, enclosed please find a the Ferrari North America Inc. booklets for Recalls 158 and 159, Fuel Injection Lines (Single Fuel Pump Vehicles) and Water Hose Clamp, which were sent to all of the dealers in our network.

Best regards,

Concetta Ciaccio  
Executive Assistant

Enclosure

Q:\RECALL\158\159-BOOK