

SSM 47192	Some 2017 F-Super Duty vehicles equipped with a 6.7L diesel engine may exhibit an exhaust odor in the vehicle cabin. This may be due to a leak at the turbocharger inlet clamps. Performing a pressurized smoke test on the exhaust system will aid in locating the source of a leak. While performing the smoke test, the use of a small mirror can help identify leaks underneath the clamps. Refer to the Powertrain Control/Emissions Diagnosis (PC/ED) Manual Pinpoint Test KA, Step KA3. Note that the turbo charger is not a contributing factor in the exhaust leak issue.
--------------	--