

**4.2 INCH INFORMATION DISPLAY - UP AND DOWN ARROWS  
INOPERATIVE ON THE STEERING WHEEL AND OR THE FCDIM - BUILT  
ON OR BEFORE 11/18/2013**

**TSB 14-0159**

**FORD:**

2013 F-150

**ISSUE**

Some 2013 F-150 vehicles built on or before 11/18/2013 and equipped with a 4.2 inch information display may exhibit a concern of the up and down arrows intermittently inoperative on the steering wheel and or the front control display interface module (FCDIM).

**ACTION**

Reprogram the FCDIM to the latest calibration using IDS release 91.04 and higher. Please ensure that you are connected to the internet when entering module programming to guarantee that you will receive the latest updates. Calibration files may also be obtained at [www.motorcraftservice.com](http://www.motorcraftservice.com).

<b>OPERATION</b>	<b>DESCRIPTION</b>	<b>TIME</b>
140159A	2013 F-150: Reprogram The FCDIM And Clear Codes (Do Not Use With Any Other Labor Operations)	0.3 Hr.

**WARRANTY STATUS:**

Eligible Under Provisions Of New Vehicle Limited Warranty Coverage

Warranty/ESP coverage limits/policies/prior approvals are not altered by a TSB. Warranty/ESP coverage limits are determined by the identified causal part and verified using the OASIS part coverage tool.

**DEALER CODING**

<b>BASIC PART NO.</b>	<b>CONDITION CODE</b>
10D885	42

NOTE: The information contained in Technical Service Bulletins is intended for use by trained, professional technicians with the knowledge, tools, and equipment to do the job properly and safely. It informs these technicians of conditions that may occur on some vehicles, or provides information that could assist in proper vehicle service. The procedures should not be performed by "do-it-yourselfers". Do not assume that a condition described affects your car or truck. Contact a Ford, Lincoln, or Mercury dealership to determine whether the bulletin applies to your vehicle. Warranty Policy and Extended Service Plan documentation determine Warranty and/or Extended Service Plan coverage unless stated otherwise in the TSB article. The information in this Technical Service Bulletin (TSB) was current at the time of printing. Ford Motor Company reserves the right to supercede this information with updates. The most recent information is available through Ford Motor Company's on-line technical resources.