Technical Bulletin



Condition

Camshaft Chain Tensioner(s) or Camshaft Adjuster(s), Rattle or Knocking Noise

15 06 01 Oct. 24, 2006 2012988

Model(s)	Year	Eng. Code	Trans. Code	VIN Range From	VIN Range To
All	1999 - 2005	1.8T, 2.8L, 4.2L	All	All	All

Technical Background

The camshaft adjustment is hydraulically actuated and controlled by the engine oil pressure.

If the vehicle has been sitting, with the engine turned off for a period of time, the oil accumulation inside the camshaft adjusters partially bleeds off and the oil flows back into the oil sump.

To ensure an efficient camshaft adjustment after an engine cold start, the oil pressure inside the camshaft adjusters must be built up as quickly as possible.

During this time a slight rattle or knocking noise may be audible.

This noise is normal at engine start and will last until the oil pressure is fully reinstated.

Production Solution

No production change required.

Technical Bulletin



Service

DO NOT replace the Camshaft Tensioner(s) or Camshaft Adjuster(s) for the noise concern as described above.

i Tip:

Replacing the Camshaft Tensioner(s) or Camshaft Adjuster(s) will not eliminate this noise.

Warranty

Information only.

Required Parts and Tools

No Special Tools required.

No Special Parts required. Always see ETKA for the latest part(s) information.

Page 2 of 2

All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Volkswagen of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.