



NUMBER: 18-003-10

GROUP: Vehicle Performance

DATE: January 15, 2010

This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of Chrysler LLC.

THIS BULLETIN SUPERSEDES SERVICE BULLETIN 18-016-09, DATED MAY 15, 2009, WHICH SHOULD BE REMOVED FROM YOUR FILES. ALL REVISIONS ARE HIGHLIGHTED WITH **ASTERISKS**** AND INCLUDE THE ADDITION OF VEHICLES BUILT UP TO APRIL 29, 2009.**

SUBJECT:

MIL Illumination Or Stored Diagnostic Trouble Code (DTC) for: P1004 Or P2016 Or P2017

OVERVIEW:

This bulletin involves replacing the Short Runner Valve (SRV), SRV connector, wiring pigtail, and adding a new stud for a tie strap.

MODELS:

2009	(DS)	Ram Truck (1500)
2009	(DH)	Ram Trucks (1500/2500)
2009	(DC)	Cab Chassis (3500)

NOTE: This bulletin applies to 2009 vehicles equipped with a 5.7L engine (Sales code EZC, EZD or EZH) built before **April 29, 2009 (MDH0429XX)****.**

SYMPTOM/CONDITION:

The customers may experience a MIL illumination for P1004 Or P2016 Or P2017. Further investigation by the Technician may find that the following DTC's are active or stored:

1. P1004 - Short Runner Valve Control Performance
2. P2016 - Intake Manifold Runner Position Sensor Circuit Low
3. P2017 - Intake Manifold Runner Position Sensor Circuit High

The SRV wiring takeout was not long enough and caused excessive wear on the SRV, and SRV wiring connector resulting in a loose connection.

DIAGNOSIS:

Using a Scan Tool (StarSCAN®) with the appropriate Diagnostic Procedures available in TechCONNECT, verify all engine systems are functioning as designed. If DTC's are present other than the ones listed above record them on the repair order and repair as necessary before proceeding further with this bulletin.

If the above condition is present, perform the Repair Procedure.

PARTS REQUIRED:

Qty.	Part No.	Description
1	68064996AA	Kit, Wiring Kit includes; 1 SRV wiring connector. 4 18 gauge wires with terminals, 1 stud mount tie-strap, 4 splice crimps and 4 wire shrink wraps
1	J3693058	Tie-strap 24 tie-straps in one package
1	6509376AA	Stud
1	53022137AF	Valve, Short Runner
1	68065586AA	Tape, High Abrasion One roll of tape will service 6 vehicles
1	04318031	Adhesive, Lock and Seal - Mopar

REPAIR PROCEDURE:

1. Remove the intake manifold. Follow the detailed service procedures available in DealerCONNECT/TechCONNECT, Refer To Group 9 - Engine - 5.7L > Manifolds > Manifold Intake Removal Procedures.
2. Cover intake ports.
3. Remove the short runner valve.
4. Discard one of the short runner valve bolts.
5. Replace the short runner valve with p/n 53022137AF. Use SRV stud supplied with kit p/n 68064996AA in the hole located on right side (passenger side on LHD vehicles) of intake manifold and 2 remaining bolts on other locations. Torque bolts to 5 Nm (44 in-lb).
6. Measure 50mm (1.9 inches) down from end of SRV connector and cut off the SRV connector.
7. Using the 18 gauge wires from wiring kit p/n 68064996AA splice in SRV wires. Follow the detailed wiring procedures available in DealerCONNECT/TechCONNECT, Refer To the Wiring Tab > 8W-01 - Wiring Diagram Information > Wire > Standard Procedure.

NOTE: Be sure to use the shrink wrap on wires after splicing.

8. Install new SRV Connector from wiring kit p/n 68064996AA. Follow the detailed wiring procedures available in DealerCONNECT/TechCONNECT, Refer To the Wiring Tab > 8W-01 - Wiring Diagram Information > Connector > Installation Procedure.
9. Wrap all exposed wiring with high abrasion tape p/n 68065586AA.
10. Measure 100 mm (3.9 inches) from end of new SRV connector and install stud mount tie-strap on wire.
11. Measure 150 mm (5.9 inches) from stud mount tie-strap toward main harness and tie-strap new SRV takeout to main harness.
12. Connect stud mount tie-strap to stud.

- 13. Apply Mopar Lock and Seal Adhesive p/n 04318031 on intake manifold bolts.
- 14. Install the intake manifold. Follow the detailed service procedures available in DealerCONNECT/TechCONNECT, Refer To Group 9 - Engine - 5.7L > Manifolds > Manifold Intake Installation Procedures.

CAUTION: When installing intake manifold care should be taken to not pinch the SRV wiring under intake.

- 15. Using the StarSCAN® erase all DTC.

POLICY:

Reimbursable within the provisions of the warranty.

TIME ALLOWANCE:

Labor Operation No:	Description	Amount
14-40-14-91	Replace ,SRV Valve, Stud, Wiring Connector. (B)	1.8 Hrs.

FAILURE CODE:

ZZ	Service Action
----	----------------