



**NUMBER:** 18-063-16 REV. A

**GROUP:** Vehicle Performance

**DATE:** August 24, 2016

*This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of FCA US LLC.*

**THIS BULLETIN SUPERSEDES SERVICE BULLETIN 18-063-16, DATED JUNE 04, 2016, WHICH SHOULD BE REMOVED FROM YOUR FILES. ALL REVISIONS ARE HIGHLIGHTED WITH **\*\*ASTERISKS\*\*** AND INCLUDE AN UPDATED SYMPTOM/CONDITION LIST AND LOP.**

**FOR HELP WITH USING wiTECH FOR ECU FLASH REPROGRAMMING, CLICK ON THE APPLICATION'S "HELP" TAB.**

**THE wiTECH SOFTWARE IS REQUIRED TO BE AT THE LATEST RELEASE BEFORE PERFORMING THIS PROCEDURE.**

***SUBJECT:***

Flash: Powertrain Diagnostic And System Enhancements

***OVERVIEW:***

This bulletin involves reprogramming the Powertrain Control Module (PCM) with the latest available software.

***MODELS:***

2015 (BU) Jeep Renegade

**NOTE: This bulletin applies to vehicles equipped with a 2.4L I4 Multiair Engine (Sales Code ED6) and a 948TE Transmission (Sales Code DFH).**

***SYMPTOM/CONDITION:***

Customers may experience a Malfunction Indicator Lamp (MIL) illumination. Upon further investigation the technician may find the following Diagnostic Trouble Codes (DTCs) stored in the PCM memory:

- **\*\*P1066 - Cylinder 1 Oil Supply Solenoid Valve Switch Off Time Out Of Range.**
- P1068 - Cylinder 2 Oil Supply Solenoid Valve Switch Off Time Out Of Range.
- P106A - Cylinder 3 Oil Supply Solenoid Valve Switch Off Time Out Of Range.
- P106C - Cylinder 4 Oil Supply Solenoid Valve Switch Off Time Out Of Range.
- U1424 - Implausible Engine Torque Signal Received.\*\*
- P050D - Cold Start Rough Idle.
- P0101 - Mass Air Flow Sensor "A" Circuit Performance.
- P0335 - Crankshaft Position Sensor Circuit.
- P1CEC - Variable Valve Solenoid Valve Cold Start Closing Position 1 Timing Over-Retard.

- P1CED - Variable Valve Timing Solenoid Valve Cold Start Closing Position Timing Over-Advance.
- P1607 - PCM Internal Shutdown Timer Rationality.
- P0128 - Thermostat Rationality.
- P2610 - PCM Internal Engine Off Timer Performance.
- P0440 - General EVAP System Failure.
- P0441 - EVAP Purge System Performance.
- P0456 - EVAP System Small Leak.
- P0455 - EVAP System Large Leak.
- P0452 - EVAP Pressure Switch Stuck Closed.
- P0133 - O2 Sensor 1/1 Slow Response.
- C0501 - Wheel Speed Signal Left Front Rationality.
- C0507 - Wheel Speed Signal Right Front Rationality.
- C050D - Wheel Speed Signal Left Rear Rationality.
- C0513 - Wheel Speed Signal Right Rear Rationality.
- U0428-00 - Implausible Data Received From Steering Angle Sensor Module.
- C0061 - Lateral Acceleration Sensor.
- U0402 - Implausible Data Received From TCM.
- P0133 - O2 Sensor 1/1 Slow Response.
- P050D - Cold Start Rough Idle.

In addition, customers may experience one or more of the following concerns:

- RPM flare at cold start.
- Less than desired idle performance.
- Cold engine RPM surge with gear engagement.

### ***DIAGNOSIS:***

Using a Scan Tool (wiTECH) with the appropriate Diagnostic Procedures available in TechCONNECT, verify all related systems are functioning as designed. If DTCs or symptom conditions, other than the ones listed above are present, record the issues on the repair order and repair as necessary before proceeding further with this bulletin.

If the customer describes the symptom/condition listed above or if the technician finds the DTC, perform the Repair Procedure.

### ***REPAIR PROCEDURE:***

**NOTE: The Transmission Control Module (TCM) must be updated to the latest available software at the conclusion of this repair procedure. Refer to all applicable published service bulletins for detailed repair procedures and labor times regarding updating the TCM software.**

**NOTE: Install a battery charger to ensure battery voltage does not drop below 13.2 volts. Do not allow the charging voltage to climb above 13.5 volts during the flash process.**

**NOTE: If this flash process is interrupted/aborted, the flash should be restarted.**

1. Reprogram the PCM with the latest software. Detailed instructions for flashing control modules using the wiTECH Diagnostic Application are available by selecting the application's "HELP" tab.

2. Clear all DTCs that may have been set in any module due to reprogramming. The wiTECH application will automatically present all DTCs after the flash and allow them to be cleared.
3. Verify the TCM is programmed with the latest available software. Refer to all applicable published service bulletins for detailed repair procedures and labor times regarding updating the TCM software.

**POLICY:**

Reimbursable within the provisions of the warranty.

**TIME ALLOWANCE:**

Labor Operation No:	Description	Skill Category	Amount
**18-19-06-MT	Module, Powertrain Control (PCM) - Reprogram (0 - Introduction)	1 - Engine Repair and Performance	0.2 Hrs**

**NOTE: The expected completion time for the flash download portion of this procedure is approximately 6 minutes. Actual flash download times may be affected by vehicle connection and network capabilities.**

**FAILURE CODE:**

**The dealer must choose which failure code to use. If the customer came in with an issue and if the dealer finds a software update to correct that issue, use failure code CC, for all other use failure code RF.**

- If the customer's concern matches the SYMPTOM/CONDITION identified in the Service Bulletin, failure code CC is to be used.
- If an available flash is completed while addressing a different customer concern, failure code RF is to be used.

CC	Customer Concern
RF	Routine Flash