



NUMBER: 18-082-15

GROUP: Vehicle Performance

DATE: November 05, 2015

This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of FCA US LLC.

THIS BULLETIN SUPERSEDES SERVICE BULLETIN 18-063-14 DATED NOVEMBER 18, 2014, WHICH SHOULD BE REMOVED FROM YOUR FILES. ALL REVISIONS ARE HIGHLIGHTED WITH **ASTERISKS**** AND INCLUDES ADDITIONAL SYMPTOM/CONDITIONS FOR 2015 WD & WK, AFFECTED VEHICLES, NEW FAILURE CODES AND NEW LOP.**

HELP USING THE wiTECH DIAGNOSTIC APPLICATION FOR FLASHING AN ECU IS AVAILABLE BY SELECTING “HELP” THEN “HELP CONTENTS” AT THE TOP OF THE wiTECH DIAGNOSTIC APPLICATION WINDOW.

THE wiTECH SOFTWARE IS REQUIRED TO BE AT THE LATEST RELEASE BEFORE PERFORMING THIS PROCEDURE.

SUBJECT:

Flash: Powertrain Diagnostic And System Improvements

OVERVIEW:

This bulletin involves selectively erasing and reprogramming the Powertrain Control Module (PCM) with new software.

MODELS:

2015	(WK)	Jeep Grand Cherokee
2014- **2015**	(WD)	Dodge Durango

NOTE: **This bulletin applies to 2015 WD and 2015 WK vehicles within the following markets/countries: LATAM, EMEA or APAC******

NOTE: This bulletin applies to **2014 WD **** vehicles equipped with a 5.7L engine (Sales Code EZH) built on or before October 9, 2014 (MDH 1009XX).**

NOTE: **This bulletin applies to 2015 WK vehicles equipped with a 3.0L engine or 5.7L engine (Sales Code EHD and EZH).****

NOTE: This bulletin applies to **2015 WD **** vehicles equipped with a 5.7L engine (Sales Code EZH).********

SYMPTOM/CONDITION:

The following powertrain system improvements/enhancements are included in this software release. These symptoms are broken down by vehicle.

****2015 WK 3.0L engine (Sales Code EHD)**

- Enhancements to remote engine start.**

2015 WK **5.7L engine (Sales Code EZH)**

- Enhancements to improve a slight lag or hesitation during Multi Displacement System (MDS) mode transitions.
- Enhancements to improve a slight drop in engine RPM when the vehicle is shifted to reverse or drive within 3 seconds of a cold start.
- Malfunction Indicator Lamp (MIL) illuminated with Diagnostic Trouble Code (DTC) U0140-00 - Lost Communication with Body Control Module (BCM).

2014 WD **5.7L engine (Sales Code EZH)**

- Enhancements to improve a slight drop in engine RPM when the vehicle is shifted to reverse or drive within 3 seconds of a cold start.

****2015 WD 5.7L engine (Sales Code EZH)**

- Enhancements to remote engine start.**

DIAGNOSIS:

Using a Scan Tool (wiTECH) with the appropriate Diagnostic Procedures available in TechCONNECT, verify all engine systems are functioning as designed. If DTCs or symptom conditions, other than the ones listed above are present, record the issues on the repair order and repair as necessary before proceeding further with this bulletin.

If the customer describes the symptom/condition or if the technician finds the DTC listed above, perform the Repair Procedure.

REPAIR PROCEDURE:

NOTE: Install a battery charger to ensure battery voltage does not drop below 13.2 volts. Do not allow the charging voltage to climb above 13.5 volts during the flash process.

NOTE: If this flash process is interrupted/aborted, the flash should be restarted.

1. Reprogram the PCM with the latest software. Detailed instructions for flashing control modules using the wiTECH Diagnostic Application are available by selecting the "HELP" tab on the upper portion of the wiTECH window, then "HELP CONTENTS." This will open the Welcome to wiTECH Help screen where help topics can be selected.

NOTE: After PCM reprogramming, the following must be performed:

2. Clear any DTCs that may have been set in any modules due to reprogramming. The wiTECH application will automatically present all DTCs after the flash and allows them to be cleared.

POLICY:

Reimbursable within the provisions of the warranty.

TIME ALLOWANCE:

Labor Operation No:	Description	Skill Category	Amount
18-19-06-FG	Module, Powertrain Control (PCM) - Reprogram (0 - Introduction)	8 - Engine Performance	0.2 Hrs.

NOTE: The expected completion time for the flash download portion of this procedure is approximately **2**** minutes. Actual flash download times may be affected by vehicle connection and network capabilities.**

****FAILURE CODE:**

The dealer must choose which failure code to use. If the customer came in with an issue and the dealer found updated software to correct that issue, use failure code CC, for all other use failure code RF.

- If the customer's concern matches the SYMPTOM/CONDITION identified in the Service Bulletin, failure code CC is to be used.
- If an available flash is completed while addressing a different customer concern, failure code RF is to be used.

CC	Customer Concern
RF	Routine Flash**