



TECHNICAL SERVICE BULLETIN

3.3L - Illuminated Malfunction Indicator Lamp (MIL) With Diagnostic Trouble Code (DTC) P0111 - Built On Or Before 26-Apr-2018

18-2148

22 May 2018

Model:

Ford
2018 F-150

Issue: Some 2018 F-150 vehicles equipped with a 3.3L engine may exhibit an illuminated MIL with DTC P0111.

Action: Follow the Service Procedure steps to correct the condition.

Warranty Status: Eligible Under Provisions Of New Vehicle Limited Warranty Coverage And Emissions Warranty Coverage Warranty/ESP coverage limits/policies/prior approvals are not altered by a TSB. Warranty/ESP coverage limits are determined by the identified causal part and verified using the OASIS part coverage tool.

Labor Times

| Description | Operation No. | Time |
|--|---------------|----------|
| 2018 F150 3.3L: Retrieve DTCs And Reprogram The PCM (Do Not Use With Any Other Labor Operations) | 182148A | 0.3 Hrs. |

Repair/Claim Coding

| | |
|-----------------|---------|
| Causal Part: | RECALEM |
| Condition Code: | 04 |

Service Procedure

- Connect the appropriate Ford scan tool or equivalent and retrieve DTCs. Is P0111 stored in the powertrain control module (PCM)?
 - Yes – proceed to Step 2.
 - No - this article does not apply. Refer to the Powertrain Control/Emissions Diagnosis (PC/ED) Manual for normal diagnostics.
- Reprogram the PCM to the latest calibration using the appropriate Ford scan tool release 109.03 or higher. Make sure you are connected to the internet when entering module programming to obtain the latest updates.
 - NOTE: ADVISE THE CUSTOMER THAT THIS VEHICLE IS EQUIPPED WITH AN ADAPTIVE TRANSMISSION SHIFT STRATEGY WHICH ALLOWS THE VEHICLE'S COMPUTER TO LEARN THE TRANSMISSION'S UNIQUE PARAMETERS AND IMPROVE SHIFT QUALITY. WHEN THE ADAPTIVE STRATEGY IS RESET, THE COMPUTER WILL BEGIN A RE-LEARNING PROCESS. THIS RE-LEARNING PROCESS MAY RESULT IN FIRMER THAN NORMAL UPSHIFTS AND DOWNSHIFTS FOR SEVERAL DAYS.

© 2018 Ford Motor Company

All rights reserved.

NOTE: The information in Technical Service Bulletins is intended for use by trained, professional technicians with the knowledge, tools, and equipment to do the job properly and safely. It informs these technicians of conditions that may occur on some vehicles, or provides information that could assist in proper vehicle service. The procedures should not be performed by "do-it-yourselfers". Do not assume that a condition described affects your car or truck. Contact a Ford or Lincoln dealership to determine whether the Bulletin applies to your vehicle. Warranty Policy and Extended Service Plan documentation determine Warranty and/or Extended Service Plan coverage unless stated otherwise in the TSB article. The information in this Technical Service Bulletin (TSB) was current at the time of printing. Ford Motor Company reserves the right to supersede this information with updates. The most recent information is available through Ford Motor Company's on-line technical resources.