



NUMBER: 21-032-18 REV. A

GROUP: 21 - Transmission and Transfer Case

DATE: June 29, 2018

This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of FCA US LLC.

NOTE: **2.4L KL equipped with Adaptive Cruise Control (NHZ) or Selec-Speed™ Control (BNK) with SYMPTOMS/CONDITIONS related to this Bulletin are included within Recall U63. Please verify the Powertrain Control Module (PCM) and Transmission Control Module (TCM) part numbers are at latest level by following the U63 service action.**

THIS BULLETIN SUPERSEDES SERVICE BULLETIN 21-032-18, DATED JUNE 20, 2018, WHICH SHOULD BE REMOVED FROM YOUR FILES. ALL REVISIONS ARE HIGHLIGHTED WITH **ASTERISKS AND INCLUDES UPDATING NOTES FOR THE 2.4L ENGINE STATEMENT, AND ADDING SALES CODE IN VEHICLE INFORMATION.**

THIS SERVICE BULLETIN IS ALSO BEING RELEASED AS RAPID RESPONSE TRANSMITTAL (RRT) 17-108. ALL APPLICABLE SOLD AND UN-SOLD RRT VIN's HAVE BEEN LOADED. TO VERIFY THAT THIS RRT SERVICE ACTION IS APPLICABLE TO THE VEHICLE, USE VIP OR PERFORM A VIN SEARCH IN TECHCONNECT. ALL REPAIRS ARE REIMBURSABLE WITHIN THE PROVISIONS OF WARRANTY.

FOR HELP WITH USING wiTECH FOR ECU FLASH REPROGRAMMING, CLICK ON THE APPLICATION'S "HELP" TAB.

SUBJECT:

Flash: Transmission Diagnostic and Shift Enhancements

OVERVIEW:

This bulletin involves reprogramming the Transmission Control Module (TCM) with the latest available software.

MODELS:

2016 (KL) Jeep Cherokee

NOTE: This bulletin applies to vehicles within the following markets/countries: NAFTA, EMEA, LATAM and APAC.

NOTE: This bulletin applies to vehicles equipped with a 2.4L Engine (Sales Codes ED6 or ED8), a 9 Speed Automatic Transmission (Sales Codes DFH or DFJ) and **without Adaptive Cruise Control (Sales Code NHZ) or Selec-Speed™ Control (Sales Code BNK).**

NOTE: This bulletin applies to vehicles equipped with a 3.2L Engine (Sales Code EHK) and a 9 Speed Automatic Transmission (Sales Codes DFH or DFJ).

SYMPTOM/CONDITION:**2.4L Engine (Sales Codes ED6 or ED8)**

Customers may experience a Malfunction Indicator Lamp (MIL) illumination. Upon further investigation the technician may find that one of the following DTCs have been set:

- P0887-00 - TCM Power Control Circuit High.
- U1412 - Implausible Vehicle Speed Signal Received - Signal Compare Failure.
- U0001-00 - High Speed CAN Communication Bus.
- P0810 - Clutch Position Control Error.
- P061B - Internal Control Module Torque Calculation Performance.

In addition, some customers may experience one or more of the following conditions:

- A harsh 4-5 upshift.
- 5-4 coast down transmission shift quality enhancement.
- Less than desired low speed driveability and response to accelerator pedal input.
- Less than desired transmission shift quality.
- Transmission is slow to upshift after releasing the accelerator pedal.

3.2L Engine (Sales Code EHK)

Some customers may experience a MIL illumination. Upon further investigation, a technician may find one of the following DTCs have been set:

- P0887-00 - TCM Power Control Circuit High.
- U1412 - Implausible Vehicle Speed Signal Received - Signal Compare Failure.
- U0001-00 - CAN C Bus.
- P061B - Internal Control Module Torque Calculation Performance.

Additionally, some customers may experience one or more of the following conditions:

- 5-4 coast down transmission shift quality enhancement.
- Less than desired low speed drivability and response to accelerator pedal input.
- Less than desired transmission shift quality.
- Less than optimal transmission shift timing, driving up and down hills.
- Less than desired Engine Stop/Start re-engagement or smoothness.
- Transmission is slow to upshift after releasing the accelerator pedal.

DIAGNOSIS:

Using a Scan Tool (wiTECH) with the appropriate Diagnostic Procedures available in TechCONNECT, verify all related systems are functioning as designed. If DTCs or symptom conditions, other than the ones listed above are present, record the issues on the repair order and repair as necessary before proceeding further with this bulletin.

If a customer's VIN is listed in VIP or your RRT VIN list, perform the repair. For all other customers that describe the symptom/condition listed above or if the technician finds the DTC, perform the Repair Procedure.

REPAIR PROCEDURE:

NOTE: **If the vehicle is equipped with a 2.4L engine, the dealer needs to check for an open recall. Refer to all applicable published recall for detailed repair procedures and labor times regarding updating the PCM and TCM software.**

NOTE: The Powertrain Control Module (PCM) must be updated to the latest available software at the conclusion of this repair procedure. Refer to all applicable published service bulletins for detailed repair procedures and labor times regarding updating the PCM software.

NOTE: Install a battery charger to ensure battery voltage does not drop below 13.2 volts. Do not allow the charging voltage to climb above 13.5 volts during the flash process.

NOTE: If this flash process is interrupted/aborted, the flash should be restarted.

1. Reprogram the TCM with the latest software. Detailed instructions for flashing control modules using the wiTECH Diagnostic Application are available by selecting the application's "HELP" tab.

NOTE: If the software is up to date use inspection LOP (18-19-05-HC) to close an active RRT.

2. Clear any DTCs that may have been set in any module due to reprogramming. The wiTECH application will automatically present all DTCs after the flash and allows them to be cleared.
3. Verify the PCM is programmed with the latest available software. Refer to all applicable published service bulletins for detailed repair procedures and labor times regarding updating the PCM software.

POLICY:

Reimbursable within the provisions of the warranty.

TIME ALLOWANCE:

Labor Operation No:	Description	Skill Category	Amount
18-19-05-HC	Module, Transmission Control (TCM) - Inspect (0 - Introduction)	2 - Automatic Transmission	0.2 Hrs.
18-19-05-HD	Module, Transmission Control (TCM) - Inspect and Reprogram (0 - Introduction)	2 - Automatic Transmission	0.3 Hrs.

NOTE: The expected completion time for the flash download portion of this procedure is approximately 6 minutes. Actual flash download times may be affected by vehicle connection and network capabilities.

FAILURE CODE:

The dealer must choose which failure code to use depending on if this is a Rapid Response Transmittal (RRT) or Service Bulletin.

- If the customer's concern matches the SYMPTOM/CONDITION identified in the Service Bulletin, failure code CC is to be used. When utilizing this failure code, the 3C's must be supplied.
- The failure code "RF" (Required Flash) can no longer be used on Service Bulletin flashes. The "RF" failure code can only be used on RRT.
- The "RF" failure code is required for essential module flash/reprogramming and can only be used after confirmation that the VIN is included on the RRT.

CC	Customer Concern
RF	Required Flash