



**NUMBER:** 21-063-15

**GROUP:** Transmission and Transfer Case

**DATE:** November 11, 2015

*This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of FCA US LLC.*

**HELP USING THE wiTECH DIAGNOSTIC APPLICATION FOR FLASHING AN ECU IS AVAILABLE BY SELECTING “HELP” THEN “HELP CONTENTS” AT THE TOP OF THE wiTECH DIAGNOSTIC APPLICATION WINDOW.**

**THE wiTECH SOFTWARE IS REQUIRED TO BE AT THE LATEST RELEASE BEFORE PERFORMING THIS PROCEDURE.**

***SUBJECT:***

Flash: Transmission Shift And Drivability Enhancements

***OVERVIEW:***

This bulletin involves reprogramming of the Transmission Control Module (TCM) with the latest available software.

***MODELS:***

2016	(LD)	Dodge Charger
2016	(LX)	Chrysler 300
2016	(LA)	Dodge Challenger

**NOTE: This bulletin applies to LA and LX vehicles built on or before October 17, 2015 (MDH 1017XX) equipped with the 3.6L engine (Sales Codes ERB) and a 8-Speed Auto 845RE transmission (Sales Code DFL).**

**NOTE: This bulletin applies to LD vehicles built on or before October 17, 2015 (MDH 1017XX) equipped with the 3.6L engine (Sales Codes ERB) and a 8-Speed Auto 845RE transmission or 8-Speed Auto 8HP45 transmission (Sales Code DFL or DFG).**

**NOTE: This bulletin applies to vehicles within the following markets/countries: NAFTA, LATAM, EMEA and APAC.**

**SYMPTOM/CONDITION:**

Customers may experience any of the following symptoms:

- Hanging or delayed upshift when braking downhill or when braking after high vehicle acceleration rate.
- Releasing the accelerator pedal rapidly causes hanging or delayed upshift.

Updating the TCM software will correct the conditions listed above.

**DIAGNOSIS:**

If the customer describes the symptom/condition listed above, perform the Repair Procedure.

**REPAIR PROCEDURE:**

**NOTE: Install a battery charger to ensure battery voltage does not drop below 13.2 volts. Do not allow the charging voltage to climb above 13.5 volts during the flash process.**

**NOTE: If this flash process is interrupted/aborted, the flash should be restarted.**

1. Reprogram the TCM with the latest available software. Detailed instructions for flashing control modules using the wiTECH Diagnostic Application are available by selecting the "HELP" tab on the upper portion of the wiTECH window, then "HELP CONTENTS." This will open the Welcome to wiTECH Help screen where help topics can be selected.
2. Clear all DTCs that may have been set in any module due to reprogramming. The wiTECH application will automatically present all DTCs after the flash and allow them to be cleared.

**NOTE: DO NOT CLEAR THE SHIFT ADAPTIVES IN THE TCM'S MEMORY. THIS ACTION MAY CAUSE THE TRANSMISSION TO NOT SHIFT SMOOTHLY UNTIL THE ADAPTIVES ARE RE-LEARNED.**

**POLICY:**

Reimbursable within the provisions of the warranty.

**TIME ALLOWANCE:**

Labor Operation No:	Description	Skill Category	Amount
18-19-05-CG	Module, Transmission Control (TCM) - Reprogram (1 - Semi-Skilled)	21- Automatic Transmission	0.2Hrs

**NOTE: The expected completion time for the flash download portion of this procedure is approximately 8 minutes. Actual flash download times may be affected by vehicle connection and network capabilities.**

***FAILURE CODE:***

**The dealer must choose which failure code to use. If the customer came in with an issue and the dealer found updated software to correct that issue, use failure code CC, for all other use failure code RF.**

- If the customer's concern matches the SYMPTOM/CONDITION identified in the Service Bulletin, failure code CC is to be used.
- If an available flash is completed while addressing a different customer concern, failure code RF is to be used.

CC	Customer Concern
RF	Routine Flash