

99-048

1994 - 00 Integra - ALL

November 29, 1999

Front Seat(s) Are Hard to Adjust

SYMPTOM

The driver and/or passenger front seat is difficult to adjust forward and backward.

PROBABLE CAUSE

The inner or outer seat track is not in alignment.

CORRECTIVE ACTION

Shim the seat track.

WARRANTY CLAIM INFORMATION

In warranty: The normal warranty applies.

OP#	Description	FRT	Template ID
852303	Shim seat track (one seat)	0.4	99-048A
852304	Shim seat track (two seats)	0.8	99-048B

P/N 81260-ST7-A03 Failed part:

Defect code: 030 Contention code: **B99**


Skill level: Repair Technician

Out of warranty: Any repair performed after warranty expiration may be eligible for goodwill consideration by the District Technical Manager or your Zone Office. You must request consideration, and get a decision, before starting work.


REPAIR PROCEDURE

- 1. Remove the seat track end covers.
- 2. Adjust the seat forward or backward to the approximate mid-point of the seat track travel.
- 3. Sit in the seat, and move it backward and forward, making sure both seat tracks are latched.
- 4. Loosen all four mounting bolts several turns.

5. Wiggle the seat backward and forward and side to side until you see a gap at one of the four mounting points.



- 6. Tighten the other three mounting bolts until they are snug, then remove the mounting bolt from the mounting point with the gap.
- 7. Use a vernier caliper to measure the mounting point gap you noticed in step 5.






BTB 21246 (9911)

- 8. Subtract 2.5 mm from the gap measurement to allow for the thickness of the seat track. Select the proper suspension alignment shim(s) to take up the measured gap. Do *not* exceed 5 mm.
 - NOTE: Alignment shim thickness is normally measured in fractions of an inch. Use this table to select the proper shim thickness.

Calculated gap	Shim thickness		
1.5 – 1.9 mm	1/16 in.		
2.0 – 2.5 mm	3/32 in.		
2.6 – 3.3 mm	1/8 in.		
3.4 – 4.2 mm	5/32 in.		
4.3 – 5.0 mm	3/16 in.		

9. Reinstall the mounting bolt, placing the shim(s) over the mounting bolt between the seat track and the mounting boss. Position the shim(s) to prevent poor appearance.



- 10. Torque all four seat track mounting bolts to 34 N·m (25 lb-ft).
- 11. Check the operation of the seat, making sure it slides smoothly and releases easily.
- 12. Reinstall the seat track end covers.
- 13. Repeat steps 1 through 12 for the other front seat if needed.

2 of 2 99-048