



To Only for USA Lamborghini Dealers and Licensed Service Point  
From Customer Service Department  
Subject Distance to Empty Indication update  
Group L140.0.17  
Attachments -  
Date 15/05/2006  
Page 9

Automobili  
Lamborghini  
S.p.A.

### **Subject**

Distance to Empty Indication update

### **Model / VIN-Range**

**All Gallardo USA MY '05** from VIN 1829 to VIN 2656.

**Attention: Please carefully check on the Lamborghini Web-portal to verify the VIN-Info and if the car is affected by this bulletin before the start of any activity.**

### **Information to the field**

In case you have one of the involved cars in the workshop, Lamborghini recommends the update of the engine management.

**This update must be performed on all USA Gallardo MY '05 involved, at the next service.**

### **Field solution**

Too optimistic Distance To Empty calculation when below 30 miles.  
United States software for MY '05 Gallardo has the wrong mile calculation.

### **Spare Parts**

No spare parts needed.



## Warranty Claim data

Please find on Lamborghini Web Portal in the Warranty section “Available campaigns”.

Campaign Code: **L140-B.03.06**  
Campaign Description: Distance to Empty Indication update  
Cost Code: **55**  
Component Code: **CCB0306**  
Trouble Code: **220**  
Labour code: **CCB0306100**  
Labour Time: **0,25 h.**

Your Area Manager is at your full disposal for further information.

Best regards


Customer Service

## A Preliminary advertising

- 1.1 Be sure that you utilize all of the necessary tools listed in section B.  
Remember to configure your laptop with the files downloaded from the portal.  
These files have to be saved in the folder: C:\LDAS 32\Service Pack 00-02

## B Necessary tools:

- 1.2 Can Line of type “C” (fig. 1 p/n 69190056) that can be recognized by the sticker on the socket “C” (fig.1 ref. A).




- 1.3 Configured Lamborghini Diagnostic Tester .

## C Reflash ECU LIE and GFA.

- 1.4 Connect your Laptop via Can line to the car (fig. 1 p/n 69190056).
- 1.5 Start LDAS.
- 1.6 While charging the battery between 8 and 14 Volt, toggle the key to the on position.
- 1.7 Select “ON line mode” from the toolbar (fig.2 ref. A).
- 1.8 Click on “Version” (fig.2 ref. B).



Fig.2



1.9 Note the “Map” (table) and the “Firmware” of the ECU GFA and LIE (fig.3).

Fig.3

Versione <>		
LIE bancata 1	FirmWare : Mappa : Kernel : FPGA : Tempo di funzionamento : Numero : Anno/sett. produzione :	Lambo LIE2003 18May2004 V4022906 E22952S9 06-21-2004 14.56 LIE2003 KERNEL 24Oct02 V1.02 2.30 2730d 15h 22' 49" 256 03/22
LIE bancata 2	FirmWare : Mappa : Kernel : FPGA : Tempo di funzionamento : Numero : Anno/sett. produzione :	Lambo LIE2003 18May2004 V4022906 E22952S9 06-21-2004 14.56 LIE2003 KERNEL 24Oct02 V1.02 2.30 5d 12h 39' 15" 208 03/22
GFA	FirmWare : Mappa : Kernel : FPGA : Tempo di funzionamento : Numero : Anno/sett. produzione :	Lambo GFA2002 28Mag2004 G2022205 G222SE5 06-21-2004 16.24 Lambo GFA2002 08Jan2003 K.02.02 3.02 5d 10h 46' 19" 0 00/00

*The information and procedures published below are strictly confidential and intended exclusively for authorized operators and individuals. All copyrights are the property of Automobili Lamborghini S.p.A based on copyright law. The company reserves the right to make updates and modifications. The reprinting, reproduction, forwarding to unauthorized people and/or to third parties and partial or entire translation thereof are prohibited without written authorization from Automobili Lamborghini S.p.A.*




**1.10** Utilizing the table below and compare the correct values of the map and the firmware in order to verify if the car has to be update. All the data should correspond.

Correct values:

Car type	LIE table	LIE firmware	GFA table	GFA firmware	PRG name to select
140 RC Step3 USA MANUALE LS	U255A2M2	V4025503	GL239MU3	G2023918	L714_LS_RC_STEP3_U_M_05_08
140 RC Step3 USA E-GEAR LS	U255A2S2	V4025503	GL239SU3	G2023918	L714_LS_RC_STEP3_U_E_05_08

If your values are not correct, please follow the next instructions:

**1.11** From menu “Commands” (fig.n.4 A) select “Program” (fig.n.4 B).




*The information and procedures published below are strictly confidential and intended exclusively for authorized operators and individuals. All copyrights are the property of Automobili Lamborghini S.p.A based on copyright law. The company reserves the right to make updates and modifications. The reprinting, reproduction, forwarding to unauthorized people and/or to third parties and partial or entire translation thereof are prohibited without written authorization from Automobili Lamborghini S.p.A.*



1.12 The programming window will appear (fig.5)

1.13 Select “Open PRG file” (fig.5 A).



1.14 Select “Service Pack 00-02” in “Look in” (fig.n.5 A).

1.15 Select the file:

**L714\_LS\_RC\_STEP3\_U\_M\_05\_08**

(for USA Gallardo with manual gearbox)

**L714\_LS\_RC\_STEP3\_U\_E\_05\_08**

(for USA Gallardo with E-gear)

**\*\*Attention:** the file name is composed in the following way:

- L714 = car version.
- LS= Lifting System
- Step 3= engine version.
- U = USA: market of the car.
- **M = manual gearbox.**
- **E = e-gear.**

05= model year

---

*The information and procedures published below are strictly confidential and intended exclusively for authorized operators and individuals. All copyrights are the property of Automobili Lamborghini S.p.A based on copyright law. The company reserves the right to make updates and modifications. The reprinting, reproduction, forwarding to unauthorized people and/or to third parties and partial or entire translation thereof are prohibited without written authorization from Automobili Lamborghini S.p.A.*



- 1.16 Select “Open”: the system will load the file automatically.
- 1.17 Select “Program PRG file” (fig.5 rif. B).
- 1.18 The system recognizes automatically the VIN of the car (fig.6a).  
Then click “OK” in order to start the ECU reprogramming.
- 1.19 Click “OK” in fig. 6b.
- 1.20 Click “Exit” (fig. 6b).

Fig.6 a)





Fig.6 b)




- 1.21 Once you have programmed the ECU, click on  that is located on the toolbar.


*The information and procedures published below are strictly confidential and intended exclusively for authorized operators and individuals. All copyrights are the property of Automobili Lamborghini S.p.A based on copyright law. The company reserves the right to make updates and modifications. The reprinting, reproduction, forwarding to unauthorized people and/or to third parties and partial or entire translation thereof are prohibited without written authorization from Automobili Lamborghini S.p.A.*

1.22 Select from the toolbar “Off line mode” (rif. B fig.7).

1.23 Select from the menu “Load Binary file” (fig.7)



1.24 The system creates two files that report the configuration condition before and after the reflash. These files are indicated by the letter A (before) and B (after) (fig.8 rif. A).



1.25 Remember to attach these files to the claim request (fig.8 ref. A).

1.26 Erase all the errors created by the system by using LDAS and LaRA-AS (erase fault memory code)

1.27 Disconnect the laptop.

1.28 Follow section D

---

*Procedures published below are strictly confidential and intended exclusively for authorized operators and individuals. All copyrights are the property of Automobili Lamborghini S.p.A based on copyright law. The company reserves the right to make updates and modifications. The reprinting, reproduction, forwarding to unauthorized people and/or to third parties and partial or entire translation thereof are prohibited without written authorization from Automobili Lamborghini S.p.A.*



## D Road Test:

**1.29** Start up and allow engine to reach operating temperature: water and oil temperatures should be up to 90°. In order to reach these temperatures we recommend to drive for about ten km. Then the system will start “*self learning*” procedure to update the entering of air volume (DBW throttle body).

**Warning:** unstable idle situations in the learning phase must be considered ordinary because the butterfly valve is not properly set.

**1.30** Once these temperatures are reached, you should wait 60 seconds to let the system acquire the data for DBW regulation.

**1.31** Let the engine idling until it becomes stable.

**1.32** The DBW procedure has been completed.