



Service Bulletin

File in Section: -

Bulletin No.: PIC5910

Date: September, 2013

PRELIMINARY INFORMATION

Subject: False Code B124B Sym04 Set In HMI Module With No Other Concerns Observed

Models: 2014 Buick LaCrosse
(Built On or Before August 26th, 2013)

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

Condition/Concern

During diagnosis, a false code B124B sym04 may be found in the HMI module with no other concerns observed.

Recommendation/Instructions

Please do not replace any components due to this code. Reprogram the HMI module with the latest calibrations in TIS2Web, which were released on 9/9/2013 to address this concern.

Note: This is not a USB program event.

Warranty Information

For vehicles repaired under warranty use:

Labor Operation	Description	Labor Time
2880088*	Reprogram Human Machine Interface Module (HMI)	0.3 hr
* This is an unique labor operation for bulletin use only. This will not be published in the Labor Time Guide.		

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.