



Service Bulletin

PRELIMINARY INFORMATION

- Subject:** Normal Characteristic - Sag Or Hesitation On Acceleration
- Models:**
- 2008-2013 Buick Enclave
 - 2013 Buick Encore
 - 2010-2013 Buick LaCrosse
 - 2011-2013 Buick Regal
 - 2012-2013 Buick Verano
 - 2006-2009 Cadillac STS-V, XLR, XLR-V
 - 2007-2013 Cadillac Escalade, Escalade EXT, Escalade ESV, SRX
 - 2007-2011 STS
 - 2008-2013 Cadillac CTS
 - 2013 Cadillac ATS, XTS
 - 2006-2013 Chevrolet Corvette
 - 2007-2013 Chevrolet Avalanche, Silverado, Suburban, Tahoe
 - 2008-2013 Chevrolet Equinox, Malibu
 - 2009-2013 Chevrolet Traverse
 - 2010-2013 Chevrolet Camaro, Cruze, Express
 - 2012-2013 Chevrolet Impala, Sonic
 - 2013 Chevrolet Trax
 - 2007-2013 GMC Sierra, Yukon, Yukon XL
 - 2008-2013 GMC Acadia
 - 2009-2013 GMC Terrain
 - 2010-2013 GMC Savana
 - 2007-2010 Pontiac G6
 - 2008-2009 Pontiac G8
 - 2008-2009 Pontiac Torrent
 - 2007-2009 Saturn Aura
 - 2008-2010 Saturn Outlook, Vue
- Equipped With a Gasoline Engine and Automatic Transmission

This PI was superseded to update model list. Please discard PIP4112K.

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

Condition/Concern

Some customers may comment on a sag or hesitation when accelerating under the following conditions:

When coasting with a closed throttle and then aggressively applying the throttle. Examples of this maneuver include a rolling stop or a lane change maneuver. In this type of maneuver, even though the accelerator is applied aggressively, the throttle blade is opened slowly for up to 0.7 seconds to help minimize drive-line lash and clunking.

Also in a vehicle equipped with a six speed automatic transmission when making a hard, complete stop with a closed throttle, immediately followed by an aggressive throttle opening the transmission down-shifts may not be completed by the time the throttle is opened. As a result approximately 0.5 seconds of "zero" torque may be commanded to allow the shift to first gear to occur.

Recommendation/Instructions

Both of the above conditions are a result of Torque Management and both of these conditions should be considered normal and no repairs should be attempted

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION