

Bulletin No.: PIT5448C

Date: Jan-2017

PRELIMINARY INFORMATION

Service Bulletin

Subject: Normal Characteristic - Engine Stops Running After Extended Idle

2015-2017 Cadillac Escalade Models Models:

2015-2017 Chevrolet Tahoe, Suburban

2015-2017 GMC Yukon Models

Equipped with Push Button Keyless Start (RPO BTM)

This PI was superseded to update the Concern and Recommendation sections. Please discard PIT5448B.

Condition/Concern

Some customers may comment that the engine stops running after extended idle with shifter in Park.

Recommendation/Instructions

An engine run timeout feature is standard on all push button start vehicles. There are 2 different scenarios for how the feature will work.

2015 Models Without RPO AVF will power off after 2.5 hours:

- 1. If the customer leaves the vehicle with the fob while the engine is running and the shifter in park it will power off after 2.5 hours. (ie no fob present.)
- If the customer is sitting with engine running and the fob is in the vehicle after 2.5 hours the vehicle will reach out and look for the fob and if it locates it in the vehicle it will reset the timer an additional 2.5 hours (5 hours total) then the vehicle will power off.

Note: If at any time during the first two scenarios the vehicle shifter is removed from park, the timer will reset and start over.

This is normal operation and no repairs should be made.

2015 Models With RPO AVF and 2016 Models will power off after 1 hour:

- 1. If the customer leaves the vehicle with the fob while the engine is running and the shifter in park it will power off after 1 hour. (ie no fob present.)
- If the customer is sitting with engine running and the fob is in the vehicle after 1 hour the vehicle will reach out and look for the fob and if it locates it in the vehicle it will reset the timer an additional 1 hour (2 hours total) then the vehicle will power off.

Note: If at any time during the first two scenarios the vehicle shifter is removed from park, the timer will reset and start over.

This is normal operation and no repairs should be made.

2017 and Newer Models:

This information can now be found in the Owner's Manual under: Driving and Operating / Driving Information / Regulated / Extended Parking See example SI Owner's Manual Document ID: 4328022.

Customer Information

Please communicate to the customer this condition is a normal operating characteristic of their vehicle. It will not impact the designed performance or reliability of the vehicle. Please share this information with the customer, including a copy of this message.

Additional SI Keywords

1/2 2 BTM keyless Police

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.