Bulletin No.: PIP5095C

GM CONTRACTOR

Date: Oct-2015

Service Bulletin

PRELIMINARY INFORMATION

Subject: Fluid In Spark Plug Tubes

Models: 2010-2016 Buick Enclave

2010-2016 Buick LaCrosse

2013-2015 Cadillac ATS

2010-2015 Cadillac CTS

2010-2016 Cadillac SRX

2013-2016 Cadillac XTS

2010-2015 Chevrolet Camaro

2012-2015 Chevrolet Caprice PPV

2012-2015 Chevrolet Captiva

2015-2016 Chevrolet Colorado

2010-2016 Chevrolet Equinox

2012-2016 Chevrolet Impala

2010-2016 Chevrolet Traverse

2010-2016 GMC Acadia

2015-2016 GMC Canyon

2010-2016 GMC Terrain

Equipped with HFV6 engines 3.0L and 3.6L LF1, LFW, LLT and LFX

This PI was superseded to update Models and Years. Please discard PIP5095B.

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

Condition/Concern

Some customers may complain of an SES light with misfire codes or possible oil or coolant leak.

Recommendation/Instructions

On inspection you may find coolant or oil in a spark plug tube.

Determine if the oil or coolant is coming from the spark plug tube and not leaking into it from above.

If the Spark Plug Tube is leaking replace the Cylinder Head, spark plug and coil.

These leaks are caused by porous spots in the head created during manufacturing.

The spark plug tubes are permanently sealed into the head and are not replaceable.

If you replace a cylinder head for this concern, mark the faulty spark plug tube before sending the head in for warranty or core so GM Engineering or the remanufacturing facility will know where the concern was.

Warranty Information

For vehicles repaired under warranty use:

Labor Operation	Description	Labor Time
4061770	Cylinder Head Replacement - Right Side	Use Published Labor Operation Time
4061790	Cylinder Head Replacement - Left Side	Use Published Labor Operation Time

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.

Additional SI Keywords

P0300 P0301 P0302 P0303 P0304 P0305 P0306

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safety. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.

WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION