



# Service Bulletin

## PRELIMINARY INFORMATION

**Subject:** A/C Blows Warm During High Ambient Temperatures

**Models:** 2015 Cadillac Escalade Models  
2015 Chevrolet Suburban, Tahoe  
2015 GMC Yukon Models  
Build prior to 1GNSKCKC5FR218605

*This PI was superseded to update Recommendation/Instructions. Please discard PIT5292>*

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

### Condition/Concern

**Note:** ALL 2015 FULL SIZE UTILITIES REQUIRE A NEW REFRIGERANT CHARGE AMOUNT OF 2.02 lb (920 g).

Some owners may comment that the A/C is inoperative. This concern may only occur during high ambient temperatures. When using GDS2 to review A/C compressor disengage reasons, it may indicate an A/C high pressure issue. This concern could be caused one of the following issues:

1. A/C refrigerant may have the incorrect charge.
2. A/C high side pressure sensor connector not fully seated or poor terminal tension
3. A/C high side pressure sensor reading may be skewed

### Recommendation/Instructions

1. Check the A/C refrigerant charge. New system capacity is 2.02 lbs (920 g). If system charge is found to be incorrect, recharge system to new specification of 2.02 lbs (920 g) and reevaluate. (The a/c system performance tables in SI have been updated to reflect the new refrigerant specification of 2.02 lbs (920 g). Please utilize these tables during the reevaluation.) This will correct the majority of the issues, but if the condition is not corrected, continue with steps 2 and 3.

**Note:** Allow the A/C refrigerant recovery and recharging equipment to fully complete its recovery cycle before recharging. When pulling a vacuum on the A/C system, the rubber A/C hoses may collapse and this is normal.

2. Check the A/C high side pressure sensor connector for proper terminal tension and to make sure that it is fully connected. Repair as necessary.
3. Connect a set of A/C pressure gages to the vehicle and open GDS2. Compare the high side pressure gage reading to the A/C high side pressure sensor reading in GDS2. Monitor the pressure when first connected to the vehicle while the system is off, and also while the A/C is operating. The high side gage reading and the data displayed in GDS2 should read relatively close. If the readings vary greatly, the sensor may be skewed or a wiring concern may be present. Repair as needed.

### Warranty Information

The correction for this concern may be one of several repairs described above. For vehicles repaired under warranty, please use the appropriate warranty labor operation based on the actual cause and repair.

### ADDITIONAL SI KEYWORDS:

AC air blow blows cold compressor condition conditioning front hot HVAC P0532 P0533 rear sensor side

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.

---

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION