

# **Service Bulletin**

File in Section: 06 - Engine

Bulletin No.: 15-06-01-002F

Date: December, 2017

# **TECHNICAL**

Subject: Engine Misfire/Tick Noise, Malfunction Indicator Lamp (MIL) Illuminated, DTC

P0300 Set

Models: 2015-2018 Cadillac Escalade

2016-2018 Cadillac CTS-V 2014 Chevrolet Silverado 1500

2014 Chevrolet Silverado 1500 2014-2018 Chevrolet Corvette

2015-2018 Chevrolet Silverado, Suburban, Tahoe

2016-2018 Chevrolet Camaro

2014 GMC Sierra 1500

2015-2018 GMC Sierra, Yukon, Yukon XL

Equipped with 5.3L Engine (RPO L83) or 6.2L Engine (RPO L86, LT1, LT4)

Attention: This Bulletin also applies to any of the above models that may be Export from North

America vehicles.

This Bulletin has been revised to add the 2018 Model Year, update the Cause and change a picture. Please discard Corporate Bulletin Number 15-06-01-002E.

### Condition

Some customers may comment on a malfunction indicator lamp (MIL) on and/or an engine misfire/tick noise.

Technicians may find DTC P0300 set or in history.

#### Cause

This may be caused by one of the following conditions:

- Active fuel management (AFM) lifter that is mechanically collapsed and/or stuck all of the time.
- Internal locking pin damage in the lifter, due to oil aeration.
- Lifter that has collapsed and is stuck in the lifter bore.
- The engine may have a bent push rod.

### Correction

**Note:** Inspect the camshaft for damage while the lifters are removed from the engine. If damage is found, replace the camshaft per SI.

If SI diagnosis does not isolate the cause of this concern, technicians should inspect for valve operation.

If the valve(s) are not moving, replace the valve lifter oil manifold and affected bank of AFM lifters. Refer to Valve Lifter Oil Manifold Replacement and Valve Lifter Replacement in SI.

If the lifter has spun the bore, the guides should also be replaced.

#### Recommendation/Instructions


There are two approved processes for removing the lifter when stuck in the bore.

Page 2 December, 2017 Bulletin No.: 15-06-01-002F



4250109

## 1. Use vice grips with a slide hammer.



4921302

**Note:** Be sure **NOT** to pry on the sealing surface of the block, as shown in the illustration above.

## 2. Use vice grips with a small pry bar.

Typically one of the above approved processes will remove the lifter that is stuck in the bore. If not, the engine will need to be replaced.

With the lifter removed, be sure to inspect the bore for any damage. Typically the lifter bores will look good with no indication of damage.

## **Parts Information**

Part Number	Description	
12660737	MANIFOLD ASM-VLV LFTR OIL (SERV KIT) (L83, L86, or LT1)	
12660736	MANIFOLD ASM-VLV LFTR OIL (SERV KIT) (LT4)	
12623104	GASKET-VLV LFTR OIL UPR MANIF	
12645725	LIFTER ASM-VLV (AFM) (4 per Bank)	
12659260	GASKET-CYL HD (6.2L)	
12622325	GASKET-CYL HD (5.3L)	
11546959	RIGHT SIDE CYLINDER HEAD BOLTS (10)	
11611976	LEFT SIDE CYLINDER HEAD BOLT (1)	
11546959	LEFT SIDE CYLINDER HEAD BOLTS (9)	
12657093	GASKET-EXH MANIF	
12626354	GASKET-INT MANIF (8)	
12619787	GASKET-VLV RKR ARM CVR	
12623308	GASKET-F/PMP BRKT	
12618336	PIPE ASM-FUEL FEED INTER	
12618337	PIPE ASM-FUEL FEED INTER	
12618338	PIPE ASM-FUEL FEED	
12668553	SEAL KIT-F/INJR (O RING) (2)	

Bulletin No.: 15-06-01-002F December, 2017 Page 3

## **Warranty Information**

For vehicles repaired under the Powertrain coverage, use the following labor operation. Reference the Applicable Warranties section of Investigate Vehicle History (IVH) for coverage information.

Labor Operation	Description	Labor Time
4080978*	Valve Lifter Oil Manifold and Valve Lifter Left Side Replacement	9.4 hrs (Silverado, Sierra)
		14.8 hrs (CTS-V)
		9.2 hrs (Escalade, Suburban, Tahoe, Yukon)
		11.7 hrs (Corvette)
		7.0 hrs (Camaro)
4080988*	Valve Lifter Oil Manifold and Valve Lifter Right Side Replacement	10.9 hrs (Silverado, Sierra)
		15.5 hrs (CTS-V)
		9.3 hrs (Escalade, Suburban, Tahoe, Yukon)
		11.4 hrs (Corvette)
		9.0 hrs (Camaro)
*This is a unique Labor Operation for Bulletin use only.		