

# SERVICE MANUAL BULLETIN

This Service Manual Bulletin is prepared by the Publications Department of New Flyer Industries Canada ULC. Refer to details below.

## **SMB-182**

ISSUE DATE: Sep 4 2018

		APPLICABILITY	•		
VEHICLE LENGTH	□ 30ft.	□ 35ft.	□ 40ft.	■60ft.	
VEHICLE TYPE	■ Xcelsior <sup>®</sup>	□ MiDi <sup>®</sup>			
	□ Low Floor	□ High Floor			
FUEL TYPE	Diesel	■ Diesel/Electric	CNG		
	■ Fuel Cell	Trolley/Electric	■ Battery/Electric		
SUBJECT	Artic Joint Retorque & Bolt Replacement				
SECTION TITLE	PM - Preventive Maintenance				
DETAILS	This bulletin identifies a new requirement for bolt replacement in the Artic Joint Support Frame installed on your New Flyer vehicle.				
	Make this Service Bulletin available to service personnel to inform them of changed information.				



## 1. Three Year Preventive Maintenance

### 1.1. Artic Joint Retorque & Bolt Replacement

 Retorque the articulation joint major fasteners every three years or 90,000 miles (145,000 km), whichever occurs first. Refer to Section 21 of the New Flyer Service manual for torque specifications and procedures.

### Real NOTE:

Set the torque wrench to the specified torque value and apply a tightening force

to the fastener until the torque value is reached. It is not necessary to break loose the fastener and then retorque.

 Replace the two outer bolts on either side of the support frame every three years or 90,000 miles (145,000 km), whichever occurs first. See "Fig. 1: Support Frame Bolt Replacement" on page 2. Refer to your New Flyer Parts Manual for correct replacement parts. Refer to Section 21 of the New Flyer Service manual for torque specifications and procedures.




Fig. 1: Support Frame Bolt Replacement