



TECHNICAL SERVICE BULLETIN

Intermittent Power Mirror And/Or Power Window Operation From Master Switch - Built On 23-Jul-2018 And Through 07-Nov-2018

19-209222 March
2019

This bulletin supersedes 19-2072. Reason for update: Not Applicable

Model:

| |
|---------------------|
| Lincoln 2019 MKC |
|---------------------|

Summary

This article supersedes TSB 19-2072 to update the Service Labor Time Standards and Tool List.

Issue: Some 2019 MKC vehicles built on 23-Jul-2018 and through 07-Nov-2018 may exhibit intermittent function of the power mirrors and/or power windows from the master switch. These symptoms may also be present with or without diagnostic trouble codes (DTCs) B1087 and/or B1088 stored in the driver door module (DDM) and/or passenger door module (PDM). This may be the result of a small impression in the left B-pillar sheet metal which has allowed water to overcome the sealing capability of the electrical harness grommet and enter connector C315. To resolve this concern, remove all moisture from the connector, apply electrical grease and seal the B-pillar wiring harness grommet to the left B-pillar sheet metal.

Action: Follow the Service Procedure steps to correct the condition on vehicles that meet all of the following criteria:

- 2019 MKC
- Built on 23-Jul-2018 and through 07-Nov-2018
- Intermittent function of the power mirrors and/or power windows from the master switch

Parts

| Part Number | Description | Quantity |
|-------------|-------------------------------|----------|
| XG-12 | Motorcraft® Electrical Grease | 1 |
| TA-2-B | Motorcraft® Seam Sealer | 1 |

Labor Times

| Description | Operation No. | Time |
|--|---------------|----------|
| 2019 MKC: Retrieve DTCs, Clean And Reseal Connector Following The Service Procedure (Do Not Use With Any Other Labor Operations) | 192092A | 0.3 Hrs. |

Repair/Claim Coding

| | |
|-----------------|---------|
| Causal Part: | 7824301 |
| Condition Code: | 01 |

Tool List

| Tool Name |
|------------------------------|
| Small flat blade screwdriver |

| Tool Name |
|-----------|
| Pick |
| Blow tip |


Service Procedure

1. Open both front and rear left side doors.
2. Using a small flat blade screwdriver or pick, release the two locking tabs on the B-pillar grommet.
(Figures 1-2)

Figure 1



Figure 2



3. Unseat the B-pillar wiring harness grommet. (Figure 3)

Figure 3



4. Pull out the wiring harness from the B-pillar exposing the hard shell connector. (Figure 4)

Figure 4




5. Disconnect connector C315 and inspect for water intrusion. (Figure 5)

Figure 5



6. Disassemble the hard shell connector attached to the grommet and inspect for water intrusion. (Figure 6)

Figure 6



7. Using compressed air, blow out any moisture from the hard shell and C315 connector.
8. Reassemble the hard shell connector and add a small amount of Motorcraft® Electrical Grease or equivalent to the C315 connector and reconnect.
9. Apply Motorcraft® Seam Sealer or equivalent to left B-Pillar around the opening for the electrical harness. (Figure 7)

Figure 7



10. Reinstall B-pillar wiring harness grommet and remove any excess sealer.

© 2019 Ford Motor Company

All rights reserved.

NOTE: The information in Technical Service Bulletins is intended for use by trained, professional technicians with the knowledge, tools, and equipment to do the job properly and safely. It informs these technicians of conditions that may occur on some vehicles, or provides information that could assist in proper vehicle service. The procedures should not be performed by "do-it-yourselfers". Do not assume that a condition described affects your car or truck. Contact a Ford or Lincoln dealership to determine whether the Bulletin applies to your vehicle. Warranty Policy and Extended Service Plan documentation determine Warranty and/or Extended Service Plan coverage unless stated otherwise in the TSB article. The information in this Technical Service Bulletin (TSB) was current at the time of printing. Ford Motor Company reserves the right to supersede this information with updates. The most recent information is available through Ford Motor Company's on-line technical resources.